DEKRA

CONDITION REPORT

Report No:
2017317062
DATE
26/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	26/10/2026		
Inspection Date	26/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	VOLKSWAGEN	Registration Number	FW55BFGP
Model	POLO VIVO GP 1.4 55KW CITI 5-DR [2017-2018]	Register Number	
		Date Of First Licensing	
VIN	AAVZZZ6SZHU023983	Last COR	
Engine Number		License Expiry Date	30/09/2026
Doors	5	Power / Displacement	
Color	RED	Paint Finish	TWO COAT UNI
Year Model	2017	Fuel	PETROL
Km Reading	131,891 KM	Transmission	MANUAL
Cab / Body Type	HATCHBACK		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU023983

DEKRA

CONDITION REPORT

Report No:
2017317062
DATE
26/10/2026





Damage	Repair Way
Radio/CD/USB Defective	Repair
Air Conditioner Insufficient	Repair
Seat Rear Dirty	Repair
Front Bumper Damaged	Repair
Bonnet Paintwork • Chipmarks	Repair
Front Fender Left Residual Traces of Repair	Repair
Rear Fender Left Residual Traces of Repair	Repair
Door Front Left Residual Traces of Repair	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Left Residual Traces of Repair	Repair
Door Rear Right Damaged	Repair
Boot Lid / Hatch door Dented	Repair
Inner Boot Floor Pan and Spare Wheel Well Damaged	Repair
Tie Rod End left Cracked	Replace
Tie Rod End right Cracked	Replace
Tyre Rear Left Worn	Replace
Rim Front Left Scratched	Repair
Rim Rear Right Scratched	Repair
Bolt(s) / Nut(s) Front Wheel Left Missing	Replace
Bolt(s) / Nut(s) Rear Wheel Left Missing	Replace
Bolt(s) / Nut(s) Rear Wheel Right Missing	Replace
Sub Frame Dented	Repair
Engine to silencer pipe Damaged	Repair
Belly plates Damaged	Repair
Gearbox Oil Sweat	Repair
Center exhaust cross member bracket damaged	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.56	2.64	-	
Rear	1.69	1.83	-	
Emergency / Parking	1.34	1.4	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/60 R14	82H	Goodyear	Efficient	V	0124	5 mm
Front Right	185/60 R14	82H	Goodyear	Efficient	V	4424	5 mm
Rear Left	185/60 R14	86H	Radar	RPX-800	V	0723	0 mm
Rear Right	185/60 R14	82H	Goodyear	Efficient	V	4623	4 mm
Spare	175/65 R14	82T	Goodyear	GT2	V	1317	4 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU023983

DEKRA

CONDITION REPORT

Report No:
2017317062
DATE
26/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	01-ENGINE CONTROL MODULE 1	P0073:00/00115:000	AMBIENT AIR TEMPERATURE SENSOR CIRCUIT HIGH	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Electrical Components and Instruments: Radio volume switch malfunction.
Body • Exterior: Poor residual traces of repair on body panels.Body panels misaligned.Stone chips and spray work on body panels.Dents and scratches on body panels.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU023983

DEKRA

CONDITION REPORT

Report No:
2017317062
DATE
26/10/2026



Brake and shock absorber repor



Diagnostic report page 1



Diagnostic report page 2



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU023983

DEKRA

CONDITION REPORT

Report No:
2017317062
DATE
26/10/2026



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual Transmission



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU023983

DEKRA

CONDITION REPORT

Report No:
2017317062
DATE
26/10/2026



90 DEGREE LEFT




LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare wheel and Accessories

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU023983

DEKRA

CONDITION REPORT

Report No:
2017317062
DATE
26/10/2026



LICENSE DISC



VIN PLATE OR STICKER




ENGINE 1



Front chassis



Rear chassis



Oil cap and dipstick

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU023983

DEKRA

CONDITION REPORT

Report No:
2017317062
DATE
26/10/2026



Center exhaust cross member br



Water level



Bonnet



Bonnet



Door Front Right



Door Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU023983

DEKRA

CONDITION REPORT

Report No:
2017317062
DATE
26/10/2026



Door Rear Right



Door Rear Right



Air Conditioner



Rim Rear Right



Bolt(s) / Nut(s) Rear Wheel Right



Boot Lid / Hatch door

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU023983

DEKRA

CONDITION REPORT

Report No:
2017317062
DATE
26/10/2026



Rear Fender Left



Door Rear Left



Door Front Left



Front Fender Left



Rim Front Left



Bolt(s) / Nut(s) Front Wheel Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU023983

DEKRA

CONDITION REPORT

Report No:
2017317062
DATE
26/10/2026



Bolt(s) / Nut(s) Rear Wheel Left



Seat Rear



Inner Boot Floor Pan and Spare Wheel Well



Front Bumper



Front Bumper



Engine to silencer pipe

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU023983

DEKRA

CONDITION REPORT

Report No:
2017317062
DATE
26/10/2026



Tie Rod End left



Tie Rod End right




Gearbox



Sub Frame



Sub Frame



Belly plates

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU023983

DEKRA

CONDITION REPORT

Report No:
2017317062
DATE
26/10/2026



Tyre Rear Left



Radio/CD/USB

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU023983