DEKRA

CONDITION REPORT

Report No:
2017305827
DATE
01/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	01/10/2026		
Inspection Date	01/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	VOLKSWAGEN	Registration Number	KWR068NW
Model	POLO VIVO GP 1.4 55KW CONCEPTLINE 5-DR [2016-2018]	Register Number	
		Date Of First Licensing	
VIN	AAVZZZ6SZHU031718	Last COR	
Engine Number		License Expiry Date	30/04/2025
Doors	5	Power / Displacement	
Color	WHITE	Paint Finish	C - COMMON
Year Model	2017	Fuel	PETROL
Km Reading	172,859 KM	Transmission	MANUAL
Cab / Body Type	HATCHBACK		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU031718

DEKRA

CONDITION REPORT

Report No:
2017305827
DATE
01/10/2026





Damage	Repair Way
Engine Oil Leak	Repair
Engine Wiring Defective	Repair
Fog Light Front Left Damaged	Replace
Fog Light Front Right Damaged	Replace
Seat Front Left Torn / Cut	Repair
Seat Front Right Torn / Cut	Repair
Door Panel Front Right Damaged	Replace
Door Handle Front Left Damaged	Replace
Door Handle Front Right Damaged	Replace
Dash Padding Damaged	Replace
Side Mirror Left Damaged	Replace
Side Mirror Right Damaged	Replace
Front Bumper Paintwork • Scratched	Repair
Bonnet Paintwork • Chipmarks	Repair
C • Pillar Right Paintwork • Scratched	Repair
Rear Fender Left Residual Traces of Repair	Repair
Rear Fender Left / Inner Tray Damaged	Replace
Door Front Left Paintwork • Scratched	Repair
Door Rear Left Residual Traces of Repair	Repair
Door Rear Right Paintwork • Scratched	Repair
Boot Lid / Hatch door Residual Traces of Repair	Repair
Rear bumper Residual Traces of Repair	Repair
Brake disc 1. Axle left Excessive Wear & Tear	Replace
Tie Rod End left Damaged	Replace
Tie Rod End right Cracked	Replace
Spring Front Left Incorrect	Replace
Spring Front Right Incorrect	Replace
Spring Rear Left Incorrect	Replace
Spring Rear Right Incorrect	Replace
Stabilizer Mounting Front Right Damaged	Replace
Control Arm Bush(es) Front Axle Left Cracked	Replace
Control Arm Bush(es) Front Axle Right Cracked	Replace
Tyre Front Left Smooth	Replace
Tyre Front Right Smooth	Replace
Tyre Rear Left Excessive Wear & Tear	Replace
Tyre Rear Right Excessive Wear & Tear	Replace
Spare Tyre Excessive Wear & Tear	Replace
Bolt(s) / Nut(s) Rear Wheel Left Missing	Replace
Bolt(s) / Nut(s) Rear Wheel Right Missing	Replace
Rear tyre size differs	Replace
radiator is loose	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU031718

DEKRA

CONDITION REPORT

Report No:
2017305827
DATE
01/10/2026

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	3.1	3.0	-	
Rear	1.3	1.9	-	
Emergency / Parking	1	1.3	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/60R14	82H	Winrun	R330	V	4923	0 mm
Front Right	185/60R14	82H	Winrun	R330	V	4923	0 mm
Rear Left	185/60R14	82H	Winrun	R330	V	4923	0 mm
Rear Right	175/65R14	82T	Dunlop	Sport	V	4723	0 mm
Spare	185/70R14	88T	Goodyear	Assurance	V	0000	0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ELECTRONIC CENTRAL ELECTRIC	01598:027	DRIVE BATTERY VOLTAGE - IMPLAUSIBLE SIGNAL	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Body • Exterior: Signs of spray work done on body panels.
Axle and Suspension: Vehicle fitted with lower suspension.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Trevino Julius

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU031718

DEKRA

CONDITION REPORT

Report No:
2017305827
DATE
01/10/2026

strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU031718

DEKRA

CONDITION REPORT


Report No:
2017305827
DATE
01/10/2026



Shock and brake report



Diagnostics report



Diagnostics report



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU031718

DEKRA

CONDITION REPORT

Report No:
2017305827
DATE
01/10/2026



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual transmission



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU031718


DEKRA

CONDITION REPORT

Report No:
2017305827
DATE
01/10/2026



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Sparewheel

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU031718

DEKRA

CONDITION REPORT

Report No:
2017305827
DATE
01/10/2026




LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



ENGINE 2



CHASSIS



REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU031718


DEKRA

CONDITION REPORT

Report No:
2017305827
DATE
01/10/2026



Expansion bottle




Oil cap and dipstick



ECU cable ties



Side Mirror Left



Side Mirror Right



Door Handle Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU031718

DEKRA

CONDITION REPORT

Report No:
2017305827
DATE
01/10/2026




Door Handle Front Right



Door Panel Front Right



Seat Front Left



Seat Front Right



Spare Tyre



Boot Lid / Hatch door

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU031718

DEKRA

CONDITION REPORT

Report No:
2017305827
DATE
01/10/2026



Boot Lid / Hatch door



Boot Lid / Hatch door



Boot Lid / Hatch door



Rear Fender Left



Door Rear Left



Door Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU031718

DEKRA

CONDITION REPORT


Report No:
2017305827
DATE
01/10/2026



Dash Padding



Bonnet



Engine Wiring



Engine Wiring



Engine Wiring



Engine Wiring


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU031718

DEKRA

CONDITION REPORT

Report No:
2017305827
DATE
01/10/2026




Engine Wiring




Spring Front Right



Tyre Front Right



Control Arm Bush(es) Front Axle Right



Tie Rod End right



Stabilizer Mounting Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU031718

DEKRA

CONDITION REPORT

Report No:
2017305827
DATE
01/10/2026



Fog Light Front Right



Fog Light Front Left



Front Bumper



Front Bumper



Front Bumper



Brake disc 1. Axle left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU031718

DEKRA

CONDITION REPORT

Report No:
2017305827
DATE
01/10/2026



Spring Front Left



Tyre Front Left



Control Arm Bush(es) Front Axle Left



Tyre Front Left



Door Front Left



Bolt(s) / Nut(s) Rear Wheel Left


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU031718


DEKRA

CONDITION REPORT

Report No:
2017305827
DATE
01/10/2026



Tyre Rear Left




Rear bumper



Rear bumper



Rear bumper



Tyre Rear Right



Bolt(s) / Nut(s) Rear Wheel Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU031718

DEKRA

CONDITION REPORT

Report No:
2017305827
DATE
01/10/2026




Door Rear Right



C • Pillar Right



Tie Rod End left



Engine



Engine



Engine Wiring

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU031718

DEKRA

CONDITION REPORT

Report No:
2017305827
DATE
01/10/2026




Spring Rear Right




Spring Rear Left



Rear Fender Left / Inner Tray



Engine Wiring



Engine Wiring

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU031718