CONDITION REPORT

Report No:
2017310667
DATE
12/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park -
Requested Date	12/10/2026		
Inspection Date	12/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	VOLKSWAGEN	Registration Number	HM18HCGP
Model	POLO 1.0 TSI COMFORTLINE 70KW 5-DR DSG [2018-2019]	Register Number	
		Date Of First Licensing	
VIN	AAVZZZAWZJU041121	Last COR	
Engine Number		License Expiry Date	30/06/2026
Doors	5	Power / Displacement	
Color	BEIGE	Paint Finish	M - METALLIC
Year Model	2018	Fuel	PETROL
Km Reading	180,027 KM	Transmission	AUTOMATIC
Cab / Body Type	HATCHBACK		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZJU041121

DEKRA

CONDITION REPORT

Report No:
2017310667
DATE
12/10/2026



Damage	Repair Way
Seat Front Right Torn / Cut	Repair
Rear Fender Left Dented	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Residual Traces of Repair	Repair
Rear bumper Residual Traces of Repair	Repair
Windscreen Cracked	Replace
Tie Rod End left Damaged	Replace
Tie Rod End right Damaged	Replace
Bolt(s) / Nut(s) Rear Wheel Left Missing	Replace
Bolt(s) / Nut(s) Rear Wheel Right Missing	Replace
Tyre pressure warning lights illuminated	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	3.1	3.3	-	
Rear	2.0	2.4	-	
Emergency / Parking	1.4	1.3	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/65R15	92T	Barum	Brillantis	V	0919	2 mm
Front Right	185/65R15	88T	Continental	Contact	V	5019	2 mm
Rear Left	185/65R15	88T	MRF	ZVTV	V	1121	5 mm
Rear Right	185/65R15	88H	Falken	Sincera	V	1418	1 mm
Spare	185/65R15	88T	MRF	ZVTV	V	0000	5 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZJU041121

DEKRA

CONDITION REPORT

Report No:
2017310667
DATE
12/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ENGINE CONTROL MODULE	P305400	STARTER DOES NOT TURN, MECHANICALLY BLOCKED OR	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Engine Compartment: Bottom of engine is fully covered.
Body • Exterior: Residual traces of repair work on body panels. Signs of spray work done on body panels.
Undercarriage: Undercarriage Is fully covered.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Trevino Julius

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZJU041121

DEKRA

CONDITION REPORT

Report No:
2017310667
DATE
12/10/2026




Shock and brake report



Diagnostics report



Diagnostics report



Diagnostics report



FRONT RIGHT CORNER



REAR LEFT CORNER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZJU041121

DEKRA

CONDITION REPORT

Report No:
2017310667
DATE
12/10/2026



INTERIOR (FRONT DRIVER DOOR)




DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic transmission



90 DEGREE FRONT



90 DEGREE RIGHT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZJU041121

DEKRA

CONDITION REPORT

Report No:
2017310667
DATE
12/10/2026



90 DEGREE REAR




90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZJU041121

DEKRA

CONDITION REPORT

Report No:
2017310667
DATE
12/10/2026



Sparewheel



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



ENGINE 2



CHASSIS

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZJU041121

DEKRA

CONDITION REPORT

Report No:
2017310667
DATE
12/10/2026



REAR



Oil cap and dipstick




Windscreen wiper reservoir cap



Tyre pressure warning lights i



Expansion bottle



Windscreen

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZJU041121

DEKRA

CONDITION REPORT


Report No:
2017310667
DATE
12/10/2026




Windscreen



Seat Front Right



Door Rear Right



Rear Fender Left



Seat Front Right



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZJU041121

DEKRA

CONDITION REPORT

Report No:
2017310667
DATE
12/10/2026



Bolt(s) / Nut(s) Rear Wheel Left



Door Rear Left



Rear bumper



Rear bumper



Rear bumper



Bolt(s) / Nut(s) Rear Wheel Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZJU041121


DEKRA

CONDITION REPORT

Report No:
2017310667
DATE
12/10/2026



Door Front Right



Tie Rod End left



Tie Rod End right



Door Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZJU041121