DEKRA

CONDITION REPORT

Report No:
2017286605
DATE
19/08/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	**MFC Auction House**	Inspection Location	**MFC** **M57 Pretoria Road - 1619** **Kempton Park -**
Requested Date	**19/08/2026**		
Inspection Date	**19/08/2026**		

Vehicle Data

Vehicle Type	**PASSENGER VEHICLE**	Registered Owner	**MFC**
Manufacturer	**VOLKSWAGEN**	Registration Number	**LY53VPGP**
Model	**POLO 1.0 TSI 70KW COMFORTLINE 5-DR DSG [2019-2021]**	Register Number	
		Date Of First Licensing	
VIN	**AAVZZZAWZLU014177**	Last COR	
Engine Number		License Expiry Date	**30/09/2026**
Doors	**5**	Power / Displacement	
Color	**WHITE**	Paint Finish	**TWO COAT UNI**
Year Model	**2019**	Fuel	**PETROL**
Km Reading	**195,472 KM**	Transmission	**AUTOMATIC**
Cab / Body Type	**HATCHBACK**		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZLU014177

DEKRA

CONDITION REPORT

Report No:
2017286605
DATE
19/08/2026





Damage	Repair Way
Engine Management Lights Set	Repair
Side Mirror Right Damaged	Repair
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Front Fender Left Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Boot Lid / Hatch door Damaged	Repair
Rear bumper Damaged	Repair
Windscreen Damaged	Replace
Service Brake Performance Rear Axle Left / Right Difference out of legal range	Repair
Tyre Rear Left Worn	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	3.65	3.81	-	
Rear	1.84	1.28	-	
Emergency / Parking	1.08	0.8	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/60R15	84H	Matador	Radial	V	0722	1 mm
Front Right	185/60R15	84H	Matador	Radial	V	1118	1 mm
Rear Left	185/60R15	84H	Hilo	Radial	V	4619	0 mm
Rear Right	185/65R15	88H	Tracmax	Radial	V	1723	2 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZLU014177

DEKRA

CONDITION REPORT

Report No:
2017286605
DATE
19/08/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	01-ENGINE CONTROL MODULE 1	P305400	STARTER DOES NOT TURN MECHANICALLY BLOCKED OR ELECTRICAL MALFUNCTION	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Body • Exterior: Minor dents and scratches and stone chips to body panels. Signs of repair work done to body panels. Poor alignment to somebody panels.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZLU014177

DEKRA

CONDITION REPORT

Report No:
2017286605
DATE
19/08/2026




Brake test.



Diagnostic.



Diagnostic.



Diagnostic.



FRONT RIGHT CORNER



REAR LEFT CORNER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZLU014177

DEKRA

CONDITION REPORT

Report No:
2017286605
DATE
19/08/2026



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic.



90 DEGREE FRONT



90 DEGREE RIGHT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZLU014177

DEKRA

CONDITION REPORT

Report No:
2017286605
DATE
19/08/2026



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZLU014177

DEKRA

CONDITION REPORT

Report No:
2017286605
DATE
19/08/2026



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



ADDITIONAL 5



ADDITIONAL 6



Oil cap and dipstick.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZLU014177

DEKRA

CONDITION REPORT


Report No:
2017286605
DATE
19/08/2026



Water level




Front Bumper



Front Bumper



Bonnet



Front Fender Left



Door Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZLU014177

DEKRA

CONDITION REPORT

Report No:
2017286605
DATE
19/08/2026


Door Rear Left


Rear bumper


Rear bumper


Boot Lid / Hatch door


Door Front Right


Side Mirror Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZLU014177

DEKRA

CONDITION REPORT

Report No:
2017286605
DATE
19/08/2026




Windscreen



Engine Management Lights



Tyre Rear Left



Service Brake Performance Rear Axle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZLU014177