DEKRA

CONDITION REPORT

Report No:
2017308858
DATE
07/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park -
Requested Date	07/10/2026		
Inspection Date	07/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	VOLKSWAGEN	Registration Number	LL73CHGP
Model	POLO 1.0 TSI 70KW COMFORTLINE 5-DR DSG [2020-2022]	Register Number	
		Date Of First Licensing	
VIN	AAVZZZAWZMU064954	Last COR	
Engine Number		License Expiry Date	
Doors	5	Power / Displacement	
Color	BLUE	Paint Finish	M - METALLIC
Year Model	2021	Fuel	PETROL
Km Reading	64,818 KM	Transmission	AUTOMATIC
Cab / Body Type	HATCHBACK		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZMU064954

DEKRA

CONDITION REPORT

Report No: 2017308858
DATE 07/10/2026



Damage	Repair Way
Fog Light Front Left Malfunction	Repair
Seat Front Right Torn / Cut	Repair
Side Mirror Left Damaged	Repair
Front Bumper Paintwork • Discoloured	Repair
Bonnet Paintwork • Discoloured	Repair
Front Fender Left Paintwork • Discoloured	Repair
Front Fender Right Paintwork • Discoloured	Repair
Rear Fender Left Paintwork • Discoloured	Repair
Rear Fender Right Paintwork • Discoloured	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Paintwork • Chipmarks	Repair
Door Rear Left Dented	Repair
Door Rear Right Paintwork • Scratched	Repair
Boot Lid / Hatch door Paintwork • Discoloured	Repair
Rear bumper Paintwork • Discoloured	Repair
Body exterior	Vehicle got some scratches, stone chips and dents
Body exterior	Discoloring on some body panels
Engine management lights illuminated	Repair
Boot not opening can not see spare wheel	Repair
No license disc	Replace
Two tires deferred name brand	Repair
Brake test failed	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	3.3	3.6	-	
Rear	2.9	2.6	-	
Emergency / Parking	0.8	0.7	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	215/45R17	91W	Continental	Contact	V	3722	3 mm
Front Right	215/45R17	91W	Dunlop	Sp sport	V	3621	3 mm
Rear Left	215/45R17	91W	Black hawk	Street -H	V	1421	3 mm
Rear Right	215/45R17	91W	Continental	Contact	V	4820	3 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZMU064954

DEKRA

CONDITION REPORT

Report No:
2017308858
DATE
07/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ENGINE	P308100	ENGINE TEMPERATURE TOO LOW	PASSIVE SPORADIC

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE EXTERIOR, INTERIOR, ELECTRICAL, AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZMU064954

DEKRA

CONDITION REPORT

Report No:
2017308858
DATE
07/10/2026



LICENSE DISC



VIN PLATE OR STICKER



FRONT RIGHT CORNER



90 DEGREE FRONT



90 DEGREE LEFT



REAR LEFT CORNER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZMU064954

DEKRA

CONDITION REPORT

Report No:
2017308858
DATE
07/10/2026



90 DEGREE REAR



90 DEGREE RIGHT



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZMU064954

DEKRA

CONDITION REPORT

Report No:
2017308858
DATE
07/10/2026




ENGINE 1




Expantion bottle




Oil cap and dipstick



Shock and brake report



Diagnostic report



Diagnostic report

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZMU064954

DEKRA

CONDITION REPORT

Report No:
2017308858
DATE
07/10/2026



Diagnostic report




Diagnostic report




LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZMU064954

DEKRA

CONDITION REPORT


Report No:
2017308858
DATE
07/10/2026



ENGINE 2



CHASSIS



Seat Front Right



Water level



Side Mirror Left



Fog Light Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZMU064954

DEKRA

CONDITION REPORT

Report No:
2017308858
DATE
07/10/2026



Bonnet



Front Bumper



Rear Fender Right



Door Rear Right



Door Front Right



Front Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZMU064954

DEKRA

CONDITION REPORT

Report No:
2017308858
DATE
07/10/2026



Front Fender Left



Door Front Left



Door Rear Left



Rear Fender Left



Boot Lid / Hatch door



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZMU064954