CONDITION REPORT

Report No:
2017316347
DATE
23/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	23/10/2026		
Inspection Date	23/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	VOLKSWAGEN	Registration Number	FWT238L
Model	POLO 1.0 TSI 70KW COMFORTLINE 5-DR [2020-2022]	Register Number	
		Date Of First Licensing	
VIN	AAVZZZAWZMU066823	Last COR	
Engine Number		License Expiry Date	30/09/2026
Doors	5	Power / Displacement	
Color	BLUE	Paint Finish	M - METALLIC
Year Model	2021	Fuel	PETROL
Km Reading	152,494 KM	Transmission	MANUAL
Cab / Body Type	HATCHBACK		

Vehicle Options & Accessories

Items


VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA

CONDITION REPORT

Report No:
2017316347
DATE
23/10/2026



Damage	Repair Way
Seat Front Right Damaged	Repair
Number Plate Rear Missing	Replace
Front Bumper Paintwork • Chipmarks	Repair
Bonnet Paintwork • Chipmarks	Repair
Front Fender Right Dented	Repair
Rear Fender Left Paintwork • Scratched	Repair
Rear Fender Right Dented	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Paintwork • Scratched	Repair
Boot Lid / Hatch door Paintwork • Scratched	Repair
Rear bumper Paintwork • Scratched	Repair
Windscreen Cracked	Replace
Tyre Front Right Smooth	Replace
Tyre Rear Right Smooth	Replace
Spare Tyre Smooth	Replace
Engine to silencer pipe Welded	Repair
CV Joint(s) Boot(s) Front Left (inner/outer) Damaged	Replace
Body exterior	Vehicle got minor scratches, stone chips and dents
Engine management lights illuminated	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	3.3	3.6	-	
Rear	2.0	2.8	-	
Emergency / Parking	1.3	1.7	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	215/45R17	91W	Hilo	Vantage xu1	V	2925	3 mm
Front Right	215/45R17	91W	Firemax	Fm601	V	0825	0 mm
Rear Left	215/45R17	91W	Pirelli	Cinturato	V	0822	2 mm
Rear Right	215/45R17	91W	Continental	Contact	V	1221	0 mm
Spare	215/45R17	91W	Continental	Contact	V	////	0 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZMU066823

DEKRA

CONDITION REPORT

Report No:
2017316347
DATE
23/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	PASSIVE SPORADIC	B13BCF2	MULTIPLE COLLISION BRAKE, NO FUNCTION	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZMU066823


DEKRA

CONDITION REPORT


Report No:
2017316347
DATE
23/10/2026



INTERIOR (FRONT DRIVER DOOR)



FRONT RIGHT CORNER



90 DEGREE FRONT



90 DEGREE LEFT



REAR LEFT CORNER



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZMU066823

DEKRA

CONDITION REPORT

Report No:
2017316347
DATE
23/10/2026



90 DEGREE RIGHT



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual



Oil cap and dipstick



Expention bottle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZMU066823


DEKRA

CONDITION REPORT

Report No:
2017316347
DATE
23/10/2026



ENGINE 1



RF TYRE TREAD



ENGINE 2



CHASSIS



LF TYRE TREAD



LR TYRE TREAD


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZMU066823

DEKRA

CONDITION REPORT


Report No:
2017316347
DATE
23/10/2026



RR TYRE TREAD



Spare wheel



Shock and brake report



Diagnostic report



Diagnostic report



Diagnostic report

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZMU066823

DEKRA

CONDITION REPORT

Report No:
2017316347
DATE
23/10/2026



Diagnostic report



LICENSE DISC




VIN PLATE OR STICKER



Spare Tyre



Windscreen



Seat Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZMU066823

DEKRA

CONDITION REPORT

Report No:
2017316347
DATE
23/10/2026



Water level



Bonnet



Front Bumper



Front Bumper



Door Front Left



Door Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZMU066823

DEKRA

CONDITION REPORT


Report No:
2017316347
DATE
23/10/2026



Rear Fender Left



Rear bumper




Rear bumper



Number Plate Rear



Boot Lid / Hatch door



Rear Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZMU066823

DEKRA

CONDITION REPORT

Report No:
2017316347
DATE
23/10/2026



Door Rear Right




Door Front Right




Front Fender Right



Engine to silencer pipe



Engine to silencer pipe



Engine to silencer pipe

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZMU066823

DEKRA

CONDITION REPORT

Report No:
2017316347
DATE
23/10/2026



Tyre Rear Right



Tyre Front Right



CV Joint(s) Boot(s) Front Left (inner/outer)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZMU066823