DEKRA

CONDITION REPORT

Report No:
2017316406
DATE
23/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	23/10/2026		
Inspection Date	23/10/2026		

Vehicle Data

Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	MFC
Manufacturer	ISUZU	Registration Number	LHV219NW
Model	D-MAX 250 HO CREWCAB HR D-CAB 4X4 DSL PU [2018-2020]	Register Number	
		Date Of First Licensing	
VIN	ACVNSCHR2J4035570	Last COR	
Engine Number		License Expiry Date	31/10/2026
Doors	4	Power / Displacement	
Color	WHITE	Paint Finish	C - COMMON
Year Model	2019	Fuel	DIESEL
Km Reading	184,719 KM	Transmission	MANUAL
Cab / Body Type	DOUBLE CAB		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ACVNSCHR2J4035570

DEKRA

CONDITION REPORT

Report No:
2017316406
DATE
23/10/2026





Damage	Repair Way
Engine Oil Sweat	Repair
Air Conditioner Defective	Repair
Number Plate Rear Defective	Repair
Front Bumper Paintwork • Scratched	Repair
Door Front Left Paintwork • Chipmarks	Repair
Windscreen Chipped	Repair
Tyre Front Left Worn	Replace
Tyre Front Right Worn	Replace
Gearbox Oil Sweat	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	0.1	0.1	-	
Rear	0.1	0.1	-	
Emergency / Parking	-	-	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	245/70R16C	111/109T	GOODYEAR	WRANGLER	V	4623	1 mm
Front Right	245/70R16C	111/109T	GOODYEAR	WRANGLER	V	4723	1 mm
Rear Left	P245/70R16	106T	LANVIGATOR	CATCHFORS	V	0825	5 mm
Rear Right	P245/70R16	106T	LANGVATOR	CATCHFORS	V	0825	5 mm
Spare	245/70R16C	111/109T	GOODYEAR	WRANGLER	V	0000	5 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ACVNSCHR2J4035570

DEKRA

CONDITION REPORT

Report No:
2017316406
DATE
23/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ECM(ENGINE CONTROL MODULE)	P0234	TURBOCHARGER OVERBOOST CONDITION	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Undercarriage: some bolts on Gear box missing

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Boitumelo Kutumela

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ACVNSCHR2J4035570

DEKRA

CONDITION REPORT


Report No:
2017316406
DATE
23/10/2026



Brake test



Diagnostics




Brake test



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ACVNSCHR2J4035570

DEKRA

CONDITION REPORT


Report No:
2017316406
DATE
23/10/2026



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ACVNSCHR2J4035570


DEKRA

CONDITION REPORT

Report No:
2017316406
DATE
23/10/2026




90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Sparewheel


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ACVNSCHR2J4035570

DEKRA

CONDITION REPORT

Report No:
2017316406
DATE
23/10/2026



LICENSE DISC



VIN PLATE OR STICKER




ENGINE 1



ENGINE 2



CHASSIS



Chasis

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ACVNSCHR2J4035570

DEKRA

CONDITION REPORT


Report No:
2017316406
DATE
23/10/2026



Oil Cap and dipstick




Gearbox



Windscreen



Tyre Front Left



Tyre Front Right



Gearbox


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ACVNSCHR2J4035570

DEKRA

CONDITION REPORT

Report No:
2017316406
DATE
23/10/2026



Engine



Windscreen



Front Bumper



Front Bumper



Front Bumper



Number Plate Rear

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ACVNSCHR2J4035570

DEKRA

CONDITION REPORT

Report No:
2017316406
DATE
23/10/2026



Door Front Left



Air Conditioner



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ACVNSCHR2J4035570