DEKRA

CONDITION REPORT

Report No:
2017313361
DATE
16/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572








Assignment

Client	MFC Auction House	Inspection Location	
Requested Date	16/10/2026		-
Inspection Date	16/10/2026		-

Vehicle Data

Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	ISUZU	Registration Number	LX59SMGP
Model	D-MAX 1.9 DDI X-RIDER HR DSL D-CAB PU AT [2023-2026]	Register Number	
		Date Of First Licensing	
VIN	ACVTFR87JPD162724	Last COR	
Engine Number		License Expiry Date	
Doors	4	Power / Displacement	
Color	GREY	Paint Finish	M - METALLIC
Year Model	2024	Fuel	DIESEL
Km Reading	28,171 KM	Transmission	AUTOMATIC
Cab / Body Type	DOUBLE CAB		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ACVTFR87JPD162724

DEKRA

CONDITION REPORT

Report No:
2017313361
DATE
16/10/2026





Damage	Repair Way
Side Mirror Left Damaged	Repair
Front Bumper Damaged	Repair
Door Front Left Paintwork • Scratched	Repair
Door Rear Left Dented	Repair
Tailgate Dented	Repair
Rear bumper Damaged	Repair
Load Body Dented	Repair
Body exterior	Signs of spray work done on body panels

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	4.0	3.8	-	
Rear	2.8	2.4	-	
Emergency / Parking	2	2.4	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	265/60R18	110H	General	Grabber	V	2124	6 mm
Front Right	265/60R18	110H	General	Grabber	V	2124	6 mm
Rear Left	265/60R18	110H	General	Grabber	V	2124	6 mm
Rear Right	265/60R18	110H	General	Grabber	V	2124	6 mm
Spare	265/60R18	110H	General	Grabber	V	0000	6 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ACVTFR87JPD162724

DEKRA

CONDITION REPORT

Report No:
2017313361
DATE
16/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ABS	U0136_87	LOST COMMUNICATION WITH DLC	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: BOTTOM OF ENGINE IS FULLY COVERED.ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Trevino Julius

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ACVTFR87JPD162724

DEKRA

CONDITION REPORT

Report No:
2017313361
DATE
16/10/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE RIGHT



90 DEGREE LEFT



90 DEGREE FRONT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ACVTFR87JPD162724

DEKRA

CONDITION REPORT


Report No:
2017313361
DATE
16/10/2026



ODOMETER




DASHBOARD (W/ ENGINE RUNNING)




INTERIOR (FRONT DRIVER DOOR)



Automatic transmission



LF TYRE TREAD



LR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ACVTFR87JPD162724

DEKRA

CONDITION REPORT

Report No:
2017313361
DATE
16/10/2026



RR TYRE TREAD



RF TYRE TREAD




Sparewheel



Coolant reservoir



Dipstick and oil cap



REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ACVTFR87JPD162724

DEKRA

CONDITION REPORT

Report No:
2017313361
DATE
16/10/2026



ENGINE 1



ENGINE 2




CHASSIS



VIN PLATE OR STICKER



LICENSE DISC



SHOCK AND BRAKE REPORT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ACVTFR87JPD162724


DEKRA

CONDITION REPORT

Report No:
2017313361
DATE
16/10/2026



DIAGNOSTIC REPORT PAGE 1



DIAGNOSTIC REPORT PAGE 2



Load Body



Load Body



Tailgate



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ACVTFR87JPD162724

DEKRA

CONDITION REPORT

Report No:
2017313361
DATE
16/10/2026




Load Body



Door Front Left



Side Mirror Left



Front Bumper



Door Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ACVTFR87JPD162724