DEKRA

CONDITION REPORT

Report No:
2017315998
DATE
23/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	
Requested Date	23/10/2026		-
Inspection Date	23/10/2026		-

Vehicle Data

Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	ISUZU	Registration Number	LH20LJGP
Model	D-MAX 3.0 DDI LSE 4X4 EX-CAB DSL PU AT [2022-2023]	Register Number	
		Date Of First Licensing	
VIN	ACVTFS40JMD127410	Last COR	
Engine Number		License Expiry Date	30/09/2025
Doors	4	Power / Displacement	
Color	WHITE	Paint Finish	TWO COAT UNI
Year Model	2023	Fuel	DIESEL
Km Reading	81,305 KM	Transmission	AUTOMATIC
Cab / Body Type	SUPER CAB		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ACVTFS40JMD127410

DEKRA

CONDITION REPORT

Report No:
2017315998
DATE
23/10/2026





Damage	Repair Way
Engine Oil Leak	Repair
Front Bumper Damaged	Repair
Bonnet Paintwork • Chipmarks	Repair
Front Fender Right Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Right Damaged	Repair
Tailgate Dented	Repair
Rear bumper Damaged	Repair
Windscreen Damaged	Replace
Differential Oil Leak	Replace

Brakes

Brake Test Results

No Brake Test on a brake test machine has been performed.

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	-	-	-	
Rear	-	-	-	
Emergency / Parking	-	-	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	265/60R18	110H	General	Radial	V	1623	3 mm
Front Right	265/60R18	110H	General	Radial	V	1623	3 mm
Rear Left	265/60R18	110H	General	Radial	V	1623	3 mm
Rear Right	265/60R18	110H	General	Radial	V	1623	3 mm
Spare	265/60R18	110H	General	Radial	V	////	4 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ACVTFS40JMD127410

DEKRA

CONDITION REPORT

Report No:
2017315998
DATE
23/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ABS	C0020_01	PUMP MOTOR ELECTRICAL FAULT	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. 27 DTC'S AT TIME OF TESTING SEE DTC REPORT.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ACVTFS40JMD127410

DEKRA

CONDITION REPORT

Report No:
2017315998
DATE
23/10/2026



INTERIOR (FRONT DRIVER DOOR)



FRONT RIGHT CORNER



90 DEGREE FRONT



90 DEGREE LEFT



REAR LEFT CORNER



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ACVTFS40JMD127410

DEKRA

CONDITION REPORT

Report No:
2017315998
DATE
23/10/2026



90 DEGREE RIGHT



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic.



ENGINE 1



Oil cap and dipstick.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ACVTFS40JMD127410


DEKRA

CONDITION REPORT


Report No:
2017315998
DATE
23/10/2026




Brake test.



Diagnostic.




Diagnostic.



Diagnostic.



Undercarriage front.



Undercarriage rear.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ACVTFS40JMD127410


DEKRA

CONDITION REPORT


Report No:
2017315998
DATE
23/10/2026




LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ACVTFS40JMD127410

DEKRA

CONDITION REPORT

Report No:
2017315998
DATE
23/10/2026



Water level



Front Bumper



Front Bumper



Bonnet



Rear bumper



Tailgate

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ACVTFS40JMD127410

DEKRA

CONDITION REPORT

Report No:
2017315998
DATE
23/10/2026



Door Rear Right



Door Front Right



Front Fender Right



Windscreen



Engine



Differential

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ACVTFS40JMD127410