DEKRA

CONDITION REPORT

Report No:
2017317285
DATE
26/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	26/10/2026		
Inspection Date	26/10/2026		

Vehicle Data

Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	CHEVROLET	Registration Number	KNW143MP
Model	UTILITY 1.4 AC BASE PU [2011-2017]	Register Number	
VIN	ADMJF4MR6H4787532	Date Of First Licensing	
Engine Number		Last COR	
Doors	2	License Expiry Date	31/10/2026
Color	WHITE	Power / Displacement	
Year Model	2016	Paint Finish	TWO COAT UNI
Km Reading	244,020 KM	Fuel	PETROL
Cab / Body Type	SINGLE CAB	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMJF4MR6H4787532

DEKRA

CONDITION REPORT

Report No:
2017317285
DATE
26/10/2026





Damage	Repair Way
Engine Oil Leak	Repair
Engine Wiring Damaged	Replace
Under bonnet insulation cover Damaged	Replace
Radio/CD/USB Defective	Repair
Heater control Damaged	Replace
Center Console / Cubbyhole + Lid Damaged	Repair
Tail Light Left Defective	Repair
Tail Light Right Defective	Repair
Headlight Left Damaged	Replace
Headlight Right Damaged	Replace
Seat Front Left Damaged	Replace
Seat Front Right Damaged	Repair
Sun Visor Right Damaged	Repair
Hood Lining Dirty	Repair
Door Handle Front Left Missing	Replace
Door Sealing Rubber Front Left Damaged	Replace
Door Sealing Rubber Front Right Damaged	Replace
Door Lock Front Left Damaged	Replace
Dash Padding Damaged	Repair
Clutch Pedal Rubber Damaged	Replace
Brake Pedal Rubber Damaged	Replace
Steering Wheel Trim Excessive Wear & Tear	Repair
Side Mirror Left Damaged	Replace
Front Bumper Damaged	Replace
Bonnet Dented	Repair
Front Fender Left Residual Traces of Repair	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Paintwork • Scratched	Repair
Tailgate Damaged	Repair
Rear bumper Damaged	Repair
Sill Panel Left Damaged	Repair
Roof Damaged	Repair
Load Body Damaged	Repair
Windscreen Damaged	Replace
Parking Brake Performance Left / Right Difference out of legal range	Repair
Shock Absorber Front Left Sweat	Replace
Shock Absorber Front Right Sweat	Replace
Shock Absorber Rear Right Sweat	Replace
Mounting Rubber(s) Rear Axle Left Cracked	Replace
Rim Front Right Dented	Repair
Bolt(s) / Nut(s) Front Wheel Right Missing	Replace
Chassis Scratched	Repair
Brakes Insufficient	Replace
Jack Missing	Replace
Left seat adjuster handle missing	Replace
Tailgate handle damaged	Replace
Vehicle antenna missing	Replace
Spare wheel missing	Replace
Original ignition missing	Replace
Aftermarket ignition fitted to vehicle	Replace
Loose wiring inside of vehicle	Replace

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMJF4MR6H4787532

DEKRA

CONDITION REPORT

Report No:
2017317285
DATE
26/10/2026

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.72	2.73	-	
Rear	1.67	1.71	-	
Emergency / Parking	0.16	1.88	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/65 R14	86H	Autogrip	P308	V	0225	3 mm
Front Right	185/65 R14	86H	Autogrip	P308	V	0225	3 mm
Rear Left	185/65 R14	86H	Autogrip	P308	V	0225	5 mm
Rear Right	185/65 R14	86H	Autogrip	P308	V	0225	5 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Electrical Components and Instruments: Radio has no sound
Lights: Left and right tail light lenses faded.
Interior: Vehicle interior dirty and panels scratched.
Body • Exterior: Poor residual traces of repair on body panels.Body panels misaligned.Stone chips and spray work on body panels.Dents and scratches on body panels.
Road Test: Gearbox faulty.Vehicle does not engage into 3rd gear.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMJF4MR6H4787532

DEKRA

CONDITION REPORT

Report No:
2017317285
DATE
26/10/2026

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMJF4MR6H4787532

DEKRA

CONDITION REPORT

Report No:
2017317285
DATE
26/10/2026



INTERIOR (FRONT DRIVER DOOR)



FRONT RIGHT CORNER



90 DEGREE FRONT



90 DEGREE LEFT



REAR LEFT CORNER



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMJF4MR6H4787532

DEKRA

CONDITION REPORT

Report No:
2017317285
DATE
26/10/2026



90 DEGREE RIGHT



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual Transmission



Oil cap and dipstick



ENGINE 1


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMJF4MR6H4787532

DEKRA

CONDITION REPORT

Report No:
2017317285
DATE
26/10/2026



Front chassis



Rear chassis



LF TYRE TREAD



LR TYRE TREAD



RF TYRE TREAD



RR TYRE TREAD


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMJF4MR6H4787532


DEKRA

CONDITION REPORT

Report No:
2017317285
DATE
26/10/2026




Brake and shock absorber repor



Diagnostic report



Engine oil sump dented



Aftermarket ignition



Loose wiring



Spare wheel Accessories

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMJF4MR6H4787532

DEKRA

CONDITION REPORT

Report No:
2017317285
DATE
26/10/2026



Tailgate handle



LICENSE DISC



VIN PLATE OR STICKER



Steering Wheel Trim



Center Console / Cubbyhole + Lid



Heater control

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMJF4MR6H4787532

DEKRA

CONDITION REPORT

Report No:
2017317285
DATE
26/10/2026



Sun Visor Right



Hood Lining



Door Sealing Rubber Front Right



Seat Front Right



Seat Front Right



Rear Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMJF4MR6H4787532

DEKRA

CONDITION REPORT

Report No:
2017317285
DATE
26/10/2026



Door Front Right



Door Front Right



Front Fender Right



Windscreen



Bonnet



Front Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMJF4MR6H4787532

DEKRA

CONDITION REPORT

Report No:
2017317285
DATE
26/10/2026



Door Front Left



Rear Fender Left



Door Handle Front Left



Door Sealing Rubber Front Left



Seat Front Left



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMJF4MR6H4787532

DEKRA

CONDITION REPORT

Report No:
2017317285
DATE
26/10/2026



Rear bumper



Rear bumper




Tailgate



Load Body



Roof



Parking Brake Performance

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMJF4MR6H4787532

DEKRA

CONDITION REPORT

Report No:
2017317285
DATE
26/10/2026



Headlight Left



Headlight Right



Under bonnet insulation cover



Bolt(s) / Nut(s) Front Wheel Right



Shock Absorber Front Right



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMJF4MR6H4787532

DEKRA

CONDITION REPORT

Report No:
2017317285
DATE
26/10/2026



Front Bumper



Front Bumper



Shock Absorber Front Left



Sill Panel Left



Engine



Engine Wiring

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMJF4MR6H4787532

DEKRA

CONDITION REPORT

Report No:
2017317285
DATE
26/10/2026



Mounting Rubber(s) Rear Axle Left



Shock Absorber Rear Right



Chassis



Rim Front Right



Water level



Clutch Pedal Rubber

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMJF4MR6H4787532

DEKRA

CONDITION REPORT

Report No:
2017317285
DATE
26/10/2026



Brake Pedal Rubber



Dash Padding



Radio/CD/USB



Door Lock Front Left



Side Mirror Left



Tail Light Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMJF4MR6H4787532

DEKRA

CONDITION REPORT

Report No:
2017317285
DATE
26/10/2026



Tail Light Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMJF4MR6H4787532