DEKRA

# CONDITION REPORT

**Report No:**
**2017310484**
**DATE**
**12/10/2026**

*MFC Auction House*
*M57 Pretoria Rd, Glenmarais, KEMPTON PARK*
*Gauteng*

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572








## Assignment

| | | | |
|---|---|---|---|
| Client | MFC Auction House | Inspection Location | MFC<br>M57 Pretoria Road - 1619<br>Kempton Park - |
| Requested Date | 12/10/2026 | | |
| Inspection Date | 12/10/2026 | | |

## Vehicle Data

| | | | |
|---|---|---|---|
| Vehicle Type | LIGHT LOAD VEHICLE | Registered Owner | MFC |
| Manufacturer | NISSAN | Registration Number | BP96HSGP |
| Model | NP200 1.6 8V BASE PU [2009-2019] | Register Number | |
| VIN | ADNUSN1D5U0036983 | Date Of First Licensing | |
| Engine Number | | Last COR | |
| Doors | 2 | License Expiry Date | 30/04/2018 |
| Color | WHITE | Power / Displacement | |
| Year Model | 2011 | Paint Finish | C - COMMON |
| Km Reading | 105,547 KM | Fuel | PETROL |
| Cab / Body Type | SINGLE CAB | Transmission | MANUAL |

## Vehicle Options & Accessories

**Items**

## VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0036983

DEKRA

# CONDITION REPORT

**Report No:**
**2017310484**
**DATE**
**12/10/2026**





| Damage | Repair Way |
|---|---|
| Engine Wiring Torn / Cut | Repair |
| Tail Light Left Damaged | Replace |
| Seat Front Right Torn / Cut | Repair |
| Gear Lever Dust Boot Torn / Cut | Replace |
| Front Bumper Paintwork • Flaking | Repair |
| Bonnet Residual Traces of Repair | Repair |
| Bonnet slam plate (Shock tower/ Inner tray) Welded | Smart Repair |
| A • Pillar Left Residual Traces of Repair | Repair |
| B • Pillar Left Residual Traces of Repair | Repair |
| Front Fender Left Residual Traces of Repair | Repair |
| Front Fender Right Dented | Repair |
| Front Fender Left / Inner Tray Corrosion | Repair |
| Rear Fender Left / Inner Tray Residual Traces of Repair | Repair |
| Door Front Left Residual Traces of Repair | Repair |
| Door Front Right Residual Traces of Repair | Repair |
| Roof Residual Traces of Repair | Repair |
| Load Body Residual Traces of Repair | Repair |
| Windscreen Chipped | Repair |
| Brake Piping Leak | Repair |
| Tie Rod End right Damaged | Replace |
| Stabilizer Mounting Front Left Damaged | Replace |
| Tyre Rear Left Excessive Wear & Tear | Replace |
| Rim Front Left Deformed | Repair |
| Rim Rear Right Deformed | Repair |
| Main Beam Right Residual Traces of Repair | Repair |
| Engine to silencer pipe Torn / Cut | Replace |
| CV Joint(s) Boot(s) Front Left (inner/outer) Damaged | Replace |
| CV Joint(s) Boot(s) Front Right (inner/outer) Damaged | Replace |
| Gear Selections Insufficient | Repair |
| Steering column cover missing | Replace |
| No reverse gear | Repair |
| Rear tyres size differs | Replace |

## Brakes

### Brake Test Results

| | Left | Right | | |
|---|---|---|---|---|
| | Braking Force [KN] | Braking Force [KN] | Axle Weight [KG] | Deceleration [m/s²] |
| **Front** | 2.4 | 2.5 | - | |
| **Rear** | 0.9 | 1.0 | - | |
| **Emergency / Parking** | 1.4 | 1.2 | - | |

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0036983

DEKRA

# CONDITION REPORT

**Report No:**
**2017310484**
**DATE**
**12/10/2026**

## Tyres and Rims

### Tyre Specification & Measurement

| | Size | Load/Speed Index | Manufacture | Model | Type* | Production Date | Tread Depth (mm) |
|---|---|---|---|---|---|---|---|
| **Front Left** | 195/60R15 | 88H | Roadking | Radial | V | 0316 | 5 mm |
| **Front Right** | 195/60R15 | 88H | Roadking | Radial | V | 0316 | 4 mm |
| **Rear Left** | 185/65R15 | 88H | Royal black | Mile | V | 1123 | 1 mm |
| **Rear Right** | 195/60R15 | 88H | Roadking | Radial | V | 0316 | 6 mm |

* Tyre Legend: V=Virgin, R=Recap

## Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

| No | System | Code | Description | Status |
|---|---|---|---|---|
| 1 | BCM | 000100 | PLEASE REFER TO VEHICLE SERVICE MANUAL | |

## Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

## Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Engine Compartment: Bottom of engine is fully covered.
Body • Exterior: Residual traces of poor repair on body panels. Signs of spray work done on body panels.

## Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

## Technician

Trevino Julius

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0036983

DEKRA

# CONDITION REPORT

**Report No:**
**2017310484**
**DATE**
**12/10/2026**



Shock and brake



Diagnostics report



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0036983

DEKRA

# CONDITION REPORT

**Report No:**
**2017310484**
**DATE**
**12/10/2026**



ODOMETER


Manual transmission



90 DEGREE FRONT


90 DEGREE RIGHT



90 DEGREE REAR


90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0036983

DEKRA

# CONDITION REPORT

**Report No:**
**2017310484**
**DATE**
**12/10/2026**




LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



No sparewheel




LICENSE DISC

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0036983

DEKRA

# CONDITION REPORT

**Report No:**
**2017310484**
**DATE**
**12/10/2026**



VIN PLATE OR STICKER


ENGINE 1


ENGINE 2


CHASSIS


REAR


Expansion bottle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0036983

DEKRA

# CONDITION REPORT

**Report No:**
**2017310484**
**DATE**
**12/10/2026**



Oil cap and dipstick



Steering column cover missing




Steering column cover missing



Exposed interior wiring



Water level



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0036983

DEKRA

# CONDITION REPORT

**Report No:**
**2017310484**
**DATE**
**12/10/2026**



Front Fender Right



Door Front Right




Load Body



Roof



Seat Front Right



Tail Light Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0036983

DEKRA

# CONDITION REPORT

**Report No:**
**2017310484**
**DATE**
**12/10/2026**




Roof



Load Body



Door Front Left



Front Fender Left



Bonnet



Windscreen

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0036983

DEKRA

# CONDITION REPORT

**Report No:**
**2017310484**
**DATE**
**12/10/2026**



Main Beam Right



Main Beam Right



Bonnet slam plate (Shock tower/ Inner tray)



Front Fender Left / Inner Tray



Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0036983

DEKRA

# CONDITION REPORT

**Report No:**
**2017310484**
**DATE**
**12/10/2026**



Rim Front Left


Rear Fender Left / Inner Tray


Rear Fender Left / Inner Tray



Rim Rear Right



Rim Rear Right


CV Joint(s) Boot(s) Front Left (inner/outer)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0036983

DEKRA

# CONDITION REPORT

**Report No:**
**2017310484**
**DATE**
**12/10/2026**



Tie Rod End right



CV Joint(s) Boot(s) Front Right (inner/outer)



Front Fender Left / Inner Tray



Stabilizer Mounting Front Left



Engine to silencer pipe



Engine to silencer pipe

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0036983

DEKRA

# CONDITION REPORT

**Report No:**
**2017310484**
**DATE**
**12/10/2026**



Engine Wiring



Engine Wiring



Tyre Rear Left



Tyre Rear Left



Brake Piping



Brake Piping

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0036983

DEKRA

# CONDITION REPORT

**Report No:**
**2017310484**
**DATE**
**12/10/2026**



Roof



A • Pillar Left



A • Pillar Left



B • Pillar Left



B • Pillar Left



Door Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0036983

DEKRA

# CONDITION REPORT


**Report No:**
**2017310484**
**DATE**
**12/10/2026**



Door Front Left



Door Front Left



Door Front Left



Door Front Left



Door Front Left



Gear Lever Dust Boot

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0036983