DEKRA

CONDITION REPORT

Report No:
2017308480
DATE
07/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park -
Requested Date	07/10/2026		
Inspection Date	07/10/2026		

Vehicle Data

Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	MFC
Manufacturer	NISSAN	Registration Number	MC78PMGP
Model	NP200 1.6 8V BASE +AC SAFETY PU [2011-2025]	Register Number	
		Date Of First Licensing	
VIN	ADNUSN1D5U0194687	Last COR	
Engine Number		License Expiry Date	
Doors	2	Power / Displacement	
Color	WHITE	Paint Finish	TWO COAT UNI
Year Model	2021	Fuel	PETROL
Km Reading	143,661 KM	Transmission	MANUAL
Cab / Body Type	SINGLE CAB		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0194687

DEKRA

CONDITION REPORT

Report No:
2017308480
DATE
07/10/2026





Damage	Repair Way
Engine Oil Sweat	Repair
Engine Wiring Defective	Repair
Power Steering Pump / Electronic Unit Defective	Repair
Heater control Damaged	Replace
Tail Light Left Damaged	Replace
Seat Front Left Torn / Cut	Repair
Seat Front Right Damaged	Repair
Door Panel Front Left Damaged	Repair
Door Lock Front Left Damaged	Replace
Door Lock Front Right Damaged	Replace
Side Mirror Left Damaged	Repair
Side Mirror Right Paintwork • Scratched	Repair
Front Bumper Paintwork • Scratched	Repair
Bonnet Dented	Repair
Front Fender Left Residual Traces of Repair	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Paintwork • Scratched	Repair
Rear Fender Right Damaged	Repair
Rear Fender Left / Inner Tray Damaged	Repair
Rear Fender Right / Inner Tray Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Tailgate Damaged	Repair
Rear bumper Damaged	Repair
Roof Dented	Repair
Load Body Damaged	Repair
Windscreen Chipped	Repair
Back Window Damaged	Replace
Tie Rod End right Damaged	Replace
Tyre Front Left Damaged	Replace
Tyre Rear Left Damaged	Replace
Spare Tyre Worn	Replace
Chassis Dented	Repair
Belly plates Damaged	Repair
Deceleration parking brake defective	Repair
Oil sludge on oil cap	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.85	3.05	-	
Rear	1.99	2.3	-	
Emergency / Parking	0.82	0.55	-	

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0194687

DEKRA

CONDITION REPORT

Report No:
2017308480
DATE
07/10/2026

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/65R15	92T	Dunlop	Sp-Touring	V	4223	1 mm
Front Right	185/65R15	92T	Dunlop	Sp-Touring	V	4423	1 mm
Rear Left	185/65R15	92H	Dunlop	Sp-Sport	V	4822	0 mm
Rear Right	185/65R15	88H	Tranzano	Radial	V	5123	4 mm
Spare	185/65R15	88H	Firestone	Touring	V	0320	0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	AIR BAG	B1040	AIRBAG MALFUNCTION INDICATOR LAMP(MIL) CIRCUIT	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: Engine Compartment: Power Steering reservoir strapped with cable ties.
Interior: Fuel flap release handle not opening. The vehicle interior is dirty, and the panels are scratched.
Body • Exterior: Dents and scratches on body panels. Signs of impact damage to the rear of the vehicle. Body panels misaligned. Residual traces of repair on body panels.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0194687


DEKRA

CONDITION REPORT

Report No:
2017308480
DATE
07/10/2026



Brake and shock absorber repor



Front chassis




Rear chassis



Diagnostic report



Spare wheel



Spare wheel Accessories


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0194687

DEKRA

CONDITION REPORT

Report No:
2017308480
DATE
07/10/2026



Oil cap and dipstick



Manual Transmission



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0194687

DEKRA

CONDITION REPORT

Report No:
2017308480
DATE
07/10/2026



ODOMETER



90 DEGREE FRONT


90 DEGREE RIGHT



90 DEGREE REAR


90 DEGREE LEFT


LF TYRE TREAD


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0194687


DEKRA

CONDITION REPORT

Report No:
2017308480
DATE
07/10/2026



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0194687

DEKRA

CONDITION REPORT


Report No:
2017308480
DATE
07/10/2026




Seat Front Right



Rear Fender Right



Door Front Right



Front Fender Right



Roof



Windscreen

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0194687

DEKRA

CONDITION REPORT

Report No:
2017308480
DATE
07/10/2026



Bonnet



Front Fender Left



Rear Fender Left



Rear Fender Left



Door Front Left



Side Mirror Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0194687

DEKRA

CONDITION REPORT

Report No:
2017308480
DATE
07/10/2026



Seat Front Left



Seat Front Left



Back Window



Door Panel Front Left



Tail Light Left



Heater control

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0194687

DEKRA

CONDITION REPORT

Report No:
2017308480
DATE
07/10/2026



Rear bumper


Rear bumper



Tailgate


Load Body



Front Bumper


Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0194687

DEKRA

CONDITION REPORT

Report No:
2017308480
DATE
07/10/2026



Tyre Front Left



Rear Fender Left / Inner Tray



Rear Fender Right / Inner Tray



Belly plates



Belly plates



Chassis

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0194687

DEKRA

CONDITION REPORT

Report No:
2017308480
DATE
07/10/2026



Chassis



Tyre Rear Left



Spare Tyre



Load Body



Tie Rod End right



Engine

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0194687

DEKRA

CONDITION REPORT


Report No:
2017308480
DATE
07/10/2026



Side Mirror Right



Water level



Engine Wiring



Engine Wiring



Power Steering Pump / Electronic Unit



Door Lock Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0194687

DEKRA

CONDITION REPORT

Report No:
2017308480
DATE
07/10/2026



Door Lock Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0194687