DEKRA

CONDITION REPORT

Report No:
2017314654
DATE
21/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	21/10/2026		
Inspection Date	21/10/2026		

Vehicle Data

Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	
Manufacturer	FORD	Registration Number	HHZ184L
Model	RANGER	Register Number	
VIN	AFAGXXMJ2GCT80215	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	31/12/2026
Color	WHITE	Power / Displacement	
Year Model		Paint Finish	TWO COAT UNI
Km Reading	193,735 KM	Fuel	DIESEL
Cab / Body Type	SUPER CAB	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFAGXXMJ2GCT80215

DEKRA

CONDITION REPORT

Report No: 2017314654
DATE 21/10/2026



Damage	Repair Way
Engine Oil Leak	Repair
Central Air Vent Damaged	Replace
Switch Electrical Window Winder front left Damaged	Repair
Switch Electrical Window Winder front right Damaged	Replace
Seat Front Right Damaged	Replace
Door Handle Rear Left Damaged	Replace
Door Handle Rear Right Damaged	Replace
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Damaged	Repair
Tailgate Damaged	Repair
Rear bumper Damaged	Repair
Tyre Front Left Worn	Replace
Tyre Front Right Worn	Replace
Tyre Rear Right Damaged	Replace
Spare Tyre Worn	Replace
Gearbox Oil Leak	Repair
Both front electric windows do not open.	Repair

Brakes

Brake Test Results

No Brake Test on a brake test machine has been performed.

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	-	-	-	
Rear	-	-	-	
Emergency / Parking	-	-	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	255/70R16	117S	BFGoodrich	Radial	V	4318	0 mm
Front Right	255/70R16	117S	BFGoodrich	Radial	V	4318	0 mm
Rear Left	255/70R16	111T	Continental	Crosscontact	V	3722	2 mm
Rear Right	255/70R16	111T	Continental	Crosscontact	V	1022	1 mm
Spare	255/70R16	111T	Continental	Crosscontact	V	4718	0 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFAGXXMJ2GCT80215

DEKRA

CONDITION REPORT

Report No:
2017314654
DATE
21/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	PCM	P0671:00-2F	CYLINDER ONE GLOW PLUG CIRCUIT OPEN	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.SIGNS OF REPAIR WORK DONE TO BODY PANELS. POOR ALIGNMENT TO SOMEBODY PANELS / 24 DTC'S AT TIME OF TESTING SEE DTC REPORT.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFAGXXMJ2GCT80215

DEKRA

CONDITION REPORT

Report No:
2017314654
DATE
21/10/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFAGXXMJ2GCT80215

DEKRA

CONDITION REPORT

Report No:
2017314654
DATE
21/10/2026



INTERIOR (FRONT DRIVER DOOR)



Automatic.



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFAGXXMJ2GCT80215

DEKRA

CONDITION REPORT

Report No:
2017314654
DATE
21/10/2026



ENGINE 1



Undercarriage front.



Undercarriage rear.



Oil cap and dipstick.



LF TYRE TREAD



RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFAGXXMJ2GCT80215

DEKRA

CONDITION REPORT


Report No:
2017314654
DATE
21/10/2026




LR TYRE TREAD




RR TYRE TREAD



Brake test.



Diagnostic Report page 1



Diagnostic Report page 2



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFAGXXMJ2GCT80215

DEKRA

CONDITION REPORT

Report No:
2017314654
DATE
21/10/2026



Front Bumper




Front Bumper



Bonnet



Front Fender Left



Door Front Left



Door Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFAGXXMJ2GCT80215

DEKRA

CONDITION REPORT

Report No:
2017314654
DATE
21/10/2026



Rear Fender Left




Rear bumper



Rear bumper



Tailgate


Door Rear Right


Door Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFAGXXMJ2GCT80215


DEKRA

CONDITION REPORT

Report No:
2017314654
DATE
21/10/2026



Rear Fender Right




Front Fender Right



Switch Electrical Window Winder front right



Switch Electrical Window Winder front left



Seat Front Right



Door Handle Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFAGXXMJ2GCT80215

DEKRA

CONDITION REPORT

Report No:
2017314654
DATE
21/10/2026



Door Handle Rear Left




Spare Tyre



Central Air Vent



Central Air Vent



Central Air Vent



Engine

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFAGXXMJ2GCT80215

DEKRA

CONDITION REPORT

Report No:
2017314654
DATE
21/10/2026




Gearbox



Tyre Front Right



Tyre Front Left



Tyre Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFAGXXMJ2GCT80215