DEKRA

CONDITION REPORT

Report No:
2017307847
DATE
08/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park -
Requested Date	08/10/2026		
Inspection Date	08/10/2026		

Vehicle Data

Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	MFC
Manufacturer	FORD	Registration Number	JR17TGGP
Model	RANGER 2.2 TDCI XLS 4X4 DSL PU AT [2020-2021]	Register Number	
		Date Of First Licensing	
VIN	AFANXXMJ2NKT42214	Last COR	
Engine Number		License Expiry Date	
Doors	2	Power / Displacement	
Color	WHITE	Paint Finish	C - COMMON
Year Model	2020	Fuel	DIESEL
Km Reading	243,840 KM	Transmission	AUTOMATIC
Cab / Body Type	SINGLE CAB		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFANXXMJ2NKT42214

DEKRA

CONDITION REPORT

Report No:
2017307847
DATE
08/10/2026



Damage	Repair Way
Seat Front Right Torn / Cut	Repair
Front Fender Left Paintwork • Scratched	Repair
Door Front Left Residual Traces of Repair	Repair
Load Body Paintwork • Scratched	Repair
Gearbox Oil Leak	Repair
Differential Oil Leak	Repair
Engine Performance Insufficient	Repair
4x4 Differential Lock Insufficient	Repair
Low and High Range Selection Insufficient	Repair
Body exterior	Residual traces of repair work on body panels
Body exterior	Minor dents scratches stone chips on body panels
Body exterior	Signs of spray work done on body panels
Engine	Bottom of engine is fully covered
Warning lights illuminated	Repair

Brakes

Brake Test Results

No Brake Test on a brake test machine has been performed.

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	-	-	-	
Rear	-	-	-	
Emergency / Parking	-	-	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	265/65R17	112S	Bridgestone	Dueler	V	2423	5 mm
Front Right	265/65R17	112S	Bridgestone	Dueler	V	2423	3 mm
Rear Left	265/65R17	112T	Annaite	AN906	V	0626	9 mm
Rear Right	265/65R17	112S	Bridgestone	Dueler	V	3522	2 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFANXXMJ2NKT42214

DEKRA

CONDITION REPORT

Report No:
2017307847
DATE
08/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	POWERTRAIN CONTROL MODULE	P0313:68&28	MISFIRE DETECTED WITH LOW FUEL	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE: NORMAL WEAR AND TEAR MARKS ON THE BODY, INTERIOR, AND MECHANICAL.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Trevino Julius

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFANXXMJ2NKT42214

DEKRA

CONDITION REPORT

Report No:
2017307847
DATE
08/10/2026




Shock test



Diagnostics report



Diagnostics report



Diagnostics report



No sparewheel



Expansion bottle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFANXXMJ2NKT42214

DEKRA

CONDITION REPORT

Report No:
2017307847
DATE
08/10/2026



Oil cap and dipstick



Automatic transmission



Warning lights illuminated



No license disc



FRONT RIGHT CORNER



REAR LEFT CORNER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFANXXMJ2NKT42214

DEKRA

CONDITION REPORT

Report No:
2017307847
DATE
08/10/2026



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFANXXMJ2NKT42214


DEKRA

CONDITION REPORT


Report No:
2017307847
DATE
08/10/2026



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



VIN PLATE OR STICKER


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFANXXMJ2NKT42214

DEKRA

CONDITION REPORT


Report No:
2017307847
DATE
08/10/2026



REAR




ENGINE 1



ENGINE 2



CHASSIS



Load Body



Load Body

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFANXXMJ2NKT42214

DEKRA

CONDITION REPORT

Report No:
2017307847
DATE
08/10/2026



Load Body



Front Fender Left



Door Front Left



Load Body



Load Body



Gearbox


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFANXXMJ2NKT42214

DEKRA

CONDITION REPORT

Report No:
2017307847
DATE
08/10/2026



Gearbox



Differential



Differential



Seat Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFANXXMJ2NKT42214