CONDITION REPORT

Report No:
2017318911
DATE
29/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	29/10/2026		
Inspection Date	29/10/2026		

Vehicle Data

Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	FORD	Registration Number	LGG614NW
Model	RANGER 2.2 TDCI XL 4X4 DSL D-CAB PU AT [2020-2021]	Register Number	
		Date Of First Licensing	
VIN	AFAPXXMJ2PLT55247	Last COR	
Engine Number		License Expiry Date	31/05/2026
Doors	4	Power / Displacement	
Color	WHITE	Paint Finish	TWO COAT UNI
Year Model	2021	Fuel	DIESEL
Km Reading	203,015 KM	Transmission	AUTOMATIC
Cab / Body Type	DOUBLE CAB		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFAPXXMJ2PLT55247

DEKRA

CONDITION REPORT

Report No:
2017318911
DATE
29/10/2026



Damage	Repair Way
Under bonnet insulation cover Damaged	Repair
Air Conditioner Insufficient	Repair
Tail Light Left Damaged	Replace
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Residual Traces of Repair	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Right Damaged	Repair
Rear bumper Damaged	Repair
Rocker Panel Right Damaged	Replace
Windscreen Damaged	Replace
Differential Oil Leak	Repair

Brakes

Brake Test Results

No Brake Test on a brake test machine has been performed.

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	-	-	-	
Rear	-	-	-	
Emergency / Parking	-	-	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	255/70R16	111H	Annaite	Radial	V	0124	3 mm
Front Right	255/70R16	111H	Annaite	Radial	V	0124	3 mm
Rear Left	2550l/70R16	111H	Annaite	Radial	V	0124	3 mm
Rear Right	255/70R16	111H	Annaite	Radial	V	0124	3 mm
Spare	255/70R16	111T	Continental	Crosscontact	V	4420	3 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFAPXXMJ2PLT55247

DEKRA

CONDITION REPORT

Report No:
2017318911
DATE
29/10/2026

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Electrical Components and Instruments: aircon does not make cold air. vehicle electronics malfunctioning.
Body • Exterior: Minor dents and scratches and stone chips to body panels. Signs of repair work done to body panels. Poor alignment to somebody panels.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE
RIGHT FRONT WHEEL CENTER
CAP MISSING.

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFAPXXMJ2PLT55247

DEKRA

CONDITION REPORT

Report No:
2017318911
DATE
29/10/2026



INTERIOR (FRONT DRIVER DOOR)



FRONT RIGHT CORNER



90 DEGREE FRONT



90 DEGREE LEFT



REAR LEFT CORNER



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFAPXXMJ2PLT55247

DEKRA

CONDITION REPORT

Report No:
2017318911
DATE
29/10/2026



90 DEGREE RIGHT



ODOMETER



DASHBOARD (W/ ENGINE RUNNING)



Automatic.



ENGINE 1



Oil cap and dipstick.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFAPXXMJ2PLT55247

DEKRA

CONDITION REPORT


Report No:
2017318911
DATE
29/10/2026



Undercarriage front.




Undercarriage rear.



RF TYRE TREAD



RR TYRE TREAD



LR TYRE TREAD



LF TYRE TREAD


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFAPXXMJ2PLT55247


DEKRA

CONDITION REPORT


Report No:
2017318911
DATE
29/10/2026



Brake test.



Diagnostic.



Diagnostic.



LICENSE DISC



VIN PLATE OR STICKER



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFAPXXMJ2PLT55247

DEKRA

CONDITION REPORT

Report No:
2017318911
DATE
29/10/2026



Under bonnet insulation cover



Front Bumper



Front Bumper



Bonnet



Front Fender Left



Door Front Left


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFAPXXMJ2PLT55247

DEKRA

CONDITION REPORT

Report No:
2017318911
DATE
29/10/2026



Rear Fender Left




Rear bumper




Rear bumper



Rear Fender Right



Door Front Right



Door Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFAPXXMJ2PLT55247

DEKRA

CONDITION REPORT

Report No:
2017318911
DATE
29/10/2026



Front Fender Right



Windscreen



Air Conditioner



Tail Light Left



Rocker Panel Right



Differential

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFAPXXMJ2PLT55247