DEKRA

CONDITION REPORT

Report No:
2017310688
DATE
12/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572








Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park -
Requested Date	12/10/2026		
Inspection Date	12/10/2026		

Vehicle Data

Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	MFC
Manufacturer	FORD	Registration Number	MG42WBGP
Model	RANGER 3.0 V6 PLATINUM 4WD DSL D-CAB PU OPT PLAN 10-SP AT [2024-2026]	Register Number	
		Date Of First Licensing	
VIN	AFAPXXMJ2PRE41003	Last COR	
Engine Number		License Expiry Date	28/02/2027
Doors	4	Power / Displacement	
Color	WHITE	Paint Finish	C - COMMON
Year Model	2025	Fuel	DIESEL
Km Reading	78,629 KM	Transmission	AUTOMATIC
Cab / Body Type	DOUBLE CAB		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFAPXXMJ2PRE41003

DEKRA

CONDITION REPORT

Report No:
2017310688
DATE
12/10/2026





Damage	Repair Way
Front Bumper Paintwork • Scratched	Repair
Grill Damaged	Replace
Door Rear Left Paintwork • Scratched	Repair
Load Body Paintwork • Scratched	Repair
Windscreen Cracked	Replace
Tyre Rear Left Smooth	Replace
Rim Front Right Deformed	Repair

Brakes

Brake Test Results

No Brake Test on a brake test machine has been performed.

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	-	-	-	
Rear	-	-	-	
Emergency / Parking	-	-	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	255/50R20	109Y	Dimax	Radar		0924	5 mm
Front Right	255/50R20	109Y	Dimax	Radar	V	0924	2 mm
Rear Left	255/55R20	110V	Goodyear	Wrangler	V	0124	0 mm
Rear Right	255/55R20	110V	Goodyear	Wrangler	V	0124	3 mm
Spare	255/55R20	110V	Goodyear	Wrangler	V	0000	6 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFAPXXMJ2PRE41003

DEKRA

CONDITION REPORT

Report No:
2017310688
DATE
12/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ABS	U3003:16-68	BATTERY VOLTAGE	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Engine Compartment: Bottom of engine is fully covered.
Body • Exterior: Signs of spray work done on body panels.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Trevino Julius

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFAPXXMJ2PRE41003

DEKRA

CONDITION REPORT


Report No:
2017310688
DATE
12/10/2026



Shock test




Diagnostics report



Diagnostics report



Diagnostics report



Diagnostics report



FRONT RIGHT CORNER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFAPXXMJ2PRE41003

DEKRA

CONDITION REPORT

Report No:
2017310688
DATE
12/10/2026



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic transmission



90 DEGREE FRONT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFAPXXMJ2PRE41003

DEKRA

CONDITION REPORT

Report No:
2017310688
DATE
12/10/2026




90 DEGREE RIGHT




90 DEGREE REAR




90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFAPXXMJ2PRE41003

DEKRA

CONDITION REPORT

Report No:
2017310688
DATE
12/10/2026



RF TYRE TREAD



Sparewheel



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



ENGINE 2

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFAPXXMJ2PRE41003

DEKRA

CONDITION REPORT

Report No:
2017310688
DATE
12/10/2026



CHASSIS



REAR



Expansion bottle



Oil cap and dipstick



Load Body



Door Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFAPXXMJ2PRE41003

DEKRA

CONDITION REPORT

Report No:
2017310688
DATE
12/10/2026




Water level



Windscreen



Grill



Front Bumper



Rim Front Right



Tyre Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFAPXXMJ2PRE41003