DEKRA

# CONDITION REPORT

**Report No:**
**2017316339**
**DATE**
**23/10/2026**

*MFC Auction House*
*M57 Pretoria Rd, Glenmarais, KEMPTON PARK*
*Gauteng*

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572








## Assignment

| | | | |
|---|---|---|---|
| Client | MFC Auction House | Inspection Location | MFC<br>M57 Pretoria Road - 1619<br>Kempton Park - GT |
| Requested Date | 23/10/2026 | | |
| Inspection Date | 23/10/2026 | | |

## Vehicle Data

| | | | |
|---|---|---|---|
| Vehicle Type | PASSENGER VEHICLE | Registered Owner | |
| Manufacturer | BAIC | Registration Number | LCT034MP |
| Model | X55 1.5T LOCAL PREMIUM DCT [2024-ON] | Register Number | |
| VIN | AFDMCUAK1RA000105 | Date Of First Licensing | |
| Engine Number | | Last COR | |
| Doors | 5 | License Expiry Date | 31/07/2026 |
| Color | GREY | Power / Displacement | |
| Year Model | 2024 | Paint Finish | TWO COAT METALLIC |
| Km Reading | 43,258 KM | Fuel | PETROL |
| Cab / Body Type | SUV | Transmission | AUTOMATIC |

## Vehicle Options & Accessories

**Items**

## VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFDMCUAK1RA000105

DEKRA

# CONDITION REPORT

**Report No:**
**2017316339**
**DATE**
**23/10/2026**





| Damage | Repair Way |
|---|---|
| Front Bumper Damaged | Repair |
| Rear Fender Left Damaged | Repair |
| Rear Fender Right Damaged | Repair |
| Door Front Right Residual Traces of Repair | Repair |
| Door Rear Right Residual Traces of Repair | Repair |
| Rear bumper Damaged | Repair |
| Windscreen Damaged | Replace |

## Brakes

### Brake Test Results

| | Left | Right | | |
|---|---|---|---|---|
| | Braking Force [KN] | Braking Force [KN] | Axle Weight [KG] | Deceleration [m/s$^2$] |
| **Front** | 3.78 | 375.0 | - | |
| **Rear** | 2.61 | 2.79 | - | |
| **Emergency / Parking** | 2.4 | 2.46 | - | |

## Tyres and Rims

### Tyre Specification & Measurement

| | Size | Load/Speed Index | Manufacture | Model | Type* | Production Date | Tread Depth (mm) |
|---|---|---|---|---|---|---|---|
| **Front Left** | 225/55R19 | 99H | Hankook | Radial | V | 3423 | 2 mm |
| **Front Right** | 225/55R19 | 99H | Hankook | Radial | V | 3623 | 2 mm |
| **Rear Left** | 225/55R19 | 99H | Hankook | Radial | V | 3523 | 3 mm |
| **Rear Right** | 225/55R19 | 99H | Hankook | Radial | V | 3423 | 3 mm |
| **Spare** | T135/90R17 | 104M | Wanli | Radial | V | 0000 | 3 mm |

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFDMCUAK1RA000105

DEKRA

# CONDITION REPORT

**Report No:**
**2017316339**
**DATE**
**23/10/2026**

## Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

## Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

## Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Body • Exterior: Minor dents and scratches and stone chips to body panels. Signs of repair work done to body panels. Poor alignment to somebody panels.

## Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

## Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFDMCUAK1RA000105


DEKRA

# CONDITION REPORT

**Report No:**
**2017316339**
**DATE**
**23/10/2026**



Brake test.





Diagnostic.



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)




DASHBOARD (W/ ENGINE RUNNING)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFDMCUAK1RA000105

DEKRA

# CONDITION REPORT

**Report No:**
**2017316339**
**DATE**
**23/10/2026**



ODOMETER


Automatic.



90 DEGREE FRONT


90 DEGREE RIGHT



90 DEGREE REAR


90 DEGREE LEFT


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFDMCUAK1RA000105

DEKRA

# CONDITION REPORT


**Report No:**
**2017316339**
**DATE**
**23/10/2026**



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD




LICENSE DISC




VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFDMCUAK1RA000105

DEKRA

# CONDITION REPORT

**Report No:**
**2017316339**
**DATE**
**23/10/2026**



ENGINE 1



Undercarriage front.



Undercarriage rear.



Oil cap and dipstick.



Water level



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFDMCUAK1RA000105

DEKRA

# CONDITION REPORT

**Report No:**
**2017316339**
**DATE**
**23/10/2026**



Front Bumper




Rear Fender Left



Rear bumper



Rear bumper



Door Rear Right



Door Front Right


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFDMCUAK1RA000105

DEKRA

# CONDITION REPORT

**Report No:**
**2017316339**
**DATE**
**23/10/2026**



Rear Fender Right



Windscreen

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFDMCUAK1RA000105