DEKRA

CONDITION REPORT

Report No:
2017316644
DATE
23/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	23/10/2026		
Inspection Date	23/10/2026		

Vehicle Data

Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	
Manufacturer	TOYOTA	Registration Number	HMF849L
Model	HILUX 2.8 GD-6 RB LEGEND DSL X-CAB PU AT [2024-2025]	Register Number	
		Date Of First Licensing	
VIN	AHTAA3DC701714857	Last COR	
Engine Number		License Expiry Date	
Doors	4	Power / Displacement	
Color	WHITE	Paint Finish	TWO COAT UNI
Year Model	2025	Fuel	DIESEL
Km Reading	53,245 KM	Transmission	AUTOMATIC
Cab / Body Type	SUPER CAB		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTAA3DC701714857

DEKRA

CONDITION REPORT

Report No:
2017316644
DATE
23/10/2026





Damage	Repair Way
Door Front Right Dented	Repair
Fuel Flap Dented	Repair
Windscreen Cracked	Replace
Belly plates Damaged	Repair
Jack Missing	Replace
Wheel Spanner Missing	Replace
Rear left storage cover damaged	Repair
Vehicle license disk missing	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s^2]
Front	4.29	4.5	-	
Rear	2.55	2.68	-	
Emergency / Parking	2.26	1.92	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	265/60 R18	110H	Dunlop	Grandtrek	V	1925	3 mm
Front Right	265/60 R18	110H	Dunlop	Grandtrek	V	1925	3 mm
Rear Left	265/60 R18	110H	Dunlop	Grandtrek	V	1925	5 mm
Rear Right	265/60 R18	110H	Dunlop	Grandtrek	V	1925	5 mm
Spare	265/60 R18	110H	Dunlop	Grandtrek	V	0000	8 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTAA3DC701714857

DEKRA

CONDITION REPORT

Report No:
2017316644
DATE
23/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	COMBINATION METER	B150A	LOST COMMUNICATION WITH HMI-LAN	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.BOTTOM OF ENGINE COVERED.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTAA3DC701714857

DEKRA

CONDITION REPORT

Report No:
2017316644
DATE
23/10/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTAA3DC701714857

DEKRA

CONDITION REPORT

Report No:
2017316644
DATE
23/10/2026



INTERIOR (FRONT DRIVER DOOR)



Automatic Transmission



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



NO LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTAA3DC701714857

DEKRA

CONDITION REPORT

Report No:
2017316644
DATE
23/10/2026



ENGINE



ENGINE 1



Front chassis



Rear chassis



Oil cap and dipstick



LF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTAA3DC701714857


DEKRA

CONDITION REPORT


Report No:
2017316644
DATE
23/10/2026



RF TYRE TREAD




LR TYRE TREAD



RR TYRE TREAD



Spare wheel



Brake and shock absorber repor



Diagnostic report page 1


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTAA3DC701714857

DEKRA

CONDITION REPORT

Report No:
2017316644
DATE
23/10/2026


Combination meter (1 DTC)
DTC Description Status
B1A5A Lost communication with HVAC LAN History
Technician Notes
Customer name:
Technician:
Date:

Diagnostic report page 2



Rear left storage cover



Fuel Flap



Windscreen



Door Front Right



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTAA3DC701714857

DEKRA

CONDITION REPORT

Report No:
2017316644
DATE
23/10/2026



Belly plates

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTAA3DC701714857