DEKRA

CONDITION REPORT

Report No:
2017304579
DATE
30/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	30/09/2026		
Inspection Date	30/09/2026		

Vehicle Data

Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	MFC
Manufacturer	TOYOTA	Registration Number	HHP856L
Model	HILUX 2.8 GD-6 RB LEGEND RS DSL D-CAB PU AT [2023-2024]	Register Number	
		Date Of First Licensing	
VIN	AHTAA3DD501735232	Last COR	
Engine Number		License Expiry Date	30/11/2026
Doors	4	Power / Displacement	
Color	WHITE	Paint Finish	PEARL EFFECT
Year Model	2024	Fuel	DIESEL
Km Reading	37,952 KM	Transmission	AUTOMATIC
Cab / Body Type	DOUBLE CAB		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTAA3DD501735232

DEKRA

CONDITION REPORT

Report No:
2017304579
DATE
30/09/2026





Damage	Repair Way
Front Bumper Paintwork • Scratched	Repair
Door Rear Left Damaged	Repair
Tailgate Damaged	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	5.03	5.84	-	
Rear	3.12	2.89	-	
Emergency / Parking	1.59	1.25	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	265/60R18	110H	Continental	Crosscontact	V	2023	2 mm
Front Right	265/60R18	110H	Continental	Crosscontact	V	2023	2 mm
Rear Left	265/60R18	110H	Continental	Crosscontact	V	2023	3 mm
Rear Right	265/60R18	110H	Continental	Crosscontact	V	2023	3 mm
Spare	265/60R18	110H	Continental	Crosscontact	V	0000	4 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTAA3DD501735232

DEKRA

CONDITION REPORT

Report No:
2017304579
DATE
30/09/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	BRAKE	C137BA2	BRAKE SYSTEM CONTROL MODULE A SYSTEM VOLTAGE SYSTEM VOLTAGE LOW	CONFIRMED

Inspection Conditions

No Test Drive
Rain at time of inspection
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. 20 DTC'S AT TIME OF TESTING SEE DTC REPORT.Body • Exterior: Minor dents and scratches and stone chips to body panels.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTAA3DD501735232


DEKRA

CONDITION REPORT


Report No:
2017304579
DATE
30/09/2026




Brake and shock absorber



Diagnostic report



Diagnostic report



Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTAA3DD501735232

DEKRA

CONDITION REPORT

Report No:
2017304579
DATE
30/09/2026



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic.



90 DEGREE FRONT



90 DEGREE RIGHT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTAA3DD501735232

DEKRA

CONDITION REPORT


Report No:
2017304579
DATE
30/09/2026



90 DEGREE REAR




90 DEGREE LEFT




LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTAA3DD501735232


DEKRA

CONDITION REPORT

Report No:
2017304579
DATE
30/09/2026



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Undercarriage front.



Undercarriage rear.



Oil cap and dipstick.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTAA3DD501735232

DEKRA

CONDITION REPORT

Report No:
2017304579
DATE
30/09/2026



Water level



Front Bumper



Door Rear Left



Tailgate

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTAA3DD501735232