DEKRA

CONDITION REPORT

Report No:
2017310677
DATE
12/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park -
Requested Date	12/10/2026		
Inspection Date	12/10/2026		

Vehicle Data

Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	MFC
Manufacturer	TOYOTA	Registration Number	KV68RYGP
Model	HILUX 2.8 GD-6 RAIDER 4X4 DSL D-CAB PU AT [2021-2023]	Register Number	
		Date Of First Licensing	
VIN	AHTBA3CD206226370	Last COR	
Engine Number		License Expiry Date	28/02/2027
Doors	4	Power / Displacement	
Color	WHITE	Paint Finish	C - COMMON
Year Model	2022	Fuel	DIESEL
Km Reading	165,617 KM	Transmission	AUTOMATIC
Cab / Body Type	DOUBLE CAB		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTBA3CD206226370

DEKRA

CONDITION REPORT

Report No:
2017310677
DATE
12/10/2026





Damage	Repair Way
Front Bumper Paintwork • Scratched	Repair
Bonnet Paintwork • Scratched	Repair
Rear Fender Left Dented	Repair
Rear Fender Right Dented	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Dented	Repair
Door Rear Right Paintwork • Chipmarks	Repair
Rear bumper Dented	Repair
Windscreen Chipped	Repair
Brakes	No brake test done vehicle is 4wd

Brakes

Brake Test Results

No Brake Test on a brake test machine has been performed.

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	-	-	-	
Rear	-	-	-	
Emergency / Parking	-	-	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	265/65R17	112T	Hankook	Dynapro	V	3924	3 mm
Front Right	265/65R17	112T	Hankook	Dynapro	V	3924	3 mm
Rear Left	265/65R17	112T	Hankook	Dynapro	V	3924	4 mm
Rear Right	265/65R17	112T	Hankook	Dynapro	V	3624	4 mm
Spare	265/65R17	112S	Dunlop	Grandtrek	V	0000	4 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTBA3CD206226370

DEKRA

CONDITION REPORT

Report No:
2017310677
DATE
12/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	HISTORY	B150A	LOST COMMUNICATION WITH HMI-LAN	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTBA3CD206226370


DEKRA

CONDITION REPORT


Report No:
2017310677
DATE
12/10/2026



Shock report



Diagnostic report



Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTBA3CD206226370

DEKRA

CONDITION REPORT


Report No:
2017310677
DATE
12/10/2026



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTBA3CD206226370


DEKRA

CONDITION REPORT

Report No:
2017310677
DATE
12/10/2026



90 DEGREE LEFT




LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTBA3CD206226370

DEKRA

CONDITION REPORT

Report No:
2017310677
DATE
12/10/2026



VIN PLATE OR STICKER


Spare tyre


ENGINE 1


ENGINE 2


CHASSIS


Oil cap and dipstick

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTBA3CD206226370

DEKRA

CONDITION REPORT


Report No:
2017310677
DATE
12/10/2026



Coolant bottle



Windscreen



Windscreen



Water level



Bonnet



Rear Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTBA3CD206226370

DEKRA

CONDITION REPORT

Report No:
2017310677
DATE
12/10/2026



Door Rear Right



Door Front Right



Front Bumper



Door Front Left



Rear Fender Left



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTBA3CD206226370