CONDITION REPORT

Report No:
2017315634
DATE
22/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	22/10/2026		
Inspection Date	22/10/2026		

Vehicle Data

Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	TOYOTA	Registration Number	HRN431L
Model	HILUX 2.4 GD S AC DSL PU [2024-ON]	Register Number	
VIN	AHTCB8CB704165221	Date Of First Licensing	
Engine Number		Last COR	
Doors	2	License Expiry Date	30/06/2027
Color	WHITE	Power / Displacement	
Year Model	2026	Paint Finish	TWO COAT UNI
Km Reading	11,418 KM	Fuel	DIESEL
Cab / Body Type	SINGLE CAB	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTCB8CB704165221

DEKRA

CONDITION REPORT

Report No:
2017315634
DATE
22/10/2026





Damage	Repair Way
Engine Oil Leak	Repair
Tailgate Paintwork • Scratched	Repair
Load Body Dented	Repair
Jack Missing	Replace
Wheel Spanner Missing	Replace
Triangle Missing	Replace
Spare wheel missing	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	4.38	4.0	-	
Rear	2.54	2.44	-	
Emergency / Parking	1.78	1.66	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	205/70 R15C	106S	Bridgestone	R623	V	1526	6 mm
Front Right	205/70 R15C	106S	Bridgestone	R623	V	1526	6 mm
Rear Left	205/70 R15C	106S	Bridgestone	R623	V	1526	6 mm
Rear Right	205/70 R15C	106S	Bridgestone	R623	V	1526	6 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTCB8CB704165221

DEKRA

CONDITION REPORT

Report No:
2017315634
DATE
22/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ABS/VSC/TRC	C1425	STOP SWITCH CIRCUIT OPEN	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Body • Exterior: Minor dents and scratches on body panels.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTCB8CB704165221

DEKRA

CONDITION REPORT

Report No:
2017315634
DATE
22/10/2026



INTERIOR (FRONT DRIVER DOOR)



Manual Transmission



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



FRONT RIGHT CORNER



90 DEGREE FRONT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTCB8CB704165221

DEKRA

CONDITION REPORT

Report No:
2017315634
DATE
22/10/2026



90 DEGREE LEFT



REAR LEFT CORNER



90 DEGREE REAR



90 DEGREE RIGHT



Oil cap and dipstick



ENGINE 1

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTCB8CB704165221

DEKRA

CONDITION REPORT


Report No:
2017315634
DATE
22/10/2026




Front Chassis



Rear chassis



RF TYRE TREAD



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTCB8CB704165221


DEKRA

CONDITION REPORT

Report No:
2017315634
DATE
22/10/2026



Diagnostic report



Brake and shock absorber repor



LICENSE DISC



VIN PLATE OR STICKER



Tailgate



Tailgate

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTCB8CB704165221

DEKRA

CONDITION REPORT

Report No:
2017315634
DATE
22/10/2026



Load Body



Water level



Engine

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTCB8CB704165221