DEKRA

CONDITION REPORT

Report No:
2017313061
DATE
16/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	16/10/2026		
Inspection Date	16/10/2026		

Vehicle Data

Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	
Manufacturer	TOYOTA	Registration Number	HMT959L
Model	HILUX 2.0 VVTI S AC PU [2021-2023]	Register Number	
VIN	AHTCW8CB701966057	Date Of First Licensing	
Engine Number		Last COR	
Doors	2	License Expiry Date	31/10/2026
Color	WHITE	Power / Displacement	
Year Model	2022	Paint Finish	C - COMMON
Km Reading	133,268 KM	Fuel	PETROL
Cab / Body Type	SINGLE CAB	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTCW8CB701966057

DEKRA

CONDITION REPORT

Report No:
2017313061
DATE
16/10/2026





Damage	Repair Way
Side Mirror Right Paintwork • Scratched	Repair
Front Bumper Paintwork • Scratched	Repair
Front Fender Left Paintwork • Scratched	Repair
Rear Fender Left Paintwork • Scratched	Repair
Rear Fender Right Dented	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Paintwork • Scratched	Repair
Tailgate Paintwork • Scratched	Repair
Parking Brake Performance Left / Right Difference out of legal range	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	3.8	3.7	-	
Rear	1.9	1.7	-	
Emergency / Parking	2.5	1.4	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	205/70R15	96H	Royal black	Royal mile	V	0924	2 mm
Front Right	205/70R15	96H	Royal black	Royal mile	V	1024	2 mm
Rear Left	205/70R15	96H	Royal black	Royal mile	V	1024	2 mm
Rear Right	205/70R15	96H	Royal black	Royal mile	V	1024	2 mm
Spare	205/70R15	106/104R	Hilo	Brawn xc1	V	0000	4 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTCW8CB701966057

DEKRA

CONDITION REPORT

Report No:
2017313061
DATE
16/10/2026

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTCW8CB701966057

DEKRA

CONDITION REPORT

Report No:
2017313061
DATE
16/10/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTCW8CB701966057

DEKRA

CONDITION REPORT

Report No:
2017313061
DATE
16/10/2026



INTERIOR (FRONT DRIVER DOOR)



Manual



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTCW8CB701966057

DEKRA

CONDITION REPORT


Report No:
2017313061
DATE
16/10/2026



ENGINE 1



ENGINE 2




CHASSIS



Oil cap and dipstick



Coolant bottle



Shock and brake report


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTCW8CB701966057


DEKRA

CONDITION REPORT


Report No:
2017313061
DATE
16/10/2026



Diagnostic report



LF TYRE TREAD



RF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



Spare wheel


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTCW8CB701966057

DEKRA

CONDITION REPORT

Report No:
2017313061
DATE
16/10/2026



Test date: 2026/10/16
Test time: 9:52
Model:
VIN: AHTCW8CB701

Test results

side-slip test

Front axle -1 m/km Rear axle --- m/km

Shock absorber test (MSD3000)

	left	right	Difference	Weight
Front axle	0,26	0,24	8 %	891 kg
Rear axle	> 0,30	> 0,30	0 %	748 kg
Total weight				1639 kg

Brake test

Brake force

	left	right	Difference
Front axle	3,80 kN	3,70 kN	3 %
Parking brake	2,53 kN	1,48 kN	42 %
Rear axle	1,98 kN	1,73 kN	12 %

Final evaluation static
Deceleration service brake 70 %
Deceleration parking brake 25 %
Total weight 1639 kg

Parking Brake Performance



Water level



Side Mirror Right



Rear Fender Right



Door Front Right



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTCW8CB701966057


DEKRA

CONDITION REPORT

Report No:
2017313061
DATE
16/10/2026



Front Bumper



Front Fender Left



Door Front Left



Rear Fender Left



Tailgate

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTCW8CB701966057