DEKRA

CONDITION REPORT

Report No:
2017317655
DATE
27/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	27/10/2026		
Inspection Date	27/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	TOYOTA	Registration Number	KD21GHGP
Model	HILUX 2.8 GD-6 RB RAIDER X-CAB DSL PU AT [2017-2019]	Register Number	
		Date Of First Licensing	
VIN	AHTGA3DC900874013	Last COR	
Engine Number		License Expiry Date	31/07/2026
Doors	4	Power / Displacement	
Color	WHITE	Paint Finish	TWO COAT UNI
Year Model	2018	Fuel	DIESEL
Km Reading	286,077 KM	Transmission	AUTOMATIC
Cab / Body Type	SUPER CAB		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTGA3DC900874013

DEKRA

CONDITION REPORT

Report No: 2017317655
DATE 27/10/2026



Damage	Repair Way
Tail Light Left Damaged	Repair
Brake Light Centre Damaged	Replace
Seat Front Right Damaged	Repair
Interior Mirror Damaged	Repair
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Damaged	Repair
Tailgate Damaged	Repair
Windscreen Damaged	Repair
Parking Brake Performance Left / Right Difference out of legal range	Repair
Silencer Defective	Replace
Catalytic converter Missing	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	5.26	4.66	-	
Rear	3.66	3.82	-	
Emergency / Parking	1.94	0.84	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	265/65R18	116Q	Sailun	Radial	V	4724	2 mm
Front Right	265/65R18	116Q	Silun	Radial	V	4724	2 mm
Rear Left	265/65R18	116Q	Sailun	Radial	V	4724	3 mm
Rear Right	265/65R18	116Q	Sailun	Radial	V	4724	3 mm
Spare	245/70R16	106T	Continental	Worldcontac	V	4112	2 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTGA3DC900874013

DEKRA

CONDITION REPORT

Report No:
2017317655
DATE
27/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ENGINE AND ECT	P1608	ENGINE LACK OF POWER	CURRENT

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Electrical Components and Instruments: signs of aftermarket performance come to vehicle.
Body • Exterior: Minor dents and scratches and stone chips to body panels. Signs of repair work done to body panels. Poor alignment to somebody panels. Repair work done to vehicle below standard.
Tyres and Rims: spare wheel deflated.
Undercarriage: non-standard exhaust exhaust fitted to vehicle.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTGA3DC900874013


DEKRA

CONDITION REPORT


Report No:
2017317655
DATE
27/10/2026



Brake and shock absorber



Diagnostic report




Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTGA3DC900874013

DEKRA

CONDITION REPORT

Report No:
2017317655
DATE
27/10/2026



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



ADDITIONAL 11



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTGA3DC900874013


DEKRA

CONDITION REPORT


Report No:
2017317655
DATE
27/10/2026




90 DEGREE LEFT




LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTGA3DC900874013

DEKRA

CONDITION REPORT


Report No:
2017317655
DATE
27/10/2026



VIN PLATE OR STICKER


ENGINE 1


ADDITIONAL 4


ADDITIONAL 5


ADDITIONAL 10


Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTGA3DC900874013

DEKRA

CONDITION REPORT

Report No:
2017317655
DATE
27/10/2026




Front Bumper



Front Bumper




Bonnet



Front Fender Left



Door Front Left



Door Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTGA3DC900874013

DEKRA

CONDITION REPORT

Report No:
2017317655
DATE
27/10/2026




Rear Fender Left



Tailgate


Rear Fender Right


Front Fender Right



Door Front Right



Door Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTGA3DC900874013

DEKRA

CONDITION REPORT

Report No:
2017317655
DATE
27/10/2026



Windscreen



Seat Front Right



Interior Mirror



Interior Mirror



Tail Light Left



Brake Light Centre


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTGA3DC900874013

DEKRA

CONDITION REPORT

Report No:
2017317655
DATE
27/10/2026



Parking Brake Performance



Catalytic converter



Silencer

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTGA3DC900874013