CONDITION REPORT

Report No:
2017318683
DATE
28/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	28/10/2026		
Inspection Date	28/10/2026		

Vehicle Data

Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	
Manufacturer	TOYOTA	Registration Number	DDT558NC
Model	HILUX 2.4 GD-6 RB RAIDER DSL D-CAB PU AT [2024-2024]	Register Number	
		Date Of First Licensing	
VIN	AHTJB3DD804537904	Last COR	
Engine Number		License Expiry Date	30/09/2026
Doors	4	Power / Displacement	
Color	WHITE	Paint Finish	PEARL EFFECT
Year Model	2024	Fuel	DIESEL
Km Reading	38,772 KM	Transmission	AUTOMATIC
Cab / Body Type	DOUBLE CAB		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTJB3DD804537904

DEKRA

CONDITION REPORT

Report No:
2017318683
DATE
28/10/2026





Damage	Repair Way
Dash Padding Defective	Repair
Front Bumper Paintwork • Chipmarks	Repair
Bonnet Paintwork • Chipmarks	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Door Front Right Paintwork • Scratched	Repair
Tailgate Damaged	Repair
Tyre Front Left Worn	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	4.43	4.47	-	
Rear	4.08	4.25	-	
Emergency / Parking	3.45	2.78	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	265/65R17	112S	Dunlop	Grandtrek	V	1324	0 mm
Front Right	265/65R17	112S	Dunlop	Grandtrek	V	1324	1 mm
Rear Left	265/65R17	112S	Dunlop	Grandtrek	V	1024	1 mm
Rear Right	265/65R17	112S	Dunlop	Grandtrek	V	1224	1 mm
Spare	265/65R17	112S	Dunlop	Grandtrek	V	0000	4 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTJB3DD804537904

DEKRA

CONDITION REPORT

Report No:
2017318683
DATE
28/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	COMBINATION METER	B150A	LOST COMMUNICATION WITH HMI-LAN	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.THERE IS A STICKY SUBSTANCE ON DASH PADDING.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTJB3DD804537904

DEKRA

CONDITION REPORT

Report No:
2017318683
DATE
28/10/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTJB3DD804537904

DEKRA

CONDITION REPORT

Report No:
2017318683
DATE
28/10/2026



INTERIOR (FRONT DRIVER DOOR)



Automatic.



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTJB3DD804537904


DEKRA

CONDITION REPORT

Report No:
2017318683
DATE
28/10/2026



ENGINE 1




Undercarriage front.



Undercarriage rear.



Oil cap and dipstick.



LF TYRE TREAD



LR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTJB3DD804537904


DEKRA

CONDITION REPORT


Report No:
2017318683
DATE
28/10/2026




RR TYRE TREAD



RF TYRE TREAD



Brake test.



Diagnostic.



Water level



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTJB3DD804537904

DEKRA

CONDITION REPORT

Report No:
2017318683
DATE
28/10/2026



Front Bumper



Bonnet



Rear Fender Left



Tailgate



Rear Fender Right



Door Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTJB3DD804537904

DEKRA

CONDITION REPORT

Report No:
2017318683
DATE
28/10/2026



Dash Padding



Tyre Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTJB3DD804537904