CONDITION REPORT

Report No:
2017317030
DATE
26/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	26/10/2026		
Inspection Date	26/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	MAZDA	Registration Number	LW46NYGP
Model	CX-5 2.0L ACTIVE AT [2018-2020]	Register Number	
VIN	JM6KF2W7AK0308421	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	30/06/2025
Color	WHITE	Power / Displacement	
Year Model	2019	Paint Finish	C - COMMON
Km Reading	486,719 KM	Fuel	PETROL
Cab / Body Type	STATION WAGON	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JM6KF2W7AK0308421

DEKRA

CONDITION REPORT

Report No:
2017317030
DATE
26/10/2026





Damage	Repair Way
Windscreen Wiper Worn	Replace
Seat Front Right Worn	Repair
Parcel Tray Damaged	Replace
Front Bumper Paintwork • Scratched	Repair
Bonnet Paintwork • Chipmarks	Repair
Front Fender Left Paintwork • Scratched	Repair
Front Fender Right Dented	Repair
Rear Fender Left Dented	Repair
Front Fender Left / Inner Tray Damaged	Replace
Door Front Left Paintwork • Scratched	Repair
Door Front Right Dented	Repair
Door Rear Left Dented	Repair
Door Rear Right Damaged	Repair
Boot Lid / Hatch door Damaged	Repair
Rear bumper Cracked	Repair
Roof Paintwork • Scratched	Repair
Windscreen Cracked	Replace
Brake disc 1. Axle left Worn	Replace
Brake disc 1. Axle right Worn	Replace
Brake disc 2. Axle left Worn	Replace
Brake disc 2. Axle right Worn	Replace
Brake Pad 1. Axle left Worn	Replace
Brake Pad 1. Axle right Worn	Replace
Brake Pad/Shoe 2. Axle left Worn	Replace
Brake Pad/Shoe 2. Axle right Worn	Replace
Tyre Front Left Smooth	Replace
Tyre Front Right Smooth	Replace
Tyre Rear Left Smooth	Replace
Tyre Rear Right Smooth	Replace
Number plates front and back not fitted	Replace
Exhaust Heat Guard/Shield damged	Repair
Warning light illuminated	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	3.9	3.6	-	
Rear	2.4	2.8	-	
Emergency / Parking	1.8	1.8	-	

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JM6KF2W7AK0308421

DEKRA

CONDITION REPORT

Report No:
2017317030
DATE
26/10/2026

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	225/65R17	102H	MIRAGE	MR-HT102	V	0921	2 mm
Front Right	225/65R17	102V	YOKOHAMA	GEOLANDAR	V	0118	1 mm
Rear Left	225/65R17	102H	GOODYEAR	EFFICIENT GR	V	0000	1 mm
Rear Right	225/65R17	102H	BRIDGESTONE	ECOPIA	V	0000	1 mm
Spare	185/80R17	99M	DUNLOP	TEMPORARY US	V	0000	5 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ABS(ANTI-LOCK BRAKE SYSTEM)	C0023:62-68	STOP LAMP CONTROL	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Boitumelo Kutumela

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JM6KF2W7AK0308421

DEKRA

CONDITION REPORT

Report No:
2017317030
DATE
26/10/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JM6KF2W7AK0308421

DEKRA

CONDITION REPORT

Report No:
2017317030
DATE
26/10/2026




INTERIOR (FRONT DRIVER DOOR)



Automatic



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JM6KF2W7AK0308421

DEKRA

CONDITION REPORT

Report No:
2017317030
DATE
26/10/2026



ENGINE 1



ENGINE 2



CHASSIS



Chasis



Oil cap and dipstick



LF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JM6KF2W7AK0308421

DEKRA

CONDITION REPORT

Report No:
2017317030
DATE
26/10/2026



RF TYRE TREAD




LR TYRE TREAD



RR TYRE TREAD



Sparewheel



Brake test



Diagnostics


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JM6KF2W7AK0308421

DEKRA

CONDITION REPORT


Report No:
2017317030
DATE
26/10/2026



Diagnostics




License plates



Exhaust Heat guard/shield



Warning lights



Windscreen



Windscreen

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JM6KF2W7AK0308421

DEKRA

CONDITION REPORT

Report No:
2017317030
DATE
26/10/2026



Windscreen Wiper




Water level




Tyre Front Left



Tyre Front Right



Tyre Rear Left



Tyre Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JM6KF2W7AK0308421

DEKRA

CONDITION REPORT

Report No:
2017317030
DATE
26/10/2026



Brake disc 1. Axle right



Brake disc 1. Axle left



Brake Pad 1. Axle left



Brake Pad/Shoe 2. Axle right



Brake disc 2. Axle left



Brake disc 2. Axle right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JM6KF2W7AK0308421

DEKRA

CONDITION REPORT

Report No:
2017317030
DATE
26/10/2026



Brake Pad 1. Axle right



Brake Pad/Shoe 2. Axle left



Rear bumper



Rear bumper



Front Fender Left / Inner Tray



Parcel Tray

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JM6KF2W7AK0308421

DEKRA

CONDITION REPORT

Report No:
2017317030
DATE
26/10/2026



Boot Lid / Hatch door



Boot Lid / Hatch door



Boot Lid / Hatch door



Boot Lid / Hatch door



Boot Lid / Hatch door



Rear bumper


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JM6KF2W7AK0308421

DEKRA

CONDITION REPORT

Report No:
2017317030
DATE
26/10/2026



Rear bumper



Roof



Door Rear Right



Door Rear Right



Door Front Right



Door Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JM6KF2W7AK0308421

DEKRA

CONDITION REPORT

Report No:
2017317030
DATE
26/10/2026




Front Fender Right



Front Fender Left




Door Front Left



Door Rear Left



Rear Fender Left



Rear Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JM6KF2W7AK0308421

DEKRA

CONDITION REPORT

Report No:
2017317030
DATE
26/10/2026



Front Bumper



Front Bumper



Front Bumper



Bonnet



Front Bumper



Seat Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JM6KF2W7AK0308421

DEKRA

CONDITION REPORT

Report No:
2017317030
DATE
26/10/2026



Windscreen Wiper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JM6KF2W7AK0308421