DEKRA

CONDITION REPORT

Report No:
2017315999
DATE
22/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	22/10/2026		
Inspection Date	22/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	MAZDA	Registration Number	LG83FPGP
Model	CX-5 2.2L DE AKERA AWD DSL AT [2022-2024]	Register Number	
		Date Of First Licensing	
VIN	JM6KF4W2AP0879999	Last COR	
Engine Number		License Expiry Date	31/12/2026
Doors	5	Power / Displacement	
Color	GREY	Paint Finish	TWO COAT METALLIC
Year Model	2023	Fuel	DIESEL
Km Reading	118,885 KM	Transmission	AUTOMATIC
Cab / Body Type	STATION WAGON		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JM6KF4W2AP0879999

DEKRA

CONDITION REPORT

Report No:
2017315999
DATE
22/10/2026



Damage	Repair Way
Tail Light Right Damaged	Replace
Seat Front Left Damaged	Repair
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Damaged	Repair
Boot Lid / Hatch door Damaged	Repair
Rear bumper Damaged	Repair
Windscreen Damaged	Repair
Tyre Front Left Worn	Replace
Tyre Rear Left Worn	Replace
Oil service warning light illuminated	Repair

Brakes

Brake Test Results

No Brake Test on a brake test machine has been performed.

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	-	-	-	
Rear	-	-	-	
Emergency / Parking	-	-	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	225/55R19	99V	Maxtrek	Radial	V	2024	0 mm
Front Right	225/55R19	99V	Toyo	Radial	V	4519	2 mm
Rear Left	225/55R19	99V	Toyo	Radial	V	4519	0 mm
Rear Right	225/55R19	99W	Vresestein	Radial	V	1518	2 mm
Spare	T155/80R17	100M	Bridgestone	Temporary	V	////	3 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JM6KF4W2AP0879999

DEKRA

CONDITION REPORT

Report No:
2017315999
DATE
22/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	PCM	P2299:00-28	BRIGHT PEDAL POSITION/ ACCELERATOR PEDAL POSITION	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. 6 DTC'S AT TIME OF TESTING SEE DTC REPORT.Interior: passenger side electric seat not working.
Body • Exterior: Minor dents and scratches and stone chips to body panels. Signs of repair work done to body panels. Poor alignment to somebody panels. Vehicle body in poor condition.Repair work done to vehicle below standard.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JM6KF4W2AP0879999

DEKRA

CONDITION REPORT

Report No:
2017315999
DATE
22/10/2026



INTERIOR (FRONT DRIVER DOOR)



FRONT RIGHT CORNER




90 DEGREE FRONT



90 DEGREE LEFT



REAR LEFT CORNER



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JM6KF4W2AP0879999

DEKRA

CONDITION REPORT

Report No:
2017315999
DATE
22/10/2026



90 DEGREE RIGHT



Automatic.



ODOMETER



DASHBOARD (W/ ENGINE RUNNING)



Oil cap and dipstick.



ENGINE 1

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JM6KF4W2AP0879999


DEKRA

CONDITION REPORT

Report No:
2017315999
DATE
22/10/2026




Undercarriage front.




Undercarriage rear.



RF TYRE TREAD



RR TYRE TREAD



LR TYRE TREAD



LF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JM6KF4W2AP0879999


DEKRA

CONDITION REPORT


Report No:
2017315999
DATE
22/10/2026




VIN PLATE OR STICKER



Brake test.



Diagnostic.



Diagnostic.



LICENSE DISC



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JM6KF4W2AP0879999

DEKRA

CONDITION REPORT

Report No:
2017315999
DATE
22/10/2026




Front Bumper




Front Bumper



Bonnet



Front Fender Left



Door Front Left



Door Rear Left


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JM6KF4W2AP0879999

DEKRA

CONDITION REPORT

Report No:
2017315999
DATE
22/10/2026




Rear Fender Left



Rear bumper



Rear bumper



Boot Lid / Hatch door



Rear Fender Right



Front Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JM6KF4W2AP0879999

DEKRA

CONDITION REPORT

Report No:
2017315999
DATE
22/10/2026



Door Front Right



Door Rear Right



Windscreen



Tail Light Right



Seat Front Left



Tyre Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JM6KF4W2AP0879999

DEKRA

CONDITION REPORT

Report No:
2017315999
DATE
22/10/2026



Tyre Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JM6KF4W2AP0879999