DEKRA

CONDITION REPORT

Report No:
2017319447
DATE
29/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	29/10/2026		
Inspection Date	29/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	NISSAN	Registration Number	CBH607L
Model	X-TRAIL 2.0 XE [2009-2012]	Register Number	
VIN	JN1TBAT31Z0710593	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	
Color	SILVER	Power / Displacement	
Year Model	2010	Paint Finish	TWO COAT METALLIC
Km Reading	264,683 KM	Fuel	PETROL
Cab / Body Type	SUV	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JN1TBAT31Z0710593

DEKRA

CONDITION REPORT

Report No:
2017319447
DATE
29/10/2026





Damage	Repair Way
Engine Oil Leak	Repair
Windscreen Wiper Damaged	Replace
Seat Front Right Damaged	Repair
Carpet Rear Missing	Replace
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Damaged	Repair
Boot Lid / Hatch door Damaged	Repair
Boot Lid / Hatch Door Shock Left Defective	Repair
Boot Lid / Hatch Door Shock Right Defective	Repair
Rear bumper Damaged	Repair
Windscreen Damaged	Replace
Stabilizer Mounting Front Left Damaged	Replace
Stabilizer Mounting Front Right Damaged	Replace
Silencer Welded	Repair
Gearbox Oil Leak	Repair
CV Joint(s) Boot(s) Front Left (inner/outer) Damaged	Replace
CV Joint(s) Boot(s) Front Right (inner/outer) Damaged	Replace
Engine Smoke Excessive	Repair
Steering wheel orientation incorrect.	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	3.27	3.3	-	
Rear	2.5	2.81	-	
Emergency / Parking	2.18	1.52	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	245/70R16	111S	Bridgestone	Radial	V	1614	1 mm
Front Right	245/70R16	111S	Bridgestone	Radial	V	1714	1 mm
Rear Left	245/70R16	111S	Bridgestone	Radial	V	1714	1 mm
Rear Right	245/70R16	111S	Bridgestone	Radial	V	1714	1 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JN1TBAT31Z0710593

DEKRA

CONDITION REPORT

Report No:
2017319447
DATE
29/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ENGINE	P1111	INTAKE VALVE TIMING VALVE CIRCUIT	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.SIGNS OF REPAIR WORK DONE TO BODY PANELS. POOR ALIGNMENT TO SOMEBODY PANELS. REPAIR WORK DONE TO VEHICLE BELOW STANDARD. 5 DTC'S AT TIME OF TESTING SEE DTC REPORT.Axle and Suspension: excessive noise from front and rear suspension.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JN1TBAT31Z0710593

DEKRA

CONDITION REPORT

Report No:
2017319447
DATE
29/10/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JN1TBAT31Z0710593

DEKRA

CONDITION REPORT

Report No:
2017319447
DATE
29/10/2026



INTERIOR (FRONT DRIVER DOOR)




Manual.



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



NO LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JN1TBAT31Z0710593


DEKRA

CONDITION REPORT

Report No:
2017319447
DATE
29/10/2026



ENGINE 1



Undercarriage front.



Undercarriage rear.



Oil cap and dipstick.



LF TYRE TREAD



LR TYRE TREAD


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JN1TBAT31Z0710593

DEKRA

CONDITION REPORT


Report No:
2017319447
DATE
29/10/2026




RR TYRE TREAD



RF TYRE TREAD



Brake test.



Diagnostic.



Water level



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JN1TBAT31Z0710593

DEKRA

CONDITION REPORT

Report No:
2017319447
DATE
29/10/2026




Front Bumper




Bonnet



Front Fender Left



Rear Fender Left



Door Front Left



Door Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JN1TBAT31Z0710593

DEKRA

CONDITION REPORT

Report No:
2017319447
DATE
29/10/2026



Rear bumper



Rear bumper



Boot Lid / Hatch door


Door Rear Right


Door Rear Right


Door Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JN1TBAT31Z0710593


DEKRA

CONDITION REPORT

Report No:
2017319447
DATE
29/10/2026



Front Fender Right



Rear Fender Right




Seat Front Right



Windscreen Wiper



Windscreen Wiper



Windscreen

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JN1TBAT31Z0710593

DEKRA

CONDITION REPORT


Report No:
2017319447
DATE
29/10/2026




Silencer



Gearbox



CV Joint(s) Boot(s) Front Left (inner/outer)



CV Joint(s) Boot(s) Front Right (inner/outer)



Engine



Stabilizer Mounting Front Left


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JN1TBAT31Z0710593


DEKRA

CONDITION REPORT

Report No:
2017319447
DATE
29/10/2026



Stabilizer Mounting Front Right



Boot Lid / Hatch Door Shock Left



Boot Lid / Hatch Door Shock Right



Carpet Rear

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JN1TBAT31Z0710593