DEKRA

CONDITION REPORT

Report No:
2017315452
DATE
21/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	21/10/2026		
Inspection Date	21/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	ACCORDING TO THE AGE AND MILEAGE OF
Manufacturer	SUZUKI	Registration Number	KLR925MP
Model	SX4 2.0I 5-DR AWD [2010-2014]	Register Number	
VIN	JSAGYB51S00302282	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/08/2026
Color	GREY	Power / Displacement	
Year Model	2011	Paint Finish	TWO COAT UNI
Km Reading	228,983 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JSAGYB51S00302282

DEKRA

CONDITION REPORT

Report No:
2017315452
DATE
21/10/2026





Damage	Repair Way
Engine Oil Leak	Repair
Fan Belt Damaged	Replace
Radiator Water Leak	Replace
Battery box Corrosion	Repair
Switch Electrical Window Winder rear right Missing	Replace
Windscreen Wiper Damaged	Replace
Fog Light Front Right Damaged	Replace
Headlight Left Defective	Repair
Headlight Right Defective	Repair
Seat Front Left Dirty	Repair
Seat Front Right Damaged	Repair
Seat Rear Damaged	Repair
Door Sealing Rubber Rear Left Damaged	Replace
Door Sealing Rubber Rear Right Damaged	Replace
Steering Wheel Trim Excessive Wear & Tear	Repair
Side Mirror Right Paintwork • Scratched	Repair
Front Bumper Paintwork • Scratched	Repair
Bonnet Damaged	Repair
C • Pillar Left Damaged	Repair
Front Fender Right Residual Traces of Repair	Repair
Rear Fender Right Dented	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Dented	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Residual Traces of Repair	Repair
Weather Strip Door Front Left Damaged	Repair
Boot Lid / Hatch door Dented	Repair
Rear bumper Damaged	Repair
Sill Panel Left Paintwork • Scratched	Repair
Windscreen Chipped	Repair
Steering Rack Boot Right Leak	Replace
Shock Absorber Rear Right Sweat	Replace
Control Arm Bush(es) Front Axle Left Cracked	Replace
Control Arm Bush(es) Front Axle Right Cracked	Replace
Tyre Front Left Worn	Replace
Rim Rear Left Dented	Repair
Chassis Dented	Repair
Belly plates Damaged	Replace
Gearbox Oil Sweat	Repair
Differential Oil Leak	Repair
CV Joint(s) Boot(s) Front Left (inner/outer) Damaged	Replace
Triangle Missing	Replace
Warning lights illuminated on dashboard	Repair
Spare wheel missing	Replace
Driver's arm rest damaged	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JSAGYB51S00302282

DEKRA

CONDITION REPORT

Report No: 2017315452
DATE 21/10/2026

Brakes

Brake Test Results

No Brake Test on a brake test machine has been performed.

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	-	-	-	
Rear	-	-	-	
Emergency / Parking	-	-	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	205/60 R16	98H	Royalblack	Royalmile	V	3624	0 mm
Front Right	205/60 R16	96H	Royalblack	Royalmile	V	3624	1 mm
Rear Left	205/60 R16	96H	Royalblack	Royalmile	V	3624	4 mm
Rear Right	205/60 R16	96H	Royalblack	Royalmile	V	3624	4 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ECM/PCM(ENGINE/POWERTRAIN	P0101	MASS OR VOLUME AIR FLOW A CIRCUIT RANGE/PERFORMANC	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Lights: Front left and right headlight lenses faded.
Interior: Vehicle interior dirty and panels scratched.
Body • Exterior: Poor residual traces of repair on body panels.Body panels misaligned.Stone chips and spray work on body panels.Dents and scratches on body panels.
Axle and Suspension: Excessive noise coming from engine suspension.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge,

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JSAGYB51S00302282

DEKRA

CONDITION REPORT

Report No:
2017315452
DATE
21/10/2026

operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JSAGYB51S00302282

DEKRA

CONDITION REPORT

Report No:
2017315452
DATE
21/10/2026



INTERIOR (FRONT DRIVER DOOR)



Manual Transmission



ODOMETER



DASHBOARD (W/ ENGINE RUNNING)



FRONT RIGHT CORNER



90 DEGREE FRONT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JSAGYB51S00302282

DEKRA

CONDITION REPORT

Report No:
2017315452
DATE
21/10/2026



90 DEGREE LEFT



REAR LEFT CORNER



90 DEGREE REAR



90 DEGREE RIGHT



Oil cap and dipstick



Front chassis

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JSAGYB51S00302282

DEKRA

CONDITION REPORT


Report No:
2017315452
DATE
21/10/2026




Rear chassis




ENGINE 1



Shock absorber report



Diagnostic report page 1



Diagnostic report page 2



Spare wheel Accessories

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JSAGYB51S00302282

DEKRA

CONDITION REPORT


Report No:
2017315452
DATE
21/10/2026




LF TYRE TREAD



LR TYRE TREAD




RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JSAGYB51S00302282

DEKRA

CONDITION REPORT

Report No:
2017315452
DATE
21/10/2026




ADDITIONAL 8



Seat Front Right



Seat Rear



Seat Rear



Door Sealing Rubber Rear Right



Switch Electrical Window Winder rear right


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JSAGYB51S00302282

DEKRA

CONDITION REPORT

Report No:
2017315452
DATE
21/10/2026



Rear Fender Right



Door Rear Right




Door Front Right



Front Fender Right



Side Mirror Right



Bonnet

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JSAGYB51S00302282

DEKRA

CONDITION REPORT


Report No:
2017315452
DATE
21/10/2026



Windscreen Wiper



Door Front Left




Door Front Left



Door Rear Left



Door Rear Left



Weather Strip Door Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JSAGYB51S00302282

DEKRA

CONDITION REPORT

Report No:
2017315452
DATE
21/10/2026



Sill Panel Left



Seat Front Left



Door Sealing Rubber Rear Left



C • Pillar Left



Rear bumper



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JSAGYB51S00302282

DEKRA

CONDITION REPORT

Report No:
2017315452
DATE
21/10/2026



Rear bumper



Boot Lid / Hatch door



Windscreen



Headlight Right



Headlight Left



Engine

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JSAGYB51S00302282

DEKRA

CONDITION REPORT

Report No:
2017315452
DATE
21/10/2026



Control Arm Bush(es) Front Axle Right



Fog Light Front Right



Front Bumper



Front Bumper



Front Bumper



Control Arm Bush(es) Front Axle Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JSAGYB51S00302282

DEKRA

CONDITION REPORT

Report No:
2017315452
DATE
21/10/2026



Engine



Tyre Front Left



CV Joint(s) Boot(s) Front Left (inner/outer)



Gearbox



Belly plates



Fan Belt

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JSAGYB51S00302282

DEKRA

CONDITION REPORT

Report No:
2017315452
DATE
21/10/2026



Steering Rack Boot Right



Chassis



Differential



Rim Rear Left



Shock Absorber Rear Right



Radiator

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JSAGYB51S00302282

DEKRA

CONDITION REPORT

Report No:
2017315452
DATE
21/10/2026



Water level



Water level



Battery box



Steering Wheel Trim

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JSAGYB51S00302282