DEKRA

# CONDITION REPORT

**Report No:**
**2017316659**
**DATE**
**23/10/2026**

*MFC Auction House*
*M57 Pretoria Rd, Glenmarais, KEMPTON PARK*
*Gauteng*

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572








## Assignment

| | | | |
|---|---|---|---|
| Client | MFC Auction House | Inspection Location | MFC<br>M57 Pretoria Road - 1619<br>Kempton Park - GT |
| Requested Date | 23/10/2026 | | |
| Inspection Date | 23/10/2026 | | |

## Vehicle Data

| | | | |
|---|---|---|---|
| Vehicle Type | PASSENGER VEHICLE | Registered Owner | MFC AUCTION HOUSE |
| Manufacturer | TOYOTA | Registration Number | KWB373MP |
| Model | RUMION 1.5 S MPV [2021-2023] | Register Number | |
| VIN | JTDDND22S00395083 | Date Of First Licensing | |
| Engine Number | | Last COR | |
| Doors | 5 | License Expiry Date | 31/05/2026 |
| Color | WHITE | Power / Displacement | |
| Year Model | 2021 | Paint Finish | M - METALLIC |
| Km Reading | 390,362 KM | Fuel | PETROL |
| Cab / Body Type | HATCHBACK | Transmission | MANUAL |

## Vehicle Options & Accessories

**Items**

## VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDDND22S00395083

DEKRA

# CONDITION REPORT

**Report No:**
**2017316659**
**DATE**
**23/10/2026**





| Damage | Repair Way |
|---|---|
| Water level Insufficient | Repair |
| Dim and Bright Indicator Light Malfunction | Repair |
| Tail Light Right Damaged | Repair |
| Dim Light Right Malfunction | Repair |
| Headlight Left Damaged | Replace |
| Headlight Right Chipped | Repair |
| Seat Front Right Damaged | Repair |
| Seat Rear Damaged | Repair |
| Front Bumper Damaged | Repair |
| Bonnet Paintwork • Chipmarks | Repair |
| Front Fender Left Residual Traces of Repair | Repair |
| Front Fender Right Paintwork • Scratched | Repair |
| Rear Fender Left Paintwork • Scratched | Repair |
| Rear Fender Right Residual Traces of Repair | Repair |
| Door Front Left Paintwork • Scratched | Repair |
| Door Front Right Dented | Repair |
| Door Rear Left Dented | Repair |
| Door Rear Right Paintwork • Scratched | Repair |
| Boot Lid / Hatch door Dented | Repair |
| Rear bumper Paintwork • Scratched | Repair |
| Windscreen Cracked | Replace |
| Gearbox Oil Leak | Repair |
| Body exterior | Vehicle got some scratches, stone chips and dents |
| Body exterior | Signs of spray work done on some body panels |
| L/F fender liner missing | Replace |
| R/R tire deferred size | Repair |

## Brakes

### Brake Test Results

| | Left | Right | | |
|---|---|---|---|---|
| | Braking Force [KN] | Braking Force [KN] | Axle Weight [KG] | Deceleration [m/s²] |
| **Front** | 3.1 | 2.9 | - | |
| **Rear** | 2.0 | 2.2 | - | |
| **Emergency / Parking** | 0.9 | 1.1 | - | |

## Tyres and Rims

### Tyre Specification & Measurement

| | Size | Load/Speed Index | Manufacture | Model | Type* | Production Date | Tread Depth (mm) |
|---|---|---|---|---|---|---|---|
| **Front Left** | 185/65R15 | 88H | Hilo | Genesys xp1 | V | 3125 | 3 mm |
| **Front Right** | 185/65R15 | 88H | Hilo | Genesys xp1 | V | 3125 | 3 mm |
| **Rear Left** | 185/65R15 | 88T | Hilo | Genesys xp1 | V | 3923 | 3 mm |
| **Rear Right** | 175/65R15 | 84H | Bridgestone | Ecopia | V | 1119 | 2 mm |
| **Spare** | 185/65R15 | 88T | Point s | Summer | V | //// | 2 mm |

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDDND22S00395083

DEKRA

# CONDITION REPORT

**Report No:**
**2017316659**
**DATE**
**23/10/2026**

## Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

## Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

## Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

## Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

## Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDDND22S00395083

DEKRA

# CONDITION REPORT

**Report No:**
**2017316659**
**DATE**
**23/10/2026**



INTERIOR (FRONT DRIVER DOOR)



FRONT RIGHT CORNER



90 DEGREE FRONT



90 DEGREE LEFT



REAR LEFT CORNER



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDDND22S00395083

DEKRA

# CONDITION REPORT

**Report No:**
**2017316659**
**DATE**
**23/10/2026**



90 DEGREE RIGHT



DASHBOARD (W/ ENGINE RUNNING)




ODOMETER



Manual



ENGINE 1



Coolant bottle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDDND22S00395083

DEKRA

# CONDITION REPORT

**Report No:**
**2017316659**
**DATE**
**23/10/2026**




Diagnostic report



Spare tire no rim



Oil cap and dipstick



Shock and brake report



LF TYRE TREAD



LR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDDND22S00395083


DEKRA

# CONDITION REPORT

**Report No:**
**2017316659**
**DATE**
**23/10/2026**



RR TYRE TREAD



RF TYRE TREAD




LICENSE DISC




VIN PLATE OR STICKER



ENGINE 2



CHASSIS

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDDND22S00395083

DEKRA

# CONDITION REPORT


**Report No:**
**2017316659**
**DATE**
**23/10/2026**



Windscreen



Seat Front Right




Dim and Bright Indicator Light



Dim Light Right



Headlight Left



Headlight Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDDND22S00395083

DEKRA

# CONDITION REPORT

**Report No:**
**2017316659**
**DATE**
**23/10/2026**




Water level



Bonnet




Seat Rear



Rear Fender Right



Door Rear Right



Door Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDDND22S00395083

DEKRA

# CONDITION REPORT

**Report No:**
**2017316659**
**DATE**
**23/10/2026**



Front Fender Right



Front Bumper



Front Bumper



Front Fender Left



Door Front Left



Door Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDDND22S00395083

DEKRA

# CONDITION REPORT

**Report No:**
**2017316659**
**DATE**
**23/10/2026**




Rear Fender Left





Boot Lid / Hatch door



Rear bumper



Rear bumper



Tail Light Right



Gearbox

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDDND22S00395083