DEKRA

CONDITION REPORT

Report No:
2017307564
DATE
05/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park -
Requested Date	05/10/2026		
Inspection Date	05/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	TOYOTA	Registration Number	KD79LJGP
Model	STARLET 1.4 XI 5-DR [2020-2023]	Register Number	
VIN	JTDGWC52S00668411	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/01/2027
Color	WHITE	Power / Displacement	
Year Model	2021	Paint Finish	TWO COAT UNI
Km Reading	206,363 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDGWC52S00668411

DEKRA

CONDITION REPORT

Report No:
2017307564
DATE
05/10/2026





Damage	Repair Way
Engine Wiring Defective	Replace
Caps Missing	Replace
Radiator Water Leak	Replace
Radio/CD/USB Defective	Repair
Center Console / Cubbyhole + Lid Damaged	Replace
Windscreen Washer Damaged	Replace
Tail Light Left Damaged	Replace
Tail Light Right Cracked	Replace
Number Plate Light Left Damaged	Replace
Number Plate Light Right Missing	Replace
Headlight Right Damaged	Replace
Seat Front Left Damaged	Repair
Seat Front Right Damaged	Repair
Seat Rear Damaged	Repair
Interior Mirror Missing	Replace
Sun Visor Right Damaged	Replace
Hood Lining Dirty	Repair
Door Panel Front Left Damaged	Repair
Carpet Front Damaged	Repair
Carpet Rear Damaged	Repair
Gear Lever Dust Boot Damaged	Repair
Steering Wheel Trim Excessive Wear & Tear	Repair
Side Mirror Left Paintwork • Scratched	Repair
Side Mirror Right Paintwork • Scratched	Repair
Front Bumper Damaged	Replace
Grill Damaged	Replace
Bonnet Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Front Fender Left / Inner Tray Damaged	Replace
Front Fender Right / Inner Tray Damaged	Replace
Rear Fender Right / Inner Tray Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Residual Traces of Repair	Repair
Boot Lid / Hatch door Damaged	Replace
Inner Boot Floor Pan and Spare Wheel Well Damaged	Repair
Sill Panel Left Paintwork • Scratched	Repair
Sill Panel Right Damaged	Repair
Windscreen Cracked	Replace
Window Rear Door Left Defective	Repair
Control Arm(s) Front Axle Right Damaged	Replace
Tyre Front Left Damaged	Replace
Rim Rear Right Dented	Repair
Chassis Scratched	Repair
Sub Frame Damaged	Repair
Windscreen washer bottle cap missing	Replace
Radio not working.	Repair
Vehicle interior dirty and panels scratched	Repair
Boot does not open	Repair
Rear left window does not open	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDGWC52S00668411

DEKRA

CONDITION REPORT

Report No: 2017307564
DATE 05/10/2026

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.26	2.69	-	
Rear	1.39	1.52	-	
Emergency / Parking	1.28	1.42	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/65 R15	88T	Barum	Brillantis	V	3014	0 mm
Front Right	185/65 R15	88H	Goodyear	Assurance	V	4422	1 mm
Rear Left	185/65 R15	88H	Annaite	AN668	V	4324	3 mm
Rear Right	185/65 R15	88H	Annaite	AN668	V	4324	4 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ECM/PCM(ENGINE/POWERTRAIN)	P0011	A CAMSHAFT POSITION(CMP) TIMING OVER-ADVANCED OR S	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.POOR RESIDUAL TRACES OF REPAIR ON BODY PANELS / BODY PANELS MISALIGNED / STONE CHIPS AND SPRAY WORK ON BODY PANELS / SIGNS OF IMPACT DAMAGE TO FRONT AND REAR OF VEHICLE.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDGWC52S00668411

DEKRA

CONDITION REPORT

Report No:
2017307564
DATE
05/10/2026

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDGWC52S00668411

DEKRA

CONDITION REPORT

Report No:
2017307564
DATE
05/10/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDGWC52S00668411

DEKRA

CONDITION REPORT

Report No:
2017307564
DATE
05/10/2026



INTERIOR (FRONT DRIVER DOOR)



Manual Transmission




DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDGWC52S00668411

DEKRA

CONDITION REPORT

Report No:
2017307564
DATE
05/10/2026



ENGINE 1



Front chassis



Rear chassis



Oil cap and dipstick



LF TYRE TREAD



RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDGWC52S00668411


DEKRA

CONDITION REPORT


Report No:
2017307564
DATE
05/10/2026




LR TYRE TREAD




RR TYRE TREAD



Brake and shock absorber repor



Diagnostic report page 1



Diagnostic report page 2



Gear Lever Dust Boot

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDGWC52S00668411

DEKRA

CONDITION REPORT

Report No:
2017307564
DATE
05/10/2026



Steering Wheel Trim




Headlight Right



Headlight Right



Engine Wiring



Caps



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDGWC52S00668411

DEKRA

CONDITION REPORT

Report No:
2017307564
DATE
05/10/2026



Center Console / Cubbyhole + Lid



Radio/CD/USB



Carpet Front



Carpet Front



Carpet Rear



Seat Front Right


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDGWC52S00668411

DEKRA

CONDITION REPORT

Report No:
2017307564
DATE
05/10/2026



Seat Rear



Seat Rear



Carpet Rear



Rear Fender Right



Front Fender Right



Side Mirror Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDGWC52S00668411

DEKRA

CONDITION REPORT

Report No:
2017307564
DATE
05/10/2026



Door Front Right



Door Rear Right




Door Rear Left



Rear Fender Left



Door Front Left



Window Rear Door Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDGWC52S00668411

DEKRA

CONDITION REPORT

Report No:
2017307564
DATE
05/10/2026



Seat Rear



Seat Front Left



Seat Front Left



Door Panel Front Left



Side Mirror Left



Front Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDGWC52S00668411

DEKRA

CONDITION REPORT

Report No:
2017307564
DATE
05/10/2026



Windscreen



Bonnet



Boot Lid / Hatch door



Sill Panel Right



Front Fender Right / Inner Tray



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDGWC52S00668411

DEKRA

CONDITION REPORT

Report No:
2017307564
DATE
05/10/2026



Front Bumper



Front Bumper



Grill



Front Fender Left / Inner Tray



Sill Panel Left



Tail Light Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDGWC52S00668411

DEKRA

CONDITION REPORT

Report No:
2017307564
DATE
05/10/2026



Tail Light Right



Number Plate Light Right



Number Plate Light Left



Tyre Front Left



Sub Frame



Sub Frame

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDGWC52S00668411

DEKRA

CONDITION REPORT

Report No:
2017307564
DATE
05/10/2026



Radiator



Windscreen Washer



Control Arm(s) Front Axle Right



Chassis



Chassis



Rim Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDGWC52S00668411

DEKRA

CONDITION REPORT


Report No:
2017307564
DATE
05/10/2026



Rear Fender Right / Inner Tray



Inner Boot Floor Pan and Spare Wheel Well



Interior Mirror



Sun Visor Right



Hood Lining

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDGWC52S00668411