DEKRA

CONDITION REPORT

Report No:
2017317360
DATE
26/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	26/10/2026		
Inspection Date	26/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	TOYOTA	Registration Number	KG73GFHP
Model	STARLET	Register Number	
VIN	JTDGWC52S00767776	Date Of First Licensing	
Engine Number		Last COR	4x2
Doors	5	License Expiry Date	30/06/2026
Color	WHITE	Power / Displacement	
Year Model		Paint Finish	TWO COAT UNI
Km Reading	137,402 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDGWC52S00767776

DEKRA

CONDITION REPORT

Report No:
2017317360
DATE
26/10/2026



Damage	Repair Way
Center Console / Cubbyhole + Lid Damaged	Replace
Switch Electrical Window Winder front left Damaged	Replace
Tail Light Left Damaged	Replace
Tail Light Right Damaged	Repair
Headlight Left Damaged	Repair
Seat Front Right Damaged	Repair
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	
Front Fender Left / Inner Tray Damaged	Replace
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Damaged	Repair
Boot Lid / Hatch door Damaged	Repair
Rear bumper Damaged	Repair
Tyre Front Right Worn	Replace
Spare Tyre Defective	Replace
Radiator Cross Member Damaged	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.27	2.19	-	
Rear	1.29	1.37	-	
Emergency / Parking	0.74	0.76	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	175/65R15	84H	Davanti	Radial	V	2425	2 mm
Front Right	175/65R15	84H	Yokohama	Radial	V	3713	0 mm
Rear Left	175/65R15	81T	MRF	Radial	V	0623	2 mm
Rear Right	175/65R15	84H	Winrun	Radial	V	4924	2 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDGWC52S00767776

DEKRA

CONDITION REPORT

Report No:
2017317360
DATE
26/10/2026

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Electrical Components and Instruments: left front side electric window does not close.
Body • Exterior: Minor dents and scratches and stone chips to body panels. Signs of repair work done to body panels. Poor alignment to somebody panels. Repair work done to vehicle below standard. Signs of impact damage to rear of vehicle.
Tyres and Rims: spare wheel missing.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDGWC52S00767776


DEKRA

CONDITION REPORT


Report No:
2017317360
DATE
26/10/2026



Brake test.



Diagnostic.



Diagnostic.



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDGWC52S00767776

DEKRA

CONDITION REPORT

Report No:
2017317360
DATE
26/10/2026



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual.



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDGWC52S00767776

DEKRA

CONDITION REPORT

Report No:
2017317360
DATE
26/10/2026




90 DEGREE LEFT




LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDGWC52S00767776

DEKRA

CONDITION REPORT

Report No:
2017317360
DATE
26/10/2026




VIN PLATE OR STICKER



ENGINE 1



Undercarriage front.



Undercarriage rear.



Oil cap and dipstick.



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDGWC52S00767776

DEKRA

CONDITION REPORT

Report No:
2017317360
DATE
26/10/2026



Headlight Left



Front Bumper



Front Bumper



Front Fender Left



Bonnet



Rear Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDGWC52S00767776

DEKRA

CONDITION REPORT

Report No:
2017317360
DATE
26/10/2026



Door Front Left



Door Rear Left



Boot Lid / Hatch door



Rear bumper



Rear bumper



Door Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDGWC52S00767776

DEKRA

CONDITION REPORT

Report No:
2017317360
DATE
26/10/2026



Door Front Right



Front Fender Right



Rear Fender Right



Switch Electrical Window Winder front left



Center Console / Cubbyhole + Lid



Center Console / Cubbyhole + Lid

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDGWC52S00767776

DEKRA

CONDITION REPORT

Report No:
2017317360
DATE
26/10/2026



Tail Light Left



Tail Light Right



Spare Tyre



Seat Front Right



Front Fender Left / Inner Tray



Radiator Cross Member

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDGWC52S00767776

DEKRA

CONDITION REPORT

Report No:
2017317360
DATE
26/10/2026



Tyre Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDGWC52S00767776