DEKRA

CONDITION REPORT

Report No:
2017318690
DATE
28/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	28/10/2026		
Inspection Date	28/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	TOYOTA	Registration Number	KXC834MP
Model	STARLET 1.4 XI 5-DR [2020-2023]	Register Number	
VIN	JTDGWC52S00826960	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/07/2026
Color	WHITE	Power / Displacement	
Year Model	2022	Paint Finish	TWO COAT UNI
Km Reading	133,450 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDGWC52S00826960

DEKRA

CONDITION REPORT

Report No:
2017318690
DATE
28/10/2026





Damage	Repair Way
Engine Oil Sweat	Repair
Switch Electrical Window Winder front left Damaged	Replace
Windscreen Wiper Damaged	Replace
Windscreen Washer Damaged	Replace
Fog Light Front Left Damaged	Replace
Headlight Left Damaged	Replace
Headlight Right Damaged	Replace
Seat Rear Dirty	Repair
Dash Padding Defective	Repair
Carpet Front Damaged	Repair
Boot Carpet Damaged	Repair
Front Bumper Damaged	Replace
Grill Damaged	Replace
Bonnet Residual Traces of Repair	Repair
Front Fender Left Residual Traces of Repair	Repair
Front Fender Right Residual Traces of Repair	Repair
Rear Fender Left Damaged	Repair
Front Fender Right / Inner Tray Damaged	Repair
Door Front Right Residual Traces of Repair	Repair
Door Rear Left Dented	Repair
Door Rear Right Dented	Repair
Boot Lid / Hatch door Dented	Repair
Rear bumper Paintwork • Scratched	Repair
Windscreen Chipped	Repair
Tyre Front Left Damaged	Replace
Tyre Front Right Damaged	Replace
Tyre Rear Left Damaged	Replace
Spare Tyre Damaged	Replace
Rim Front Left Dented	Repair
Rim Rear Left Dented	Repair
Main Beam Right Residual Traces of Repair	Repair
Chassis Scratched	Repair
Sub Frame Damaged	Replace
Belly plates Damaged	Replace
Gearbox Oil Sweat	Repair
Fuel Tank Damaged	Repair
Radiator Cradle Damaged	Replace
Signs of vehicle Airbags deployed	Replace.
Airbag warning light illuminated on dashboard	Repair
Front left and right tyres regrooved	Replace
Fuel tank strap damaged	Repair
Rear left and right tyre sizes different	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDGWC52S00826960

DEKRA

CONDITION REPORT

Report No:
2017318690
DATE
28/10/2026

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.31	2.64	-	
Rear	1.39	1.2	-	
Emergency / Parking	1.39	1.31	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/65 R15	88H	Velocity	Rota-R	V	0723	0 mm
Front Right	185/65 R15	88H	Davanti	DX390	V	2828	0 mm
Rear Left	175/65 R15	84H	Royalblack	Royalmile	V	3023	2 mm
Rear Right	T135/70 R15	99M	Jk tyre	Temporary	V	4621	1 mm
Spare	185/65 R15	92T	Dunlop	Sp-Sport	V	2214	2 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ABS/ESP(ANTI-LOCK BRAKING SYSTEM/ELECTRONIC STABIL	C1057	POWER SUPPLY VOLTAGE	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Body • Exterior: Poor residual traces of repair on body panels.Body panels misaligned.Stone chips and spray work on body panels.Dents and scratches on body panels.Signs of impact damage to front of vehicle.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDGWC52S00826960

DEKRA

CONDITION REPORT

Report No:
2017318690
DATE
28/10/2026

strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDGWC52S00826960

DEKRA

CONDITION REPORT

Report No:
2017318690
DATE
28/10/2026



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual Transmission



FRONT RIGHT CORNER



90 DEGREE FRONT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDGWC52S00826960

DEKRA

CONDITION REPORT

Report No:
2017318690
DATE
28/10/2026



90 DEGREE LEFT



REAR LEFT CORNER



90 DEGREE REAR



90 DEGREE RIGHT



Oil cap and dipstick



ENGINE 1

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDGWC52S00826960

DEKRA

CONDITION REPORT


Report No:
2017318690
DATE
28/10/2026




Front chassis




Rear chassis



Brake and shock absorber repor



Diagnostic report page 1



Diagnostic report page 2



Fuel tank strap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDGWC52S00826960

DEKRA

CONDITION REPORT

Report No:
2017318690
DATE
28/10/2026



Spare wheel and Accessories




LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDGWC52S00826960

DEKRA

CONDITION REPORT

Report No:
2017318690
DATE
28/10/2026




VIN PLATE OR STICKER



Dash Padding



Carpet Front



Seat Rear



Door Rear Right



Door Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDGWC52S00826960

DEKRA

CONDITION REPORT


Report No:
2017318690
DATE
28/10/2026



Front Fender Right



Bonnet



Front Fender Left



Rim Front Left



Rim Rear Left



Switch Electrical Window Winder front left


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDGWC52S00826960

DEKRA

CONDITION REPORT

Report No:
2017318690
DATE
28/10/2026



Rear Fender Left



Boot Lid / Hatch door



Rear bumper



Rear bumper



Windscreen Wiper



Door Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDGWC52S00826960

DEKRA

CONDITION REPORT

Report No:
2017318690
DATE
28/10/2026



Windscreen



Headlight Right



Headlight Left



Headlight Left



Headlight Right



Main Beam Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDGWC52S00826960

DEKRA

CONDITION REPORT

Report No:
2017318690
DATE
28/10/2026



Front Fender Right / Inner Tray



Windscreen Washer



Grill



Front Bumper



Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDGWC52S00826960

DEKRA

CONDITION REPORT

Report No:
2017318690
DATE
28/10/2026



Fog Light Front Left



Belly plates



Gearbox



Sub Frame



Sub Frame



Engine


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDGWC52S00826960


DEKRA

CONDITION REPORT

Report No:
2017318690
DATE
28/10/2026



Chassis



Tyre Front Right



Tyre Front Left



Radiator Cradle



Radiator Cradle



Main Beam Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDGWC52S00826960

DEKRA

CONDITION REPORT

Report No:
2017318690
DATE
28/10/2026



Fuel Tank



Tyre Rear Left



Chassis



Spare Tyre



Boot Carpet



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDGWC52S00826960

DEKRA

CONDITION REPORT

Report No:
2017318690
DATE
28/10/2026



Water level



Switch Electrical Window Winder front left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDGWC52S00826960