DEKRA

CONDITION REPORT

Report No:
2017316400
DATE
23/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	23/10/2026		
Inspection Date	23/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	TOYOTA	Registration Number	LJG836NW
Model	STARLET 1.5 XI 5-DR [2022-2025]	Register Number	
VIN	JTDJWCA3S00601412	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	30/11/2026
Color	WHITE	Power / Displacement	
Year Model	2024	Paint Finish	M - METALLIC
Km Reading	63,016 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDJWCA3S00601412

DEKRA

CONDITION REPORT

Report No:
2017316400
DATE
23/10/2026





Damage	Repair Way
Side Mirror Right Paintwork • Scratched	Repair
Front Bumper Paintwork • Chipmarks	Repair
Front Fender Left Dented	Repair
Rear Fender Left Dented	Repair
Rear Fender Right Paintwork • Scratched	Repair
Rear bumper Paintwork • Scratched	Repair
Windscreen Cracked	Replace
Body exterior	Vehicle got minor scratches, stone chips and dents
L/F fender liner damage	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.4	2.2	-	
Rear	1.5	1.8	-	
Emergency / Parking	1	1.1	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/65R15	88H	Annaite	An600	V	0125	3 mm
Front Right	185/65R15	88H	Annaite	An600	V	0825	3 mm
Rear Left	185/65R15	88H	Annaite	An600	V	0125	3 mm
Rear Right	185/65R15	88H	Annaite	An600	V	0125	3 mm
Spare	T135/70R5	99M	Jk tyre	Temporary	V	////	4 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDJWCA3S00601412

DEKRA

CONDITION REPORT

Report No:
2017316400
DATE
23/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	HISTORY	B1150-17	POWER SOURCE VOLTAGE TOO HIGH	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDJWCA3S00601412

DEKRA

CONDITION REPORT

Report No:
2017316400
DATE
23/10/2026



INTERIOR (FRONT DRIVER DOOR)




FRONT RIGHT CORNER



90 DEGREE FRONT



90 DEGREE LEFT



REAR LEFT CORNER



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDJWCA3S00601412

DEKRA

CONDITION REPORT

Report No:
2017316400
DATE
23/10/2026



90 DEGREE RIGHT



ODOMETER




DASHBOARD (W/ ENGINE RUNNING)



Oil cap and dipstick



Coolant bottle



Shock and brake report


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDJWCA3S00601412


DEKRA

CONDITION REPORT

Report No:
2017316400
DATE
23/10/2026




Diagnostic report



Diagnostic report



Spare wheel



Manual



LF TYRE TREAD



LR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDJWCA3S00601412


DEKRA

CONDITION REPORT

Report No:
2017316400
DATE
23/10/2026



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



ENGINE 2

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDJWCA3S00601412

DEKRA

CONDITION REPORT

Report No:
2017316400
DATE
23/10/2026



CHASSIS



Windscreen



Water level



Rear Fender Right



Side Mirror Right



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDJWCA3S00601412


DEKRA

CONDITION REPORT

Report No:
2017316400
DATE
23/10/2026



Front Bumper



Front Fender Left



Rear Fender Left



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDJWCA3S00601412