DEKRA

CONDITION REPORT

Report No:
2017315194
DATE
21/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	21/10/2026		
Inspection Date	21/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	TOYOTA	Registration Number	LX50DRGP
Model	URBAN CRUISER 1.5 XS [2021-2023]	Register Number	
VIN	JTDPYGJ1S00979739	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/05/2027
Color	WHITE	Power / Displacement	
Year Model	2022	Paint Finish	M - METALLIC
Km Reading	95,755 KM	Fuel	PETROL
Cab / Body Type	STATION WAGON	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDPYGJ1S00979739

DEKRA

CONDITION REPORT

Report No:
2017315194
DATE
21/10/2026



Damage	Repair Way
Side Mirror Left Paintwork • Scratched	Repair
Side Mirror Right Cracked	Repair
Front Bumper Paintwork • Scratched	Repair
Front Fender Left Paintwork • Scratched	Repair
Front Fender Right Paintwork • Scratched	Repair
Rear Fender Left Paintwork • Overspray	Repair
Rear Fender Right Paintwork • Chipmarks	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Paintwork • Overspray	Repair
Rear bumper Paintwork • Scratched	Repair
Windscreen Cracked	Replace
Body exterior	Vehicle got minor scratches, stone chips and dents
Tow hook plug damage	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	0.8	0.9	-	
Rear	1.6	1.6	-	
Emergency / Parking	1.2	1.2	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	215/60R16	95H	Boto	Genesys 228	V	1423	3 mm
Front Right	215/60R16	95H	Boto	Genesys 228	V	1423	3 mm
Rear Left	215/60R16	95H	Apollo	Alnac	V	2522	3 mm
Rear Right	215/60R16	95H	Apollo	Alnac	V	2522	3 mm
Spare	215/60R16	95V	Sailun	Atrezzo	V	////	4 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDPYGJ1S00979739

DEKRA

CONDITION REPORT

Report No:
2017315194
DATE
21/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	HISTORY	B1004-18	POWER SOURCE VOLTAGE TOO LOW	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDPYGJ1S00979739

DEKRA

CONDITION REPORT

Report No:
2017315194
DATE
21/10/2026



INTERIOR (FRONT DRIVER DOOR)



90 DEGREE RIGHT



FRONT RIGHT CORNER



90 DEGREE FRONT



90 DEGREE LEFT



REAR LEFT CORNER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDPYGJ1S00979739

DEKRA

CONDITION REPORT

Report No:
2017315194
DATE
21/10/2026



Oil cap and dipstick



90 DEGREE REAR



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual



Coolant bottle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDPYGJ1S00979739

DEKRA

CONDITION REPORT

Report No:
2017315194
DATE
21/10/2026



ENGINE 1




ENGINE 2




CHASSIS



Spare wheel



RR TYRE TREAD



LF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDPYGJ1S00979739


DEKRA

CONDITION REPORT

Report No:
2017315194
DATE
21/10/2026




LR TYRE TREAD




RF TYRE TREAD




Tow hook plug damage



Shock and brake report



Diagnostic report



Diagnostic report

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDPYGJ1S00979739

DEKRA

CONDITION REPORT


Report No:
2017315194
DATE
21/10/2026



LICENSE DISC



VIN PLATE OR STICKER


Windscreen


Water level


Side Mirror Right


Front Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDPYGJ1S00979739

DEKRA

CONDITION REPORT

Report No:
2017315194
DATE
21/10/2026



Front Bumper




Front Bumper




Front Fender Left



Side Mirror Left



Door Front Left



Door Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDPYGJ1S00979739

DEKRA

CONDITION REPORT

Report No:
2017315194
DATE
21/10/2026



Rear Fender Left




Rear bumper



Rear bumper



Rear bumper



Rear Fender Right



Door Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDPYGJ1S00979739

DEKRA

CONDITION REPORT

Report No:
2017315194
DATE
21/10/2026



Door Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDPYGJ1S00979739