DEKRA

CONDITION REPORT

Report No:
2017310511
DATE
12/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park -
Requested Date	12/10/2026		
Inspection Date	12/10/2026		

Vehicle Data

Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	MFC
Manufacturer	HYUNDAI	Registration Number	LR48XCGP
Model	H-100 BAKKIE 2.6 DECK DSL PU [2011-2020]	Register Number	
VIN	KMFZBX7BLKU617550	Date Of First Licensing	
Engine Number		Last COR	
Doors	2	License Expiry Date	
Color	WHITE	Power / Displacement	
Year Model	2019	Paint Finish	TWO COAT UNI
Km Reading	162,904 KM	Fuel	DIESEL
Cab / Body Type	SINGLE CAB	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMFZBX7BLKU617550

DEKRA

CONDITION REPORT

Report No:
2017310511
DATE
12/10/2026



Damage	Repair Way
Engine Oil Leak	Repair
Seat Front Left Damaged	Repair
Seat Front Right Damaged	Repair
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
B • Pillar Right Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Load Body Damaged	Repair
Tyre Front Left Worn	Replace
Tyre Rear Left Worn	Replace
Tyre Rear Right Worn	Replace
Front tyres size differs	Replace
Rear tyres size differs	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	3.7	3.48	-	
Rear	0.53	2.33	-	
Emergency / Parking	1.54	2.33	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195/70R15C	102S	Dunlop	Sp	V	2621	0 mm
Front Right	195/80R15	106S	Michelin	Radial	V	3021	1 mm
Rear Left	195R15C	104S	Sailun	Radial	V	3324	0 mm
Rear Right	215/75R15	100S	Ceat	Radial	V	1718	0 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMFZBX7BLKU617550

DEKRA

CONDITION REPORT

Report No:
2017310511
DATE
12/10/2026

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.SIGNS OF REPAIR WORK DONE TO BODY PANELS. POOR ALIGNMENT TO SOMEBODY PANELS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMFZBX7BLKU617550

DEKRA

CONDITION REPORT

Report No:
2017310511
DATE
12/10/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMFZBX7BLKU617550

DEKRA

CONDITION REPORT

Report No:
2017310511
DATE
12/10/2026



INTERIOR (FRONT DRIVER DOOR)



Manual.



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



NO LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMFZBX7BLKU617550

DEKRA

CONDITION REPORT

Report No:
2017310511
DATE
12/10/2026



ENGINE 1



Undercarriage front.




Undercarriage rear.



Oil cap and dipstick.



LF TYRE TREAD



RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMFZBX7BLKU617550

DEKRA

CONDITION REPORT


Report No:
2017310511
DATE
12/10/2026




LR TYRE TREAD



RR TYRE TREAD



Brake test.



Diagnostic.



Seat Front Left



Seat Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMFZBX7BLKU617550

DEKRA

CONDITION REPORT

Report No:
2017310511
DATE
12/10/2026



Water level



Front Bumper



Front Bumper



Bonnet



Door Front Left



Load Body

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMFZBX7BLKU617550

DEKRA

CONDITION REPORT

Report No:
2017310511
DATE
12/10/2026



Load Body




Door Front Right




B • Pillar Right



Tyre Rear Left



Tyre Rear Right



Tyre Front Left


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMFZBX7BLKU617550

DEKRA

CONDITION REPORT

Report No:
2017310511
DATE
12/10/2026



Engine

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMFZBX7BLKU617550