DEKRA

CONDITION REPORT

Report No:
2017317139
DATE
26/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	26/10/2026		
Inspection Date	26/10/2026		

Vehicle Data

Vehicle Type	HEAVY LOAD VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	HYUNDAI	Registration Number	MM38FXGP
Model	H-100 BAKKIE 2.6 DECK AC DSL PU [2012-2020]	Register Number	
		Date Of First Licensing	
VIN	KMFZBX7BLKU689391	Last COR	
Engine Number		License Expiry Date	30/11/2026
Doors	2	Power / Displacement	
Color	WHITE	Paint Finish	C - COMMON
Year Model	2019	Fuel	PETROL
Km Reading	175,632 KM	Transmission	MANUAL
Cab / Body Type	OTHERS		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMFZBX7BLKU689391

DEKRA

CONDITION REPORT

Report No:
2017317139
DATE
26/10/2026



Damage	Repair Way
Engine Oil Leak	Repair
12V Socket Defective	Repair
Center Console / Cubbyhole + Lid Defective	Repair
Windscreen Wiper Worn	Replace
Dim Light Left Defective	Repair
Interior Mirror Missing	Replace
Window Winder front right Defective	Replace
Side Mirror Right Cracked	Replace
Front Bumper Damaged	Repair
Grill Damaged	Repair
Bonnet Dented	Repair
B • Pillar Left Dented	Repair
Door Front Left Dented	Repair
Load Body Dented	Repair
Windscreen Cracked	Replace
Spare Tyre Worn	Replace
Belly plates Damaged	Replace
Prop Shaft Oil Sweat	Repair
Front Bumper Stiffener Damaged	Replace
Oil cooler Damaged	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	4.5	5.5	-	
Rear	1.3	2.5	-	
Emergency / Parking	1.6	2.7	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195/70R15C	104/102 S8 P	DUNLOP	SP ENDURA	V	0523	4 mm
Front Right	195/70R15C	104/102 S8 P	DUNLOP	SP ENDURE	V	0523	4 mm
Rear Left	195/70R15C	104/102 S8 P	DUNLOP	SPENDURA	V	2924	4 mm
Rear Right	195/70R15C	104/102 S8 P	DUNLOP	SP ENDURA	V	3624	5 mm
Spare	195/65R15	91H	KINERGY	temporary	V	0000	0 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMFZBX7BLKU689391

DEKRA

CONDITION REPORT

Report No:
2017317139
DATE
26/10/2026

Diagnostic

A vehicle diagnostic has not been conducted.

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Boitumelo Kutumela

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMFZBX7BLKU689391

DEKRA

CONDITION REPORT

Report No:
2017317139
DATE
26/10/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMFZBX7BLKU689391


DEKRA

CONDITION REPORT

Report No:
2017317139
DATE
26/10/2026



INTERIOR (FRONT DRIVER DOOR)



Manual



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMFZBX7BLKU689391

DEKRA

CONDITION REPORT

Report No:
2017317139
DATE
26/10/2026



ENGINE 1



ENGINE 2




CHASSIS



Chasis



Oil cap and dipstick



LF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMFZBX7BLKU689391

DEKRA

CONDITION REPORT


Report No:
2017317139
DATE
26/10/2026



LR TYRE TREAD




RR TYRE TREAD



RF TYRE TREAD



Sparewheel



Brake test



Stiffener

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMFZBX7BLKU689391


DEKRA

CONDITION REPORT

Report No:
2017317139
DATE
26/10/2026



Stiffener




Dim Light Left



Windscreen



Windscreen



Windscreen Wiper



Bonnet

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMFZBX7BLKU689391

DEKRA

CONDITION REPORT

Report No:
2017317139
DATE
26/10/2026



Bonnet



Front Bumper



Front Bumper



Front Bumper



Grill



Door Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMFZBX7BLKU689391

DEKRA

CONDITION REPORT

Report No:
2017317139
DATE
26/10/2026



Side Mirror Right



Load Body



Load Body



B • Pillar Left



B • Pillar Left



B • Pillar Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMFZBX7BLKU689391

DEKRA

CONDITION REPORT

Report No:
2017317139
DATE
26/10/2026



Water level



Interior Mirror



Center Console / Cubbyhole + Lid



Center Console / Cubbyhole + Lid



Spare Tyre



Belly plates

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMFZBX7BLKU689391

DEKRA

CONDITION REPORT

Report No:
2017317139
DATE
26/10/2026



Belly plates



Engine



Engine



Prop Shaft



Window Winder front right



12V Socket

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMFZBX7BLKU689391