DEKRA

CONDITION REPORT

Report No:
2017314576
DATE
21/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572








Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	21/10/2026		
Inspection Date	21/10/2026		

Vehicle Data

Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	
Manufacturer	HYUNDAI	Registration Number	LP39TCGP
Model	H-100 BAKKIE 2.6 EURO II DECK DSL PU [2020-ON]	Register Number	
		Date Of First Licensing	
VIN	KMFZBX7BLRU077853	Last COR	
Engine Number		License Expiry Date	30/04/2027
Doors	2	Power / Displacement	
Color	WHITE	Paint Finish	C - COMMON
Year Model	2024	Fuel	DIESEL
Km Reading	72,203 KM	Transmission	MANUAL
Cab / Body Type	SINGLE CAB		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA

CONDITION REPORT

Report No:
2017314576
DATE
21/10/2026





Damage	Repair Way
Seat Front Right Torn / Cut	Repair
Front Bumper Damaged	Repair
Bonnet Dented	Repair
B • Pillar Left Paintwork • Scratched	Repair
B • Pillar Right Dented	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Paintwork • Scratched	Repair
Tailgate Paintwork • Scratched	Repair
Load Body Paintwork • Scratched	Repair
Windscreen Cracked	Replace
Parking Brake Performance Left / Right Difference out of legal range	Repair
Bolt(s) / Nut(s) Rear Wheel Left Missing	Replace
Body exterior	Vehicle got minor scratches, stone chips and dents
Front and rear tires deferred name brand	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	3.8	3.9	-	
Rear	0.8	0.9	-	
Emergency / Parking	1.1	2.2	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195/70R15	104/102R	Timax	Ecomax61	V	1626	4 mm
Front Right	195/70R15	104/102R	Timax	Ecomax61	V	1626	4 mm
Rear Left	195/70R15	104/102S	Nexen	Cp321	V	2623	3 mm
Rear Right	195/70R15	104/102S	Nexen	Cp321	V	2623	3 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMFZBX7BLRU077853

DEKRA

CONDITION REPORT

Report No:
2017314576
DATE
21/10/2026

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMFZBX7BLRU077853

DEKRA

CONDITION REPORT

Report No:
2017314576
DATE
21/10/2026



INTERIOR (FRONT DRIVER DOOR)



FRONT RIGHT CORNER



90 DEGREE FRONT



90 DEGREE LEFT



REAR LEFT CORNER



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMFZBX7BLRU077853

DEKRA

CONDITION REPORT

Report No:
2017314576
DATE
21/10/2026



90 DEGREE RIGHT



Manual



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Oil cap and dipstick



Coolant bottle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMFZBX7BLRU077853

DEKRA

CONDITION REPORT

Report No:
2017314576
DATE
21/10/2026



ENGINE 1



ENGINE 2




CHASSIS



No spare wheel



RF TYRE TREAD



RR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMFZBX7BLRU077853


DEKRA

CONDITION REPORT


Report No:
2017314576
DATE
21/10/2026



LF TYRE TREAD



LR TYRE TREAD




Diagnostic report



LICENSE DISC



VIN PLATE OR STICKER



Shock and brake report


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMFZBX7BLRU077853

DEKRA

CONDITION REPORT

Report No:
2017314576
DATE
21/10/2026


Test date: 2026/10/20
Test time: 13:04
Test results
side-slip test
Front axle -2 m/km Rear axle -1 m/km
Shock absorber test (MSD3000)

	left	right	Difference	Weight
Front axle	0,16	0,13	6 %	989 kg
Rear axle	0,28	0,20	29 %	559 kg
Total weight				1548 kg

Brake test

	left	right	Difference
Front axle	3,82 kN	3,95 kN	3 %
Parking brake	1,13 kN	2,26 kN	50 %
Rear axle	0,81 kN	0,91 kN	11 %
Final evaluation static			
Deceleration service brake		63 %	
Deceleration parking brake		22 %	Total weight 1548 kg

Parking Brake Performance


Seat Front Right


Water level


Windscreen


Front Bumper


Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMFZBX7BLRU077853

DEKRA

CONDITION REPORT

Report No:
2017314576
DATE
21/10/2026



Bonnet



B • Pillar Right



Door Front Right



Door Front Left



B • Pillar Left



Load Body

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMFZBX7BLRU077853

DEKRA

CONDITION REPORT

Report No:
2017314576
DATE
21/10/2026



Load Body



Tailgate



Bolt(s) / Nut(s) Rear Wheel Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMFZBX7BLRU077853