CONDITION REPORT

Report No:
2017315212
DATE
21/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	21/10/2026		
Inspection Date	21/10/2026		

Vehicle Data

Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	HYUNDAI	Registration Number	LW72WMGP
Model	H-100	Register Number	
VIN	KMFZBX7BLRU105499	Date Of First Licensing	
Engine Number		Last COR	
Doors	2	License Expiry Date	31/08/2027
Color	WHITE	Power / Displacement	
Year Model		Paint Finish	TWO COAT UNI
Km Reading	44,694 KM	Fuel	DIESEL
Cab / Body Type	SINGLE CAB	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMFZBX7BLRU105499

DEKRA

CONDITION REPORT

Report No:
2017315212
DATE
21/10/2026





Damage	Repair Way
Engine Oil Leak	Repair
Engine Wiring Defective	Repair
Clutch Pedal Rubber Missing	Replace
Front Bumper Paintwork • Scratched	Repair
Roof Dented	Repair
Load Body Paintwork • Scratched	Repair
Gearbox Oil Leak	Repair
Wheel Spanner Missing	Replace
Deceleration service brake defective	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	3.52	3.63	-	
Rear	0.56	0.72	-	
Emergency / Parking	1.71	1.87	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195/70 R15C	104S	Nexen	CP321	V	4123	1 mm
Front Right	195/70 R15C	104S	Nexen	CP321	V	4123	1 mm
Rear Left	195/70 R15C	104S	Nexen	CP321	V	4123	3 mm
Rear Right	195/70 R15C	104S	Nexen	CP321	V	4023	3 mm
Spare	195/70 R15C	104S	Nexen	CP321	V	4023	5 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMFZBX7BLRU105499

DEKRA

CONDITION REPORT

Report No:
2017315212
DATE
21/10/2026

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Body • Exterior: Minor dents and scratches on body panels

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMFZBX7BLRU105499

DEKRA

CONDITION REPORT

Report No:
2017315212
DATE
21/10/2026



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual Transmission



INTERIOR (FRONT DRIVER DOOR)



FRONT RIGHT CORNER



90 DEGREE FRONT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMFZBX7BLRU105499

DEKRA

CONDITION REPORT

Report No:
2017315212
DATE
21/10/2026



90 DEGREE LEFT



REAR LEFT CORNER



90 DEGREE REAR



90 DEGREE RIGHT



Front chassis



Rear chassis

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMFZBX7BLRU105499

DEKRA

CONDITION REPORT

Report No:
2017315212
DATE
21/10/2026



Spare wheel



LF TYRE TREAD



RF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



ENGINE 1

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMFZBX7BLRU105499

DEKRA

CONDITION REPORT


Report No:
2017315212
DATE
21/10/2026




Spare wheel Accessories



Oil cap and dipstick



Brake and shock absorber repor



Diagnostic report



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMFZBX7BLRU105499

DEKRA

CONDITION REPORT

Report No:
2017315212
DATE
21/10/2026



Load Body



Load Body




Engine Wiring



Front Bumper



Front Bumper



Roof

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMFZBX7BLRU105499

DEKRA

CONDITION REPORT

Report No:
2017315212
DATE
21/10/2026



Clutch Pedal Rubber



Water level



Gearbox



Engine



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMFZBX7BLRU105499