DEKRA

CONDITION REPORT

Report No:
2017317768
DATE
27/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	27/10/2026		
Inspection Date	27/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	KIA	Registration Number	HV35FGGP
Model	PICANTO	Register Number	
VIN	KNAB2511LKT373931	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	
Color	RED	Power / Displacement	
Year Model		Paint Finish	C - COMMON
Km Reading	120,332 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511LKT373931

DEKRA

CONDITION REPORT

Report No:
2017317768
DATE
27/10/2026





Damage	Repair Way
Center Console / Cubbyhole + Lid Damaged	Repair
Windscreen Wiper Damaged	Replace
Air Conditioner Defective	Repair
Park Light Rear Right Damaged	Replace
Tail Light Right Damaged	Replace
Headlight Left Damaged	Replace
Headlight Right Defective	Repair
Seat Front Left Torn / Cut	Repair
Seat Front Right Excessive Wear & Tear	Repair
Seat Belt Front Right Defective	Repair
Door Sealing Rubber Front Right Worn	Replace
Door Sealing Rubber Rear Right Torn / Cut	Replace
Parcel Tray Damaged	Replace
Channel / Roof Gutter Left Paintwork • Flaking	Repair
Channel / Roof Gutter Right Paintwork • Flaking	Repair
Side Mirror Left Damaged	Replace
Front Bumper Damaged	Repair
Bonnet Discoloured	Repair
A • Pillar Left Dented	Repair
A • Pillar Right Dented	Repair
Front Fender Left Poor Alignment	Repair
Front Fender Right Paintwork • Scratched	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Poor Alignment	Repair
Door Rear Left Dented	Repair
Door Rear Right Paintwork • Scratched	Repair
Boot Lid / Hatch door Damaged	Repair
Rear bumper Damaged	Repair
Rear Bumper / Mounting points Damaged	Replace
Sill Panel Left Damaged	Repair
Sill Panel Right Damaged	Repair
Windscreen Cracked	Replace
Parking Brake Performance Insufficient	Repair
Tyre Rear Left Worn	Replace
Spare Tyre Torn / Cut	Replace
Rim Rear Left Dented	Repair
Silencer Damaged	Replace
Belly plates Damaged	Replace
Radiator Cradle Damaged	Replace
BODY EXTERIOR	excessive dents scratches stone chips on body
LICENSE DISC	Not available
Rear Bumper stiffener	damaged
BODY EXTERIOR	Signs of impact damage to rear of vehicle
Boot light and safety belt	illuminated

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511LKT373931

DEKRA

CONDITION REPORT

Report No:
2017317768
DATE
27/10/2026

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.4	2.3	-	
Rear	1.1	1.2	-	
Emergency / Parking	0.8	0	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	155/80R13	79T	ADAMAS H/P	POWERTRAC	V	2224	3 mm
Front Right	155/80R13	79T	ADAMAS H/P	POWERTRAC	V	2224	3 mm
Rear Left	T115/70D15	90M	Maxis	temporary	V	2818	1 mm
Rear Right	155/80R13	79T	ANNAITE	AN600	V	1725	4 mm
Spare	155/80R13	79T	SUMITOMO	HTR T5	V	0916	1 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Inspection Conditions

No Test Drive
Vehicle Dirty
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE: NORMAL WEAR AND TEAR MARKS ON THE BODY, INTERIOR, AND MECHANICAL.Undercarriage: Heat shield/Guard bent

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Boitumelo Kutumela

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511LKT373931

DEKRA

CONDITION REPORT


Report No:
2017317768
DATE
27/10/2026



Sparewheel



Oil cap and dipstick



BRAKE REPORT



DIAGNOSTICS



Boot inner plastic panel



Rear Bumper Stiffener

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511LKT373931

DEKRA

CONDITION REPORT

Report No:
2017317768
DATE
27/10/2026



Heat guard/Shield



Manual



CHASIS



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511LKT373931

DEKRA

CONDITION REPORT

Report No:
2017317768
DATE
27/10/2026



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511LKT373931

DEKRA

CONDITION REPORT

Report No:
2017317768
DATE
27/10/2026




LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511LKT373931

DEKRA

CONDITION REPORT

Report No:
2017317768
DATE
27/10/2026



ENGINE 1



ENGINE 2



Spare Tyre



Parcel Tray



Parcel Tray



Boot Lid / Hatch door

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511LKT373931

DEKRA

CONDITION REPORT

Report No:
2017317768
DATE
27/10/2026



Boot Lid / Hatch door



Boot Lid / Hatch door



Boot Lid / Hatch door



Park Light Rear Right



Park Light Rear Right



Tail Light Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511LKT373931

DEKRA

CONDITION REPORT

Report No:
2017317768
DATE
27/10/2026




Rear bumper




Rear bumper


Rear bumper


Windscreen


Windscreen


Headlight Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511LKT373931


DEKRA

CONDITION REPORT

Report No:
2017317768
DATE
27/10/2026



Headlight Left




Headlight Right



Front Bumper



Front Bumper



Front Bumper



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511LKT373931

DEKRA

CONDITION REPORT

Report No:
2017317768
DATE
27/10/2026



Bonnet



Front Fender Right




Door Front Right



Door Rear Right



Rear Fender Right



Rear Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511LKT373931

DEKRA

CONDITION REPORT

Report No:
2017317768
DATE
27/10/2026



Front Fender Left



Door Front Left



Door Rear Left



Side Mirror Left



A • Pillar Right



A • Pillar Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511LKT373931

DEKRA

CONDITION REPORT

Report No:
2017317768
DATE
27/10/2026



Belly plates



Radiator Cradle



Radiator Cradle



Sill Panel Left



Sill Panel Left



Sill Panel Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511LKT373931

DEKRA

CONDITION REPORT

Report No:
2017317768
DATE
27/10/2026



Sill Panel Right



Sill Panel Right



Rear Bumper / Mounting points



Silencer



Silencer



Tyre Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511LKT373931

DEKRA

CONDITION REPORT

Report No:
2017317768
DATE
27/10/2026



Front Bumper



Rim Rear Left



Windscreen Wiper



Air Conditioner



Center Console / Cubbyhole + Lid



Door Sealing Rubber Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511LKT373931

DEKRA

CONDITION REPORT

Report No:
2017317768
DATE
27/10/2026



Door Sealing Rubber Front Right



Door Sealing Rubber Rear Right



Seat Front Right



Seat Front Left



Seat Belt Front Right



Channel / Roof Gutter Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511LKT373931


DEKRA

CONDITION REPORT

Report No:
2017317768
DATE
27/10/2026



Channel / Roof Gutter Left



Parking Brake Performance

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511LKT373931