DEKRA

# CONDITION REPORT

**Report No:**
**2017311602**
**DATE**
**13/10/2026**

*MFC Auction House*
*M57 Pretoria Rd, Glenmarais, KEMPTON PARK*
*Gauteng*

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572








## Assignment

| | | | |
|---|---|---|---|
| Client | MFC Auction House | Inspection Location | MFC<br>M57 Pretoria Road - 1619<br>Kempton Park - GT |
| Requested Date | 13/10/2026 | | |
| Inspection Date | 13/10/2026 | | |

## Vehicle Data

| | | | |
|---|---|---|---|
| Vehicle Type | PASSENGER VEHICLE | Registered Owner | |
| Manufacturer | KIA | Registration Number | FW49KJGP |
| Model | RIO | Register Number | |
| VIN | KNADN512LG6766580 | Date Of First Licensing | |
| Engine Number | | Last COR | |
| Doors | 5 | License Expiry Date | 30/04/2019 |
| Color | GREY | Power / Displacement | |
| Year Model | | Paint Finish | M - METALLIC |
| Km Reading | 120,286 KM | Fuel | PETROL |
| Cab / Body Type | HATCHBACK | Transmission | MANUAL |

## Vehicle Options & Accessories

**Items**

## VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADN512LG6766580

DEKRA

# CONDITION REPORT

**Report No:**
**2017311602**
**DATE**
**13/10/2026**



| Damage | Repair Way |
|---|---|
| Switch Electrical Window Winder front right Defective | Repair |
| Windscreen Wiper Missing | Replace |
| Indicator Light Front Left Damaged | Replace |
| Indicator Light Front Right Cracked | Replace |
| Seat Front Right Torn / Cut | Repair |
| Front Bumper Paintwork • Scratched | Repair |
| Front Fender Left Paintwork • Scratched | Repair |
| Front Fender Right Dented | Repair |
| Rear Fender Left Paintwork • Scratched | Repair |
| Rear Fender Right Dented | Repair |
| Door Front Left Paintwork • Scratched | Repair |
| Door Front Right Dented | Repair |
| Door Rear Right Dented | Repair |
| Rear bumper Paintwork • Scratched | Repair |
| Sill Panel Left Damaged | Repair |
| Sill Panel Right Damaged | Repair |
| Roof Paintwork • Scratched | Repair |
| Windscreen Cracked | Replace |
| Stabilizer Mounting Front Left Damaged | Replace |
| Stabilizer Mounting Front Right Damaged | Replace |
| Alignment Left / Right Difference out of legal range | Repair |
| Tyre Front Left Excessive Wear & Tear | Replace |
| Tyre Front Right Damaged | Replace |
| Spare Tyre Smooth | Replace |
| Warning lights illuminated | Repair |
| Front tyre size differs | Replace |

## Brakes

### Brake Test Results

| | Left | Right | | |
|---|---|---|---|---|
| | Braking Force [KN] | Braking Force [KN] | Axle Weight [KG] | Deceleration [m/s²] |
| **Front** | 2.1 | 2.4 | - | |
| **Rear** | 2.2 | 2.5 | - | |
| **Emergency / Parking** | 1.5 | 1.9 | - | |

## Tyres and Rims

### Tyre Specification & Measurement

| | Size | Load/Speed Index | Manufacture | Model | Type* | Production Date | Tread Depth (mm) |
|---|---|---|---|---|---|---|---|
| **Front Left** | 185/65R15 | 88H | Duraturn | Mozzo | V | 0000 | 2 mm |
| **Front Right** | 185/60R15 | 84H | Continental | Contact | V | 4319 | 1 mm |
| **Rear Left** | 185/65R15 | 88H | Kumho | Solus | V | 4715 | 1 mm |
| **Rear Right** | 185/65R15 | 88H | Kumho | Solus | V | 4616 | 1 mm |
| **Spare** | 185/65R15 | 88H | Kumho | Solus | V | 0000 | 0 mm |

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADN512LG6766580

DEKRA

# CONDITION REPORT

**Report No:**
**2017311602**
**DATE**
**13/10/2026**

## Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

| No | System | Code | Description | Status |
|---|---|---|---|---|
| 1 | ENGINE | C1203 | RIGHT FRONT VEHICLE SPEED SENSOR VSS CIRCUIT OPEN | |

## Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

## Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.SIGNS OF SPRAY WORK DONE ON BODY PANELS

## Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

## Technician

Trevino Julius

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADN512LG6766580

DEKRA

# CONDITION REPORT

**Report No:**
**2017311602**
**DATE**
**13/10/2026**



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADN512LG6766580

DEKRA

# CONDITION REPORT

**Report No:**
**2017311602**
**DATE**
**13/10/2026**



INTERIOR (FRONT DRIVER DOOR)



Manual transmission



DASHBOARD (W/ ENGINE RUNNING)




ODOMETER




LICENSE DISC




VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADN512LG6766580

DEKRA

# CONDITION REPORT

**Report No:**
**2017311602**
**DATE**
**13/10/2026**



ENGINE 1



ENGINE 2




CHASSIS



REAR



Oil cap and dipstick



Expansion Bottle


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADN512LG6766580


DEKRA

# CONDITION REPORT


**Report No:**
**2017311602**
**DATE**
**13/10/2026**



Coolant reservoir



LF TYRE TREAD




RF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



Sparewheel


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADN512LG6766580

DEKRA

# CONDITION REPORT

**Report No:**
**2017311602**
**DATE**
**13/10/2026**




Shock and brake report



Diagnostic Report page 1




Diagnostic Report page 2




Warning lights illuminated



Windscreen



Front Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADN512LG6766580

DEKRA

# CONDITION REPORT

**Report No:**
**2017311602**
**DATE**
**13/10/2026**



Door Front Right




Indicator Light Front Right



Seat Front Right



Door Rear Right



Rear Fender Right



Windscreen Wiper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADN512LG6766580

DEKRA

# CONDITION REPORT


**Report No:**
**2017311602**
**DATE**
**13/10/2026**




Spare Tyre



Roof



Rear Fender Left



Front Fender Left



Door Front Left



Indicator Light Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADN512LG6766580

DEKRA

# CONDITION REPORT

**Report No:**
**2017311602**
**DATE**
**13/10/2026**



Windscreen



Stabilizer Mounting Front Right



Front Bumper



Front Bumper




Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADN512LG6766580

DEKRA

# CONDITION REPORT

**Report No:**
**2017311602**
**DATE**
**13/10/2026**



Stabilizer Mounting Front Left




Sill Panel Left




Sill Panel Left



Rear bumper



Rear bumper



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADN512LG6766580

DEKRA

# CONDITION REPORT

**Report No:**
**2017311602**
**DATE**
**13/10/2026**



Sill Panel Right



Tyre Front Right



Tyre Front Left



Sill Panel Right



Switch Electrical Window Winder front right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADN512LG6766580