DEKRA

CONDITION REPORT

Report No:
2017306875
DATE
02/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park -
Requested Date	02/10/2026		
Inspection Date	02/10/2026		

Vehicle Data

Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	MFC
Manufacturer	KIA	Registration Number	KP46GYGP
Model	K2700	Register Number	
VIN	KNCSHX71LN7586476	Date Of First Licensing	
Engine Number		Last COR	
Doors	2	License Expiry Date	31/07/2027
Color	WHITE	Power / Displacement	
Year Model		Paint Finish	TWO COAT UNI
Km Reading	130,390 KM	Fuel	DIESEL
Cab / Body Type	SINGLE CAB	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNCSHX71LN7586476

DEKRA

CONDITION REPORT

Report No:
2017306875
DATE
02/10/2026





Damage	Repair Way
Engine Oil Leak	Repair
Hoses Damaged	Repair
Central Air Vent Damaged	Replace
Center Console / Cubbyhole + Lid Damaged	Repair
Tail Light Right Damaged	Replace
Number Plate Light Right Damaged	Replace
Headlight Left Damaged	Replace
Headlight Right Damaged	Repair
Seat Front Right Damaged	Repair
Number Plate Rear Damaged	Repair
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Front Fender Right Damaged	Replace
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Tailgate Damaged	Repair
Rear bumper Damaged	Repair
Load Body Damaged	Repair
Windscreen Damaged	Replace
Service Brake Performance Front Axle Left / Right Difference out of legal range	Repair
Tyre Front Left Worn	Replace
Tyre Front Right Worn	Replace
Tyre Rear Left Worn	Replace
Tyre Rear Right Worn	Replace
Gearbox Oil Leak	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	4.55	3.16	-	
Rear	1.33	1.37	-	
Emergency / Parking	1.49	2	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195R14LT	103R	Timax	Radial	V	3025	0 mm
Front Right	195R14LT	103R	Timax	Radial	V	3025	0 mm
Rear Left	195R14C	104R	Dunlop	Sp	V	1525	0 mm
Rear Right	195R14C	104R	Dunlop	Sp	V	1425	0 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNCSHX71LN7586476

DEKRA

CONDITION REPORT

Report No:
2017306875
DATE
02/10/2026

Diagnostic

A vehicle diagnostic has not been conducted.
Diagnostic could not be performed due to no data available and or OBD interface malfunction.

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Body • Exterior: Minor dents and scratches and stone chips to body panels. Signs of repair work done to body panels. Poor alignment to somebody panels. Vehicle body in poor condition.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNCSHX71LN7586476

DEKRA

CONDITION REPORT

Report No:
2017306875
DATE
02/10/2026



Brake test.



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNCSHX71LN7586476

DEKRA

CONDITION REPORT

Report No:
2017306875
DATE
02/10/2026



MANUAL



90 DEGREE FRONT




90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNCSHX71LN7586476

DEKRA

CONDITION REPORT

Report No:
2017306875
DATE
02/10/2026



LR TYRE TREAD



RR TYRE TREAD




RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNCSHX71LN7586476

DEKRA

CONDITION REPORT

Report No:
2017306875
DATE
02/10/2026



Undercarriage front.



Undercarriage rear.



ADDITIONAL 10



Hoses



Water level



Center Console / Cubbyhole + Lid

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNCSHX71LN7586476

DEKRA

CONDITION REPORT

Report No:
2017306875
DATE
02/10/2026



Central Air Vent



Front Bumper



Front Bumper



Bonnet



Door Front Left



Load Body

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNCSHX71LN7586476

DEKRA

CONDITION REPORT

Report No:
2017306875
DATE
02/10/2026



Load Body



Load Body



Rear bumper



Tailgate



Door Front Right



Front Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNCSHX71LN7586476

DEKRA

CONDITION REPORT

Report No:
2017306875
DATE
02/10/2026



Windscreen



Headlight Right



Headlight Left



Tail Light Right



Number Plate Light Right



Number Plate Rear

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNCSHX71LN7586476

DEKRA

CONDITION REPORT


Report No:
2017306875
DATE
02/10/2026



Seat Front Right




Tyre Rear Left



Tyre Rear Right



Tyre Front Left



Tyre Front Right



Engine

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNCSHX71LN7586476


DEKRA

CONDITION REPORT

Report No:
2017306875
DATE
02/10/2026



Gearbox



Service Brake Performance Front Axle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNCSHX71LN7586476