DEKRA

CONDITION REPORT

Report No:
2017315657
DATE
22/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	22/10/2026		
Inspection Date	22/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	HAVAL	Registration Number	JM89TYGP
Model	H1	Register Number	
VIN	LGWED2A3XLE621257	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/07/2027
Color	SILVER	Power / Displacement	
Year Model		Paint Finish	TWO COAT METALLIC
Km Reading	137,078 KM	Fuel	PETROL
Cab / Body Type	STATION WAGON	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWED2A3XLE621257

DEKRA

CONDITION REPORT

Report No: 2017315657
DATE 22/10/2026



Damage	Repair Way
Center Console / Cubbyhole + Lid Damaged	Repair
Engine Management Lights Set	Repair
Windscreen Wiper Damaged	Replace
Seat Front Right Damaged	Repair
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Front Fender Left Damaged	Repair
Door Front Left Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Damaged	Repair
Boot Lid / Hatch door Damaged	Repair
Rear bumper Damaged	Repair
Windscreen Damaged	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.33	2.93	-	
Rear	2.05	1.78	-	
Emergency / Parking	1.52	1.3	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	205/55R16	91V	Tracmax	Radial	V	4124	2 mm
Front Right	205/55R16	91V	Tracmax	Radial	V	4124	3 mm
Rear Left	205/55R16	91V	Tracmax	Radial	V	4224	3 mm
Rear Right	205/55R16	91V	Tracmax	Radial	V	4124	3 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWED2A3XLE621257

DEKRA

CONDITION REPORT

Report No:
2017315657
DATE
22/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	SRS	B1091	WARNING LAMP SHORTS TO GROUND	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. 4 DTC'S AT TIME OF TESTING SEE DTC REPORT.Body • Exterior: door does not open. Minor dents and scratches and stone chips to body panels. Signs of repair work done to body panels. Poor alignment to somebody panels.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWED2A3XLE621257

DEKRA

CONDITION REPORT

Report No:
2017315657
DATE
22/10/2026



INTERIOR (FRONT DRIVER DOOR)



FRONT RIGHT CORNER



90 DEGREE FRONT



90 DEGREE LEFT



REAR LEFT CORNER



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWED2A3XLE621257

DEKRA

CONDITION REPORT

Report No:
2017315657
DATE
22/10/2026




90 DEGREE RIGHT




DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Brake test.



Diagnostic.



Undercarriage front.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWED2A3XLE621257

DEKRA

CONDITION REPORT

Report No:
2017315657
DATE
22/10/2026



Undercarriage rear.



Oil cap and dipstick.




Manual.



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWED2A3XLE621257

DEKRA

CONDITION REPORT

Report No:
2017315657
DATE
22/10/2026



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Water level



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWED2A3XLE621257

DEKRA

CONDITION REPORT


Report No:
2017315657
DATE
22/10/2026



Front Bumper




Bonnet



Front Fender Left



Door Front Left



Door Rear Left



Boot Lid / Hatch door


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWED2A3XLE621257

DEKRA

CONDITION REPORT

Report No:
2017315657
DATE
22/10/2026



Rear bumper



Rear bumper



Door Rear Right



Windscreen



Center Console / Cubbyhole + Lid



Seat Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWED2A3XLE621257

DEKRA

CONDITION REPORT

Report No:
2017315657
DATE
22/10/2026



Engine Management Lights



Windscreen Wiper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWED2A3XLE621257