DEKRA

CONDITION REPORT

Report No:
2017311205
DATE
13/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	13/10/2026		
Inspection Date	13/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	HAVAL	Registration Number	KT56CTGP
Model	H6 2.0T LUXURY AWD DCT [2021-2025]	Register Number	
VIN	LGWFF6A57NH932637	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/08/2027
Color	WHITE	Power / Displacement	
Year Model	2022	Paint Finish	PEARL EFFECT
Km Reading	72,991 KM	Fuel	PETROL
Cab / Body Type	STATION WAGON	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWFF6A57NH932637

DEKRA

CONDITION REPORT

Report No:
2017311205
DATE
13/10/2026





Damage	Repair Way
Engine Oil Leak	Repair
Sill Panel Right Dented	Repair

Brakes

Brake Test Results

No Brake Test on a brake test machine has been performed.

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	-	-	-	
Rear	-	-	-	
Emergency / Parking	-	-	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	225/60 R18	100V	Hankook	Ventus	V	2322	2 mm
Front Right	225/60 R18	100V	Hankook	Ventus	V	2322	2 mm
Rear Left	225/60 R18	104W	Bridgestone	Alenza	V	2625	5 mm
Rear Right	225/60 R18	104W	Bridgestone	Alenza	V	4123	4 mm
Spare	T135/90 R17	104M	Sailun	Temporary	V	0922	3 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWFF6A57NH932637

DEKRA

CONDITION REPORT

Report No:
2017311205
DATE
13/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	SRS(SUPPLEMENTAL RESTRAINT SYSTEM)	U110116	DIAGNOSTIC VOLTAGE TOO LOW	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWFF6A57NH932637

DEKRA

CONDITION REPORT

Report No:
2017311205
DATE
13/10/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWFF6A57NH932637

DEKRA

CONDITION REPORT

Report No:
2017311205
DATE
13/10/2026



INTERIOR (FRONT DRIVER DOOR)



Automatic Transmission




DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWFF6A57NH932637

DEKRA

CONDITION REPORT

Report No:
2017311205
DATE
13/10/2026



ENGINE 1



Front chassis




Rear chassis



Oil cap and dipstick



LF TYRE TREAD



RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWFF6A57NH932637

DEKRA

CONDITION REPORT

Report No:
2017311205
DATE
13/10/2026




LR TYRE TREAD



RR TYRE TREAD



Spare wheel and Accessories



Shock absorber report



Diagnostic report page 1



Diagnostic report page 2

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWFF6A57NH932637


DEKRA

CONDITION REPORT

Report No:
2017311205
DATE
13/10/2026



Diagnostic report page 3



Diagnostic report page 4



Water level



Sill Panel Right



Engine

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWFF6A57NH932637