DEKRA

CONDITION REPORT

Report No:
2017306890
DATE
05/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park -
Requested Date	05/10/2026		
Inspection Date	05/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	HAVAL	Registration Number	KWN976MP
Model	H6 2.0T SUPER LUXURY AWD DCT [2021-2025]	Register Number	
		Date Of First Licensing	
VIN	LGWFF6A5XPH923711	Last COR	
Engine Number		License Expiry Date	31/07/2026
Doors	5	Power / Displacement	
Color	WHITE	Paint Finish	M - METALLIC
Year Model	2023	Fuel	PETROL
Km Reading	87,616 KM	Transmission	AUTOMATIC
Cab / Body Type	STATION WAGON		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWFF6A5XPH923711

DEKRA

CONDITION REPORT

Report No:
2017306890
DATE
05/10/2026





Damage	Repair Way
Front Bumper Paintwork • Chipmarks	Repair
Bonnet Paintwork • Chipmarks	Repair
Rear Fender Right Paintwork • Scratched	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Left Dented	Repair
Door Rear Right Dented	Repair
Engine light illuminated	Repair

Brakes

Brake Test Results

No Brake Test on a brake test machine has been performed.

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	-	-	-	
Rear	-	-	-	
Emergency / Parking	-	-	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	225/55R19	103W	Royal black	Royal explor	V	4224	3 mm
Front Right	225/55R19	103W	Royal black	Royal explor	V	4424	3 mm
Rear Left	225/55R19	99V	Hankook	Ventus	V	4322	3 mm
Rear Right	225/55R19	99V	Hankook	Ventus	V	4322	3 mm
Spare	T135/90R17	104M	Ling long	Temporary	V	0000	4 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWFF6A5XPH923711

DEKRA

CONDITION REPORT

Report No:
2017306890
DATE
05/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	HISTORY DTC	P023622	BOOST PRESSURE IMPLAUSIBILITY HIGH	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWFF6A5XPH923711

DEKRA

CONDITION REPORT

Report No:
2017306890
DATE
05/10/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWFF6A5XPH923711

DEKRA

CONDITION REPORT

Report No:
2017306890
DATE
05/10/2026



INTERIOR (FRONT DRIVER DOOR)



Automatic




DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWFF6A5XPH923711

DEKRA

CONDITION REPORT

Report No:
2017306890
DATE
05/10/2026



ENGINE 1



CHASSIS



ENGINE 2



Expention bottle



Oil cap and dipstick



LF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWFF6A5XPH923711

DEKRA

CONDITION REPORT


Report No:
2017306890
DATE
05/10/2026



RF TYRE TREAD




LR TYRE TREAD




RR TYRE TREAD



Spare wheel



Shock report



Diagnostic Report page 1


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: LGWFF6A5XPH923711


DEKRA


CONDITION REPORT


Report No:
2017306890
DATE
05/10/2026



Diagnostic Report page 2


Diagnostic Report page 3


Diagnostic Report page 4


Diagnostic Report page 5


Diagnostic Report page 6


Diagnostic Report page 7

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWFF6A5XPH923711


DEKRA

CONDITION REPORT

Report No:
2017306890
DATE
05/10/2026



Water level



Bonnet



Door Rear Right



Door Front Right



Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWFF6A5XPH923711

DEKRA

CONDITION REPORT


Report No:
2017306890
DATE
05/10/2026



Door Front Left



Door Rear Left



Rear Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWFF6A5XPH923711