DEKRA

CONDITION REPORT

Report No:
2017316344
DATE
23/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	23/10/2026		
Inspection Date	23/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	CHERY	Registration Number	LKH788MP
Model	TIGGO 4 PRO 1.5 LIT [2023-ON]	Register Number	
VIN	LVVDB11B2SC119709	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	30/09/2026
Color	GREY	Power / Displacement	
Year Model	2025	Paint Finish	TWO COAT UNI
Km Reading	24,017 KM	Fuel	PETROL
Cab / Body Type	STATION WAGON	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LVVDB11B2SC119709

DEKRA

CONDITION REPORT

Report No:
2017316344
DATE
23/10/2026





Damage	Repair Way
Fog Light Front Right Defective	Repair
Front Bumper Paintwork • Scratched	Repair
Bonnet Dented	Repair
Door Rear Left Dented	Repair
Door Rear Right Dented	Repair
Windscreen Cracked	Replace
Deceleration parking brake defective	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.4	2.56	-	
Rear	2.68	2.84	-	
Emergency / Parking	1.09	0.85	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	215/65 R16	98H	Choayang	SU318	V	0125	5 mm
Front Right	215/65 R16	98H	Choayang	SU318	V	0123	5 mm
Rear Left	215/65 R16	98H	Chaoyang	SU318	V	0125	5 mm
Rear Right	215/65 R16	98H	Chaoyang	SU318	V	0125	5 mm
Spare	T125/80 R17	99M	Linglong	Temporary	V	1025	3 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LVVDB11B2SC119709

DEKRA

CONDITION REPORT

Report No:
2017316344
DATE
23/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	BCM(BODY CONTROL SYSTEM)-BDM(BODY DOMAIN MODULE	B152E1D	BOOT DETECTION FAILED	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Body • Exterior: Minor dents and scratches on body panels

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LVVDB11B2SC119709

DEKRA

CONDITION REPORT

Report No:
2017316344
DATE
23/10/2026



INTERIOR (FRONT DRIVER DOOR)



FRONT RIGHT CORNER



90 DEGREE FRONT



90 DEGREE LEFT



REAR LEFT CORNER



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LVVDB11B2SC119709

DEKRA

CONDITION REPORT

Report No:
2017316344
DATE
23/10/2026



90 DEGREE RIGHT



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual Transmission



ENGINE 1



Oil cap and dipstick


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LVVDB11B2SC119709

DEKRA

CONDITION REPORT

Report No:
2017316344
DATE
23/10/2026



Brake and shock absorber repor



Front chassis



Rear chassis



Diagnostic report page 1



Diagnostic report page 2



Spare wheel and Accessories

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LVVDB11B2SC119709

DEKRA

CONDITION REPORT

Report No:
2017316344
DATE
23/10/2026



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LVVDB11B2SC119709


DEKRA

CONDITION REPORT

Report No:
2017316344
DATE
23/10/2026



Door Rear Right



Door Rear Left



Windscreen



Bonnet



Water level



Fog Light Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LVVDB11B2SC119709

DEKRA

CONDITION REPORT

Report No:
2017316344
DATE
23/10/2026



Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LVVDB11B2SC119709