DEKRA

CONDITION REPORT

Report No:
2017315644
DATE
22/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	22/10/2026		
Inspection Date	22/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	CHERY	Registration Number	MF89YZGP
Model	TIGGO 4 PRO 1.5 LIT [2023-ON]	Register Number	
VIN	LVVDB11B9RC111357	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	28/02/2027
Color	WHITE	Power / Displacement	
Year Model	2025	Paint Finish	C - COMMON
Km Reading	38,363 KM	Fuel	PETROL
Cab / Body Type	STATION WAGON	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LVVDB11B9RC111357

DEKRA

CONDITION REPORT

Report No:
2017315644
DATE
22/10/2026



Damage	Repair Way
Radiator Damaged	Replace
Air Conditioner Defective	Repair
Dim Light Right Defective	Replace
Front Bumper Damaged	Repair
Bonnet Dented	Repair
Rear Fender Left Paintwork • Scratched	Repair
Rear Fender Right Paintwork • Scratched	Repair
Front Fender Left / Inner Tray Damaged	Replace
Front Fender Right / Inner Tray Damaged	Replace
Door Rear Left Damaged	Repair
Door Rear Right Dented	Repair
Rear bumper Paintwork • Scratched	
Belly plates Damaged	Replace
Radiator Cross Member Damaged	Replace
Body exterior	Minor dents and scratches/chip stone
Undercarriage	signs of impact in front of vehicle
Tyre pressure warning light illuminated	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.8	2.9	-	
Rear	2.7	2.7	-	
Emergency / Parking	1.1	1.9	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	215/65R16	98H	Linglong	Cross Wind H	V	3124	3 mm
Front Right	215/65R16	98H	Linglong	Cross wind h	V	3142	3 mm
Rear Left	215/65R16	96H	Linglong	Wind hp	V	3124	4 mm
Rear Right	215/65R16	98H	Linglong	Wind Hp	V	3324	4 mm
Spare	T125/80R17	99M	linglong	temporary	V	////	4 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LVVDB11B9RC111357

DEKRA

CONDITION REPORT

Report No:
2017315644
DATE
22/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	TIRE PRESSURE MONITORING SYSTEM (TPMS)	B103713	PLEASE REFER TO VEHICLE SERVICE MANUAL	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Electrical Components and Instruments: Air conditioning not working Warning light illuminated

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LVVDB11B9RC111357

DEKRA

CONDITION REPORT

Report No:
2017315644
DATE
22/10/2026



INTERIOR (FRONT DRIVER DOOR)



FRONT RIGHT CORNER



90 DEGREE FRONT



90 DEGREE LEFT



REAR LEFT CORNER



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LVVDB11B9RC111357


DEKRA

CONDITION REPORT

Report No:
2017315644
DATE
22/10/2026




90 DEGREE RIGHT



Brake test



Diagnostics report



Diagnostics report



Dash light illuminated



Sparewheel

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LVVDB11B9RC111357

DEKRA

CONDITION REPORT

Report No:
2017315644
DATE
22/10/2026



Oil cap and dipstick



manual




Chasis



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



LF TYRE TREAD


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LVVDB11B9RC111357


DEKRA

CONDITION REPORT

Report No:
2017315644
DATE
22/10/2026



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LVVDB11B9RC111357

DEKRA

CONDITION REPORT

Report No:
2017315644
DATE
22/10/2026




ENGINE 2



CHASSIS



Belly plates



Front Fender Left / Inner Tray



Front Fender Right / Inner Tray



Radiator

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LVVDB11B9RC111357

DEKRA

CONDITION REPORT

Report No:
2017315644
DATE
22/10/2026



Radiator Cross Member



Radiator Cross Member



Front Bumper



Front Bumper



Front Bumper



Door Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LVVDB11B9RC111357

DEKRA

CONDITION REPORT


Report No:
2017315644
DATE
22/10/2026




Rear bumper




Rear bumper



Rear bumper



Door Rear Left



Door Rear Left



Rear Fender Left


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LVVDB11B9RC111357

DEKRA

CONDITION REPORT

Report No:
2017315644
DATE
22/10/2026



Rear Fender Right



Dim Light Right



Water level



Radiator



Bonnet



Air Conditioner

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LVVDB11B9RC111357