DEKRA

CONDITION REPORT

Report No:
2017316055
DATE
22/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	22/10/2026		
Inspection Date	22/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	CHERY	Registration Number	HFL044L
Model	TIGGO 4 PRO 1.5 COMFORT CVT [2022-2026]	Register Number	
VIN	LVVDB21B3PD975723	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/08/2027
Color	SILVER	Power / Displacement	
Year Model	2023	Paint Finish	C - COMMON
Km Reading	59,655 KM	Fuel	PETROL
Cab / Body Type	STATION WAGON	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LVVDB21B3PD975723

DEKRA

CONDITION REPORT

Report No:
2017316055
DATE
22/10/2026





Damage	Repair Way
Side Mirror Right Paintwork • Flaking	Repair
Front Bumper Paintwork • Scratched	Repair
Bonnet Dented	Repair
Front Fender Right Dented	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Right Dented	Repair
Body exterior	Traces dents and scratches on body panels

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.8	2.9	-	
Rear	2.2	2.1	-	
Emergency / Parking	0.9	0.8	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	215/65R16	98H	CHAO YANG	SU318a H/T	V	1723	4 mm
Front Right	215/65R16	98H	CHAO YANG	SU318a H/T	V	1723	4 mm
Rear Left	215/65R16	98H	CHAO YANG	SU1318a H/T	V	1723	4 mm
Rear Right	215/65R16	98H	CHAO YANG	SU318a	V	1723	4 mm
Spare	T125/80D17	99m	Westlake	temporary T5	V	////	6 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LVVDB21B3PD975723

DEKRA

CONDITION REPORT

Report No:
2017316055
DATE
22/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	AT(AUTOMATIC TRANSMISSION SYSTEM)	P176100	CALIBRATION DATA DOES NOT MATCH MAIN SOFTWARE	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LVVDB21B3PD975723

DEKRA

CONDITION REPORT

Report No:
2017316055
DATE
22/10/2026



INTERIOR (FRONT DRIVER DOOR)



FRONT RIGHT CORNER



90 DEGREE FRONT



90 DEGREE LEFT



REAR LEFT CORNER



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LVVDB21B3PD975723

DEKRA

CONDITION REPORT

Report No:
2017316055
DATE
22/10/2026



90 DEGREE RIGHT



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic



Oil Cap and dipstick



ENGINE 2

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LVVDB21B3PD975723


DEKRA

CONDITION REPORT

Report No:
2017316055
DATE
22/10/2026




ENGINE 1




CHASSIS



Chasis



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LVVDB21B3PD975723

DEKRA

CONDITION REPORT

Report No:
2017316055
DATE
22/10/2026



RF TYRE TREAD




Sparewheel



LICENSE DISC



VIN PLATE OR STICKER



Brakes Report



Diagnostics

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: LVVDB21B3PD975723

DEKRA

CONDITION REPORT

Report No:
2017316055
DATE
22/10/2026


diagnostics



Diagnostics


Bonnet



Front Bumper


Front Bumper


Front Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LVVDB21B3PD975723

DEKRA

CONDITION REPORT

Report No:
2017316055
DATE
22/10/2026



Door Rear Right



Door Front Right



Side Mirror Right



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LVVDB21B3PD975723