DEKRA

CONDITION REPORT

Report No:
2017314868
DATE
21/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	21/10/2026		
Inspection Date	21/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	MAHINDRA	Registration Number	LR83GRGP
Model	XUV 700	Register Number	
VIN	MA1NF2ZFFP6B78473	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	30/06/2027
Color	WHITE	Power / Displacement	
Year Model		Paint Finish	TWO COAT UNI
Km Reading	53,032 KM	Fuel	PETROL
Cab / Body Type	SUV	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA1NF2ZFFP6B78473

DEKRA

CONDITION REPORT

Report No:
2017314868
DATE
21/10/2026



Damage	Repair Way
Central Air Vent Damaged	Replace
Engine Management Lights Set	Repair
Headlight Left Damaged	Replace
Side Mirror Left Damaged	Replace
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Door Front Right Damaged	Replace
Door Rear Right Damaged	Repair
Rear bumper Damaged	Repair
Tyre Front Left Worn	Replace
Rim Front Left Damaged	Replace
Jack Missing	Repair
Wheel Spanner Missing	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	4.1	4.1	-	
Rear	2.69	2.73	-	
Emergency / Parking	2.39	3.04	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	235/65R17	108H	Rapid	Radial	V	2523	0 mm
Front Right	235/65R17	104R	MRF	Radial	V	0223	2 mm
Rear Left	235/65R17	108H	Rapid	Radial	V	0123	4 mm
Rear Right	235/65R17	104H	MRF	Radial	V	0223	3 mm
Spare	T155/90R18	113H	Gritte	Temporary	V	0000	2 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA1NF2ZFFP6B78473

DEKRA

CONDITION REPORT

Report No:
2017314868
DATE
21/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	MAHINDRA BODY FUNCTION MODEL	B110016	ECM UNDERVOLTAGE	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. 48 DTC'S AT TIME OF TESTING SEE DTC REPORT.Body • Exterior: Minor dents and scratches and stone chips to body panels. Signs of repair work done to body panels. Poor alignment to somebody panels. Repair work done to vehicle below standard.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA1NF2ZFFP6B78473


DEKRA

CONDITION REPORT


Report No:
2017314868
DATE
21/10/2026




Brake test.




Diagnostic.



Diagnostic.



Diagnostic.



Diagnostic.



FRONT RIGHT CORNER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA1NF2ZFFP6B78473

DEKRA

CONDITION REPORT

Report No:
2017314868
DATE
21/10/2026



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic.



90 DEGREE FRONT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA1NF2ZFFP6B78473

DEKRA

CONDITION REPORT

Report No:
2017314868
DATE
21/10/2026




90 DEGREE RIGHT




90 DEGREE REAR




90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA1NF2ZFFP6B78473

DEKRA

CONDITION REPORT

Report No:
2017314868
DATE
21/10/2026



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Undercarriage front.



Undercarriage rear.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA1NF2ZFFP6B78473

DEKRA

CONDITION REPORT

Report No:
2017314868
DATE
21/10/2026



Oil cap and dipstick.



Water level



Front Bumper



Front Bumper



Bonnet



Front Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA1NF2ZFFP6B78473

DEKRA

CONDITION REPORT

Report No:
2017314868
DATE
21/10/2026




Rear Fender Left



Rear bumper




Rear bumper



Door Front Right



Door Rear Right



Front Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA1NF2ZFFP6B78473

DEKRA

CONDITION REPORT

Report No:
2017314868
DATE
21/10/2026



Jack



Wheel Spanner



Tyre Front Left



Tyre Front Left



Rim Front Left



Side Mirror Left


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA1NF2ZFFP6B78473

DEKRA

CONDITION REPORT

Report No:
2017314868
DATE
21/10/2026



Headlight Left



Central Air Vent



Central Air Vent



Engine Management Lights

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA1NF2ZFFP6B78473