DEKRA

CONDITION REPORT

Report No:
2017314703
DATE
20/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572








Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	20/10/2026		
Inspection Date	20/10/2026		

Vehicle Data

Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	MAHINDRA	Registration Number	LH86RCGP
Model	SCORPIO PIK-UP 2.2 MHAWK S4 DSL [2017-ON]	Register Number	
		Date Of First Licensing	
VIN	MA1RA2VK2P2F21345	Last COR	
Engine Number		License Expiry Date	
Doors	2	Power / Displacement	
Color	WHITE	Paint Finish	C - COMMON
Year Model	2023	Fuel	DIESEL
Km Reading	42,160 KM	Transmission	MANUAL
Cab / Body Type	SINGLE CAB		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA1RA2VK2P2F21345

DEKRA

CONDITION REPORT

Report No:
2017314703
DATE
20/10/2026



Damage	Repair Way
Tail Light Left Damaged	Replace
Tail Light Right Damaged	Replace
Fog Light Front Left Malfunction	Repair
Seat Front Left Damaged	Repair
Seat Front Right Damaged	Repair
Window Winder front right Malfunction	Repair
Side Mirror Left Damaged	Repair
Side Mirror Right Paintwork • Scratched	Repair
Bonnet Dented	Repair
B • Pillar Left Paintwork • Scratched	Repair
B • Pillar Right Dented	Repair
Front Fender Right Paintwork • Scratched	Repair
Rear Fender Left Paintwork • Scratched	Repair
Rear Fender Right Dented	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Paintwork • Scratched	Repair
Tailgate Paintwork • Scratched	Repair
Rear bumper Damaged	Repair
Windscreen Cracked	Replace
No license disc	Replace
L/F A piller inner panel missing	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	3.9	4.0	-	
Rear	3.1	2.9	-	
Emergency / Parking	1.9	1.8	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	245/75R16	111S	Jk tyre	Elanzo	V	0823	3 mm
Front Right	245/75R16	111S	Jk tyre	Elanzo	V	0623	3 mm
Rear Left	245/75R16	111S	Jk tyre	Elanzo	V	0923	3 mm
Rear Right	245/75R16	111S	Jk tyre	Elanzo	V	4322	2 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA1RA2VK2P2F21345

DEKRA

CONDITION REPORT

Report No:
2017314703
DATE
20/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	OTHER	U140100	EMS MESSAGE CONTENT FAILURE	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA1RA2VK2P2F21345

DEKRA

CONDITION REPORT

Report No:
2017314703
DATE
20/10/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE RIGHT



90 DEGREE LEFT



90 DEGREE FRONT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA1RA2VK2P2F21345

DEKRA

CONDITION REPORT

Report No:
2017314703
DATE
20/10/2026



ODOMETER




DASHBOARD (W/ ENGINE RUNNING)



INTERIOR (FRONT DRIVER DOOR)



Manual



LF TYRE TREAD



LR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA1RA2VK2P2F21345

DEKRA

CONDITION REPORT

Report No:
2017314703
DATE
20/10/2026



RF TYRE TREAD




RR TYRE TREAD



No spare wheel



Expention bottle



Oil cap and dipstick



ENGINE 1


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA1RA2VK2P2F21345

DEKRA

CONDITION REPORT

Report No:
2017314703
DATE
20/10/2026



ENGINE 2




CHASSIS




VIN PLATE OR STICKER



LICENSE DISC MISSING



SHOCK AND BRAKE REPORT



DIAGNOSTIC REPORT PAGE 1


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA1RA2VK2P2F21345

DEKRA

CONDITION REPORT

Report No:
2017314703
DATE
20/10/2026



DIAGNOSTIC REPORT



Seat Front Right



Seat Front Left



Window Winder front right



Water level



Side Mirror Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA1RA2VK2P2F21345

DEKRA

CONDITION REPORT

Report No:
2017314703
DATE
20/10/2026



Fog Light Front Left



Windscreen




B • Pillar Right



Rear Fender Right



Door Front Right



Front Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA1RA2VK2P2F21345

DEKRA

CONDITION REPORT

Report No:
2017314703
DATE
20/10/2026



Side Mirror Right




Bonnet



Side Mirror Left



Door Front Left



B • Pillar Left



Rear Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA1RA2VK2P2F21345

DEKRA

CONDITION REPORT

Report No:
2017314703
DATE
20/10/2026



Rear bumper



Tailgate



Tail Light Left



Tail Light Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA1RA2VK2P2F21345