DEKRA

CONDITION REPORT

Report No:
2017315317
DATE
21/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572








Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	21/10/2026		
Inspection Date	21/10/2026		

Vehicle Data

Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	
Manufacturer	MAHINDRA	Registration Number	MS03GWGP
Model	SCORPIO PIK-UP 2.2 MHAWK S6 DSL D-CAB [2020-ON]	Register Number	
		Date Of First Licensing	
VIN	MA1RC2CY2T2031709	Last COR	
Engine Number		License Expiry Date	31/10/2026
Doors	4	Power / Displacement	
Color	WHITE	Paint Finish	TWO COAT UNI
Year Model	2025	Fuel	DIESEL
Km Reading	38,255 KM	Transmission	MANUAL
Cab / Body Type	DOUBLE CAB		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA1RC2CY2T2031709

DEKRA

CONDITION REPORT

Report No: 2017315317
DATE 21/10/2026



Damage	Repair Way
Engine Oil Leak	Repair
Seat Front Right Damaged	Repair
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Door Front Left Damaged	Repair
Tailgate Damaged	Repair
Rear bumper Damaged	Repair
Windscreen Damaged	Replace
Gearbox Oil Leak	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	4.74	4.76	-	
Rear	4.02	4.55	-	
Emergency / Parking	2.97	3.53	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	245/75R16	111S	JKTyre	Radial	V	3225	3 mm
Front Right	245/75R16	111S	JKTyre	Radial	V	3225	3 mm
Rear Left	245/75R16	111S	JKTyre	Radial	V	3325	3 mm
Rear Right	245/75R16	111S	JKTyre	Radial	V	3225	3 mm
Spare	245/75R16	111S	JKTyre	Radial	V	0000	5 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA1RC2CY2T2031709

DEKRA

CONDITION REPORT

Report No:
2017315317
DATE
21/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	INFOTAINMENT SYSTEM (21 DTCS)	U130100	VIN MISMATCH IN IS	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.SIGNS OF REPAIR WORK DONE TO BODY PANELS. POOR ALIGNMENT TO SOMEBODY PANELS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA1RC2CY2T2031709

DEKRA

CONDITION REPORT

Report No:
2017315317
DATE
21/10/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA1RC2CY2T2031709

DEKRA

CONDITION REPORT

Report No:
2017315317
DATE
21/10/2026



INTERIOR (FRONT DRIVER DOOR)



Manual.



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA1RC2CY2T2031709

DEKRA

CONDITION REPORT

Report No:
2017315317
DATE
21/10/2026



ENGINE 1




Undercarriage front.




Undercarriage rear.



Oil cap and dipstick.



LF TYRE TREAD



RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA1RC2CY2T2031709

DEKRA

CONDITION REPORT


Report No:
2017315317
DATE
21/10/2026




LR TYRE TREAD




RR TYRE TREAD



Brake test.



Diagnostic.



Diagnostic.



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA1RC2CY2T2031709

DEKRA

CONDITION REPORT

Report No:
2017315317
DATE
21/10/2026



Front Bumper



Front Bumper



Bonnet



Front Fender Left



Rear Fender Left



Tailgate

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA1RC2CY2T2031709

DEKRA

CONDITION REPORT

Report No:
2017315317
DATE
21/10/2026



Rear bumper



Rear bumper



Rear Fender Right



Front Fender Right



Door Front Left



Windscreen


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA1RC2CY2T2031709

DEKRA

CONDITION REPORT

Report No:
2017315317
DATE
21/10/2026



Seat Front Right



Engine



Gearbox

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA1RC2CY2T2031709